ASS. REC. BY:	20042621Kg
/ IF MAETA	
From:	SSIGNMENT
Estimated Cost:	Veh No: \(\frac{50142663P}{1016} \) Yr Regn: \(\frac{10}{6} \)
OD /AP I WS / TP RES / OD RES / EVA / INV / MY	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
To Inspect Vehicle No:	Make: Pruseof 5008 c.c 1560
at Workshop m/s NGS	Make:
of July 1	Colour AC: Insured / Std / NI / NA
Insured:	Sp.Reading 228183 T/Radio: Insured / Std / NI / NA
Policy No.	Eng/No:
Claims No.	CNO: VI= 30 EB1+ 7 7.45139414
Sum Insured: Excess:	Gen. Cond: Good / Fair / Poor / Burnt
(Client's Record)	Steering: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Brake: Inorder / Jammed / Leaked / Burnt or
	Mod1: Nill / S/Rim / STD A/Rim or
(Dollar Condition)	Tyre Size: F: 215/50R17
(Policy Condition)	R:
Remark: The veh had commenced its repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
	TOYO/YOKO or Gizi
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal mm R/Bal. }
GIA / PR Seen: Consistent? : Yes or No	L/Bal.
Est. Repairs: 4-5 days Res.: Yes or No	D.O.A. 29/4/22 D.O.I. 9/5/2022
Lum Sum:/-/3/_ % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS	
. Vehicle: IN / OUT	Des. of Damages: Frt Rear O/S N/S U/C Rooftop or
Date:Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
Wilsy Said 1-B1, no 2nd par	ts avoilable
PART BY PART \$4583.65, 5DAYS	
DED: 5045 05:500	
RED: 5245.85;53%	
Date/Time, File Pass to? : Prell. Report	One Of Panels. F
. Trens Report	Days Of Repair: 5
	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transporta621:
Add Fee:	: Site Insp (\$)s - RsSi
*	: Interview (\$) Farths
Report Format :	Tech Invs (\$) Others
Lump Sum / I.B.I: (\$	Weekend (\$
Lump dum rion (o	
	TOTAL

ASS. I

ASS. RI

1/127

From:
Estimate

OD / TF

To Insp
at Work

of
Insured

Policy I

Claims

Sum In

(Clier

Hake c

(Polk emar

al. or

AC, A / at. R m S

te: ale

NGSAUTOMOTIVE

111

\$ 11

120

्राम् इस्म

NOW.

uned ions ions ions ions ions

्या ।

K

PSR 10 Ang Me Kio Ind. Pk 2a #02-01 AMK AutoPoint Singapore 568047 Fel: 64815727 Fax: 64815772 | Dinail: evelyn191 Ingsautomotive@gmail.com Reg No.53405718K

			MOITATOU	No	· : AQT-0062	
ALLIANZ INSURANCE SING	APORE P			Your Ref.	}	
79 ROBINSON ROAD		Not	Arthur	Our Ref	` }	
#09-01		<i>A</i> .		C. C.	•	
SINGAPORE 068897		/4/m	ty Bepain	Date	: 07/05/2022	
TEL : 6297 8802	FA	·× :	ry Blipaing 5-6-421	Page	: 1 of 2	
	Description	on		Qty	U/ Price	Amount
					S\$	S\$
Accident on 29/04/2022 @ Along SLE (Woodlands) Ba	efore Mad		2663P & SLZ746C			
Replacement Parts: Puege Tailgate	ot 5008					By 1456 80 L
Rubber, Tailgate				1	1,456.80	1,400,00
Outer Garnish, Tailgate				1	148.60	الم 148.60 ك
Rear Bumper				1	267.50	267.50
				1	976.50	CM 976.50
Tow Cover, Rear Bumper				1	46.20	46.20
Rear Bumper Lamp RH				1	179.00	Br 179.00
Parking Sensor				14	208.00	Mar 832.00
Lock, Inner Lock				1	147.00	M 147.00
Reinforcement, Rr Bumper				1	468.00	468.00
Rear bracket RH/LH				2	89.00	178.00
Side Retainer RH/LH				2	158.00	امر 316.00
End Panel Outer				1 ,	390.60	390.60
End Panel Inner	-	LKK Auto Co	neultante hence notific		576.70	576.70
Garnish, End Panel		the Repairer	onsultants hence notify of the following:		104.90	رم 104.90 م
Emblem "5008"			efore/after spray painting maged part(s) during resurvey.		51.40	Ma 51.40
Emblem " Blue FDI"		 Parts prices a 	re subject to confirmation		58.80	Mc 58.80
Exhaust			rvey is on a "Without Prejudice tification(s) is allowed	e" basis	1,257.00	1,257.00
ubTotal		 Supplementar 	y item(s) must be resurveyed			7,455.00
ess 10%		Acknowledged I	nal approval from Insurance C by Repairer	ompany	-745.50	-745.50
o Plate C/W Casing	S.Net	Signature: Date:			50.00	Ry 50.00
•	S.Ne	tt		1	60.00	1a 60.00
alant						Ma 400

NGS AUTOMOTIVE

Blk 10 Ang Mo Kio Ind. Pk 2a #02-01 AMK AutoPoint Singapore 568047 Tel: 64815727 Fax: 64815772 Email: evelyn1911ngsautomotive@gmail.com Reg No.:53405718K

QUOTATION No.: AQT-0062 ALLIANZ INSURANCE SINGAPORE PTE LTD Your Ref. Our Ref **79 ROBINSON ROAD** C. C. #09-01 SINGAPORE 068897 : 07/05/2022 Date Page : 2 of 2 TEL : 6297 8802 FAX: Amount Qty U/ Price Description

o an ipadii		-	
		S\$	S\$
To Remove Rear damaged part with all necessary component/attachment. Straighten Chassis member.	1	1,400.00	? 1,400.00
Repair/Reshape dented body panel. Replace Damaged Part. Refit into position.			601
Transfer door Mechanism	1	150.00	150.00
Remove/Replace Exhast	1	180.00	601 180.00
Transfer rear windscreen glass	1	280.00	120(280.00
Soray Painting	1	1,000.00	600 1,000.00

Any other parts which necessitate repair or renewal will incur additional charged. Please contact our Ms Evelyn @ HP 96955547 to arrange for survey. Thank you.

Total

9,829.50

Yours faithfully,

EVELYN

SN07224U0008 / NTUC Income Insurance Co-operative Ltd ENTRY DATE & TIME: 30/04/2022 11:54 (SGT) SUBMITTED BY: Louis Lim VERSION: 1 (30/04/2022 11:54 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- IMPORTANT NOTICE

 1. Please report <u>correctly</u> the details of the accident to speed up the claims process.

 2. This Form must be <u>completed by the Policyholder and/or the Authorised Driver</u>

 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding or material facts may allow insurance companies to reputation policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

 5. Any false reporting may be referred to the Police for Investigation.

 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Date of Accident Exact Location of Accident Additional Location Information Country/State of Loss	30/04/2022 11:54 (SGT) 29/04/2022 19:17 (SGT) Singapore SLE (WOODLANDS) BEFORE MANDAI LAKE FLYOVER Singapore
--	--

DETAILS OF OWN VEHICLE

Vehicle Registration Number **SLH2663P**

Is company?	
Name Of Registered Owner	No
Name Of Registered Owner NRIC No	TAN HOCK CHYE
	S1522317.J
Email Address	
A I - L To - Direct - A I	HCTAN@SINGNET.COM.SG
	(Phone) +65-98198489
Alternative Phone No	+65-98198489

Manufacturer	Peugeot 5008
Variant	-
Exact purpose for which vehicle was being used at time of	
accident	Private hire
Are you claiming under your own insurance policy for repair to	
your vehicle?	No - Claiming third party
Vehicle Category	Private hire
Transmission	Auto
CC	1600

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5121136306-01
Cover Note Number	<u>-</u>

TAN HOCK CHYE Name of Driver NRIC No S1522317J



Date Of Birth	09/09/1962
Occupation	Outdoor
Date Of Driving Pass	31/08/1982
Driving experience	39 YEARS AND 8 MONTHS
Gender	Male
Mobile Number	(Phone) +65-98198489
Alt. Phone Number	+65-98198489
Email Address	HCTAN@SINGNET.COM.SG
Address	BLK 542 #19-46 JELAPANG ROAD
Address complement	-
Postcode	670542
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	,
Insurance Company of Other Vehicle Owned by Driver	-
Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry
	Diy
Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	INU
Was any other vehicle or property demonstrate.	- -
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s)	
soliciting/offering accident claims assistance?	No
PASSENGER 1	
Name	LINIKNIOWNI
=	UNKNOWN
Gender	Female
Vas the accident reported to the police?	No
/as notice of intended Prosecution given?	No
yes, against whom?	-
,, -9	
VAS DRIVING STRAIGHT ALONG SLE (WOODLANDS). THE AS ABLE TO BRAKE IN TIME AS WELL. HOWEVER, I FELT T DLLIDED ONTO REAR OF MY VEHICLE.	VEHICLE IN FRONT OF ME SUDDENLY JAMMED BRAKE AND THAT THERE WAS AN IMPACT FROM BEHIND AND VEHICLE B
accident photos available for attachment?	Yes
s there any video captured by Car Camera?	Yes
s there any video captured by Car Camera?	Yes ADVISED THE DRIVER TO SEND TO
s there any video captured by Car Camera?assons for not uploading a video of the accident	ADVISED THE DRIVER TO SEND TO
asons for not uploading a video of the accident	ADVISED THE DRIVER TO SEND TO MOTORVIDEO@INCOME.COM.SG
s there any video captured by Car Camera?asons for not uploading a video of the accidents there any audio recorded?	ADVISED THE DRIVER TO SEND TO
s there any audio recorded?	ADVISED THE DRIVER TO SEND TO MOTORVIDEO@INCOME.COM.SG No
s there any audio recorded?	ADVISED THE DRIVER TO SEND TO MOTORVIDEO@INCOME.COM.SG No
s there any audio recorded?	ADVISED THE DRIVER TO SEND TO MOTORVIDEO@INCOME.COM.SG
asons for not uploading a video of the accidents there any audio recorded?	ADVISED THE DRIVER TO SEND TO MOTORVIDEO@INCOME.COM.SG No
asons for not uploading a video of the accidents there any audio recorded?	ADVISED THE DRIVER TO SEND TO MOTORVIDEO@INCOME.COM.SG No R VEHICLE PROPERTY 1
s there any audio recorded? DETAILS OF OTHER	ADVISED THE DRIVER TO SEND TO MOTORVIDEO@INCOME.COM.SG No
s there any audio recorded? DETAILS OF OTHER	ADVISED THE DRIVER TO SEND TO MOTORVIDEO@INCOME.COM.SG No R VEHICLE PROPERTY 1
asons for not uploading a video of the accidents there any audio recorded?	ADVISED THE DRIVER TO SEND TO MOTORVIDEO@INCOME.COM.SG No R VEHICLE PROPERTY 1