

ASS. REQ. BY:

REF:

Smo/ 2200 4266/Kv

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

1-B.I.%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

27/5 81223-85

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Veh No:

SDS 1238C

Yr Regn:

05, 17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Altis

C.C

1598

Colour

M. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

74310

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NR053REH104559272

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

215/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	261H
Vehicle Details	
Vehicle No.:	SDS1238C
Vehicle to be Exported:	Yes
Intended Deregistration Date:	04 Apr 2022
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 CVT
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	1ZRY336646
Chassis No.:	MR053REH104559272
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$19,990.00
Original Registration Date:	23 May 2017
First Registration Date:	23 May 2017
Transfer Count:	0
Actual ARF Paid:	\$19,990.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 May 2027
PARF Rebate Amount:	\$14,992.00
Intended COE Rebate Details	
COE Expiry Date:	22 May 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,600.00
COE Rebate Amount:	\$26,479.00
Total Rebate Amount:	\$41,471.00

The information contained herein is correct as at 04 Apr 2022

OK

SL0V22540003 / LIM TAN MOTOR PTE LTD
ENTRY DATE & TIME: 04/05/2022 16:48 (SGT)
SUBMITTED BY: Lim Li Choo
VERSION: 1 (04/05/2022 16:48 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	04/05/2022 16:48 (SGT)
Date of Accident	02/05/2022 15:20 (SGT)
Exact Location of Accident	100 North Buona Vista Rd, Buona Vista, Singapore 139349
Additional Location Information	JUNCTION OF COMMONWEALTH AVE WEST AVE NEAR BUOMA VISTRA MRT STATION & THE STAR VISTA
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDS1238C
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	CHAN YIM LENG
NRIC No	SXXXX261H
Email Address	CHANYIMLENG@GMAIL.COM
Mobile Phone No	(Phone) +65-98199808
Alternative Phone No	(Home) +65-98199808

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Corolla
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1600

INSURANCE COMPANY

Name of Insurance Company	MSIG Insurance (Singapore) Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	A29144361AT2
Cover Note Number	-

DRIVER

Name of Driver	HAN ZHENWEI, JEREMIAH
----------------	-----------------------

NRIC No	SXXXX070B
Date Of Birth	03/10/1993
Occupation	Indoor
Date Of Driving Pass	07/02/2014
Driving experience	8 YEARS AND 3 MONTHS
Gender	Male
Mobile Number	(Phone) +65-97737626
Alt. Phone Number	-
Email Address	HZWJEREMIAH@HOTMAIL.COM
Address	22 LORONG PUNTONG #08-03
Address complement	-
Postcode	576439
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Child
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	DRIVER'S FRIEND
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO THE ATTACHED STATEMENT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	SLT206B
-----------------------------------	---------


Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature Date
& Time:


Driver's Signature
(If driver is not the policyholder) Date
& Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN #2

SKETCH PLAN

Date & Time of Accident: 2.5.22 / 1520 Location: North Buona Vista Rd x Commonwealth Ave West Rd
 Veh A: SDS 1238 C Veh B: SLT 206 B Veh C/Others: -

As Attached

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As Attached

NOTE : PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION.

[] Own Damage Claim at Lim Tan Motor [☒] TP Claim at Lim Tan Motor
 [] Own Damage Claim at Other Workshop [] TP Claim at Other Workshop [] Reporting Only


I/We hereby authorised Lim Tan Motor Pte Ltd to forward my/our filed GIA accident report to:-


My/Our workshop via email : _____

My/Our email : _____

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature Date
 & Time:


 Driver's Signature
 (If driver is not the policyholder) Date
 & Time:




 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

GIARMC SketchPlanForm_V3

2

3rd May 2022

To whom it may concern at MSIG

Dear Sir/Madam,

LETTER OF AUTHORISATION FOR VEHICLE ACCIDENT REPORTING FOR SDS1238C

I, Jeremiah Han (driver of the above vehicle at time of accident) of NRIC S9336070B, hereby authorise my mother, Mdm Chan Yim Leng (the owner of SDS1238C), of NRIC S1352261H, to report the accident that occurred between SDS 1238C and SLT 206B on my behalf.

Details are as follows:

A) Date and Time of accident: 2 May 2022 at 1520 hours

B) Vehicle A – SDS1238C, a black Toyota Altis driven by me, Jeremiah Han, NRIC S9336070B

C) Vehicle B – SLT206B, a blue Mazda driven by Mr Hon Cheong, NRIC S9137568J

D) Description of accident – I, Jeremiah Han, was driving Vehicle A along a straight main road, North Buona Vista Road which was a dual carriage way. My vehicle came to a stop at the junction of this road and Commonwealth Avenue West Road because the traffic lights had turned red. My vehicle was stationary for a while waiting for the traffic lights to turn green. Suddenly I heard a bang sound and felt a jerk. It turned out that Vehicle B had hit the rear of my car.

E) Description of damage on Vehicle A – The rear of my car was damaged. Both the bumper and the car plate became loose and there was a visible scratch on the bumper.

F) Description of damage on Vehicle B – The front of the car was slightly damaged.

G) Weather & Traffic condition at time of accident – The weather was clear and the road was dry. The road speed limit was 70km/hour. The traffic volume was light. No other pedestrians or cars were involved in this accident.

H) Agreement with Mr Hon Cheong – Verbally, Mr Hon Cheong admitted that it was his fault and that he would pay for all the damages and replacement vehicle needed by me during the time of repair.

I) A sketch plan of the accident is attached as Appendix A.


Thank You

Yours Sincerely



Dr. Jeremiah Han Zhenwei,
22 Lorong Puntong #08-03, Singapore 576439
Mobile number : 97737626

Sketch Plan of accident and location for the accident on 2 May 2022 at 1520 hours



Submitted by Jeremiah Han : *J*

Not Withheld
Heavy B&P
2 days

Q 1223.85



ESTIMATE TO REPAIR

VEHICLE NO. : SDS 1238 C
MAKE : TOYOTA
MODEL : COROLLA ATIS 1.6 CVT
YEAR : 2016
CHASSIS NO : MR053REH104559272

SURVEYOR NAME : Kenneth
DATE OF SURVEY : 20.05.2022
TIME OF SURVEY :

DATE : 5-May-22
DATE OF ACCIDENT : 2-May-22
THIRD PARTY REF : SLT 206 B / SOMPO

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	rear bumper 540.20			Bumper	\$589.50 ✓
2 ps	rear bumper retainer		\$116.00	ps	\$232.00 x
2 ps	rear bumper bracket		\$64.00	ps	\$128.00 ✓
10 ps	rear bumper clip		\$3.50	ps	\$35.00 ✓
1 pc per	rear bumper sensor			Short	\$496.60 ✓
					\$1,481.10
	less 25%				\$370.28
					\$1,110.83
	To putty and spray paint.				\$350.00 22d
	Labour charges.				\$450.00 2cd
TG-ML/-	TOTAL				\$1,910.83

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127

Email: edmund@LTM.sg

Website : www.LTM.sg