

(08/11/13) wef
ASS. REC. BY: *Carne*

REF:

CS/NC22004286/RVY3

C
985R

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *GAE 5109M*

at Workshop m/s *WAT HONK*

of *28,70th Guan Road EAST #01-57*

Insured: *GBJ 3098Y INC*

Policy No. _____

Claims No. *MT/1171307-002*

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value: *32K*

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: *GAE 5109M* Yr Regn: *2015 / DBC*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *NISSAN NV200 1.5MT* c.c. *1461*

Colour: *WHITE* A/C: *Insured / Std / NI / NA*

Sp. Reading: *168261* T/Radio: *Insured / Std / NI / NA*

Eng/No: _____

C/No: *VSKYBAM 202011447*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: *Inorder* / Jammed / Leaked / Burnt or

Brake: *Inorder* / Jammed / Leaked / Burnt or

Modi: *Nil* / S/Rim / STD A/Rim or

Tyre Size: F: *175/70R14*

R: _____

BS / *DUN* / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. *6* mm

R/Bal. *6* mm

L/Bal. *6* mm

L/Bal. *6* mm

D.O.A. *04/05/22*

D.O.I. *10/05/22*

Survey held at *WAT HONK*

Des. of Damages: *Frnt* / *Rear* / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 16K

6/7/22 Rasul informed LS \$10,400 (Red 8818.50, 45%)

Date/Time, File Pass to?

☐

: Prell. Report

Days Of Repair: *12*

1)

☐

: Final Report

Resurvey No. of Trip: *2*

Date/Time, File Return to?

2) 6/7/22-typist

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS, SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

Report Format: *TP*

Lump Sum H.B.: (\$ 10,400)



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref	: WH1170
Vehicle No.	: GBE5109M
Make & Model	: NISSAN NV200

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
	PARTS (LIST ITEMS)			
1	Rear fender outer panel LH <i>buc /</i>		1637.00	
1	Tail lamp outer panel LH <i>2?</i>		466.00	
1	Rear fender center track garnish LH <i>X</i>		168.00	
1	Rear floor panel <i>repa-y</i>		1375.00	
1	End panel top garnish <i>?</i>		96.00	
1	Rear fender inner panel LH <i>st /</i>		1354.00	
1	Rear fender inner pillar panel LH <i>st /</i>		155.00	
1	Rear wheel housing outer panel LH <i>?</i>		373.00	
1	Tail lamp LH <i>buc /</i>		252.00	
1	Rear bumper <i>de /</i>		486.00	
2	Rear bumper side bracket LH/RH @2*\$38 <i>m /</i>		76.00	
1	Rear bumper side reflector LH <i>m13 /</i>		62.00	
1	End panel inner <i>st /</i>		576.00	
1	End panel outer <i>st /</i>		157.00	
1	Rear trunk weatherstrip <i>m /</i>		102.00	
1	Rear door RH weatherstrip <i>m /</i>		70.00	
1	Rear door LH <i>st /</i>		1215.00	
1	Rear door inner trim board LH <i>de /</i>		73.00	
1	Rear door upper lock LH <i>?</i>		109.00	
1	Rear door lower lock LH <i>?</i>		116.00	
1	Rear door central lock LH <i>?</i>		254.00	
1	Rear door upper hinge LH <i>?</i>		108.00	
1	Rear door lower hinge LH <i>?</i>		108.00	
1	Rear door checker LH <i>?</i>		84.00	
1	Rear door checker bracket LH <i>X</i>		34.00	
1	Rear door logo badge <i>m /</i>		65.00	
1	Rear door emblem "nv200" <i>m /</i>		95.00	
1	Rear door emblem "dci" <i>m /</i>		136.00	
1	Rear door center garnish LH <i>buc / m13 /</i>		352.00	
2	Rear car plate side lamp LH/RH @2*\$81 <i>con / m14 /</i>		162.00	
1	Rear door outer handle <i>m13 X</i>		254.00	
1	Rear Wiper arm motor <i>?</i>		238.00	
1	Rear Wiper arm <i>X</i>		84.00	
1	Rear Wiper arm cover <i>m13 /</i>		21.00	

1	Rear door RH <i>bt</i>	911.00		
1	Rear door upper lock RH <i>?</i>	109.00		
1	Rear door lower lock RH <i>?</i>	116.00		
1	Front bumper <i>da. de</i>	542.00		
2	Front bumper side retainer LH/RH @2*\$27 <i>X</i>	54.00		
1	Front bumper towing cover <i>de</i>	25.00		
1	Headlamp side lower garnish L/RH @2*\$369 <i>1 pc sm</i>	738.00		
1	Front reinforcement <i>?</i>	767.00		
1	Front bumper sponge <i>?</i>	272.00		
Part Items Total:		14447.00		
		-10%	-1444.70	
			13002.30	
SPECIAL NETT ITEMS				
1	Rear bumper clips <i>m</i>	25.00	<i>✓</i>	
1	Rear floor panel sealant <i>X</i>	60.00	<i>X</i>	
1	End panel sealant <i>m</i>	60.00	<i>40</i>	
1	Rear fender sealant LH <i>m</i>	60.00	<i>40</i>	
1	Rear door windscreen sealant LH <i>m</i>	60.00	<i>80</i>	
1	Rear door windscreen sealant RH <i>m</i>	60.00	<i>80</i>	
1	Rear fender sealant <i>m</i>	50.00	<i>40</i>	
1	Rear Reverse Sensor <i>m</i>	200.00	<i>m</i>	
1	Front car plate with holder <i>bt</i>	35.00	<i>✓</i>	
1	Rear car plate with holder <i>sea</i>	35.00	<i>✓</i>	
1	Rear floor panel top board <i>ca</i>	300.00	<i>200</i>	
1	Rear fender company sticker <i>m</i>	400.00	<i>200</i>	
1	Rear both door company sticker <i>m</i>	400.00	<i>200</i>	
1	70 km/h sticker <i>m</i>	20.00	<i>10</i>	
1	Bizsafe 3 sticker <i>m</i>	80.00	<i>50</i>	
SN Items Total:		1845.00		
Total Parts:		14847.30		



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref : WH1170
Vehicle No. : GBE5109M
Make & Model : NISSAN NV200

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	2000.00	1500
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1600.00	1000
3	To remove and repair/refix wiring system at accident damaged area and check for all electrical proper function	90.00	60
4	To remove and replace Rear reverse sensor	100.00	60
5	To perform anti-rust treatment on affected areas	90.00	40
6	To remove and refit rear door LH windscreen	120.00	60
7	To remove and refit rear door RH windscreen	120.00	60
8	To remove and refit/replace rear compartment fitting, timming, garnish, rear spare tyre with bracket and ect	100.00	60
Labour Total :		4220.00	
TOTAL (PARTS & LABOUR):		19067.30	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Perme
Hp 900 100 68
12 days
L/S
10/05/22 @ 1200
Reg after repair

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any fees reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 05/05/2022 18:02 (SGT)
 Date of Accident 04/05/2022 17:05 (SGT)
 Exact Location of Accident Singapore
 Additional Location Information PIE(Tuas) after CTE(AYE) exit
 Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBES109M
 INSURED/POLICYHOLDER
 Is company? Yes
 Name Of Registered Owner CIS-TRONICS PTE LTD
 Company Reg No 200104955R
 Email Address nicolas@cistronics.com.sg
 Mobile Phone No (Phone) +65-96635895
 Alternative Phone No +65-96635895

VEHICLE PARTICULARS

Manufacturer Nissan
 Model Nv200
 Variant
 Exact purpose for which vehicle was being used at time of accident Employment
 Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
 Vehicle Category Commercial vehicle
 Transmission Manual
 CC 2000

INSURANCE COMPANY

Name of Insurance Company NTUC Income Insurance Co-operative Ltd
 Type of Coverage Comprehensive
 Fleet Policy No
 Policy Number 5114898202-02
 Cover Note Number

DRIVER

Name of Driver ISLAM NOZRUL
 Passport No/FIN G2087686M

Accident report SN0722550015

Date Of Birth 06/01/1984
 Occupation Outdoor
 Date Of Driving Pass 08/10/2020
 Driving experience 1 YEAR AND 7 MONTHS
 Gender Male
 Mobile Number (Phone) +65-88457610
 Alt. Phone Number
 Email Address nicolas@cistronics.com.sg
 Address 50 Toh Guan Road East
 Address complement #03-01
 Postcode S608587
 Is the driver the policyholder? No
 If No, Relationship of the Driver with the Insured Employee
 Does Driver Own Other Vehicles? No
 Vehicle Registration Number of Other Vehicle Owned by Driver
 Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Chain Collision
 Weather Conditions Clear
 Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? Yes
 Number of vehicles involved in the accident 8
 Was anybody injured in the Accident? Yes
 Was any injured conveyed to hospital by ambulance? Yes
 Was any other vehicle or property damaged? Yes
 Number of Passengers (Including Driver) 2
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

FOREIGN VEHICLE 1

Vehicle Registration Number JTF9743
 Vehicle Category Motorcycle

PASSENGER 1

Name SOLAYMAN
 Gender Male

DETAILS OF POLICE ACTION

Was the accident reported to the police? Yes
 Police Station Name Hong Kah North Neighbourhood Police Post
 Police Station Phone No (Phone) +65-1800567999
 Alt. Police Station Phone No (Fax) +65-65652508
 Police Station Address Blk 370 Bukit Batok Street 31 #01-201 Singapore 650370
 Was notice of Intended Prosecution given? No
 If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

Refer to sketch plan

ATTACHMENT(S)

Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? No
 Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBJ3098Y
 Vehicle Manufacturer
 Vehicle Model
 Vehicle Variant
 Vehicle Colour
 Vehicle Category Commercial vehicle
 Name of Driver
 Contact Number
 Address
 Address complement
 Postcode
 Insurance Company Name
 Nature Of Damage
 Details of property damaged in accident
 No. Of Passenger (including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number CB7721K
 Vehicle Manufacturer
 Vehicle Model
 Vehicle Variant
 Vehicle Colour
 Vehicle Category Bus
 Name of Driver
 Contact Number
 Address
 Address complement
 Postcode
 Insurance Company Name
 Nature Of Damage
 Details of property damaged in accident
 No. Of Passenger (including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number EP1118U
 Vehicle Manufacturer
 Vehicle Model
 Vehicle Variant
 Vehicle Colour
 Vehicle Category Private car
 Name of Driver
 Contact Number
 Address
 Address complement
 Postcode
 Insurance Company Name
 Nature Of Damage
 Details of property damaged in accident
 No. Of Passenger (including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number JTF9743
 Vehicle Manufacturer
 Vehicle Model
 Vehicle Variant
 Vehicle Colour
 Vehicle Category Motorcycle
 Name of Driver
 Contact Number

Address
 Address complement
 Postcode
 Insurance Company Name
 Nature Of Damage
 Details of property damaged in accident
 No. Of Passenger (including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 5

Vehicle Registration Number UNKNOWN
 Vehicle Manufacturer
 Vehicle Model
 Vehicle Variant
 Vehicle Colour
 Vehicle Category Taxi
 Name of Driver
 Contact Number
 Address
 Address complement
 Postcode
 Insurance Company Name
 Nature Of Damage
 Details of property damaged in accident
 No. Of Passenger (including Driver)

INJURED PERSONS DETAILS

INJURED 1

Name of injured person UNKNOWN
 Gender
 Phone No
 Address
 Address Complement
 Post Code
 Approximate Age Years Old
 Injuries Sustained
 Injured person in which vehicle? JTF9743
 Were seat belts worn? No
 Was this injured conveyed to hospital by ambulance? Yes



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Hong Kah North NPP
370 Bukit Batok Street 31 #01-201
SINGAPORE 650370
Tel No: 1800-5679999



1/20220504/0096

1 of 4

Report No. T/20220504/0096

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 05/05/2022 18:58		Vide Report No.: J/20220504/0096	Station Diary No.: 69
Name of Informant: ISLAM NOZRUL		Address: 60 TOH GUAN ROAD EAST #03-01 QUEK INDUSTRIAL BUILDING SINGAPORE 606587	
ID Type / ID No.: FIN NO / G2087686M		Contact No.: Home/Office: Mobile: 88457810	
Nationality: BANGLADESHI		Email:	
Sex: Male	Age: 38	Date of Birth: 06/01/1984	Type of Informant: Driver
Race: Bangladeshi		Language:	
Occupation: SYSTEM INSTALLER		Institution / School Name:	
Driving Licence Information: Class: 3		Date of Expiry:	

Type of Accident: Collision	Injury: Absence by Police	Drink Drive: No	Date/Time of Accident: 04/05/2022 17:05	Type of Location: Borough Road
Location: PAN ISLAND EXPRESSWAY				
Road Surface: Dry		Road Speed Limit:		
Traffic Control: Not Controlled		Traffic Volume: Moderate		
Anyone conveyed by ambulance: Yes				

Vehicle	Make	Model	Color	Damage	Notes
DRIVER	TOYOTA	SPACE SUPER GL	White	Seriously Damaged	1
OTHER	TOYOTA	MODELS STANDARD RANGE	White	Slightly Damaged	0



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Hong Kah North NPP
370 Bukit Batok Street 31 #01-201
SINGAPORE 650370
Tel No: 1800-5679999



1/20220504/0096

1 of 4

Report No. T/20220504/0096

CONTINUATION OF REPORT

Vehicle	Make	Model	Color	Damage	Notes
GBES108M	Van	NISSAN NV200 1.8 MT ABS AIRBAG ZWD 6DR ELNWB	White	Seriously Damaged	1
GBJ308Y	Van	TOYOTA HIACE VAN TURBO 5DR MT	Silver	Seriously Damaged	0
JTF8743	Motorcycle	YAMAHA LC135		Seriously Damaged	0

Any Pedestrian Involved: No		Use of Pedestrian Crossing: NA	
No. of Pedestrians Injured: NA			
Name:	ISLAM NOZRUL	ID No.:	G2087686M
Related Vehicle:	GBES108M (Van)	Contact No.:	88457810
Hospital/ Clinic:	NA	Class of Driving Licence & Expiry Date:	Class: 3 Date of Expiry: NA
Date/Time of Accident:	04/05/2022 17:05	Date/Time of Report:	05/05/2022 18:58
Rev. of Date/Time of Medical Leave:	NA	Rev. of Date/Time of Injury:	NA

Witness Details:
On 04/05/2022 at around 17:05hrs, I was driving along ME Avenue, TMA3. I was driving along road 2 and traffic volume was quite moderate.

Vehicle bearing plate number 88457810 (Van) was in front of me and had slowed down. I slowed down as well and suddenly felt an impact and came to a halt. This impact had caused me to collide with the Van.

A male driver (name: JTF8743) (V2) was in front of me and had slowed down. This is when a motorcycle (bearing plate number JTF8743) (V2) arrived in my lane from the right to make a left turn with the motorcycle bearing plate number JTF8743 (V2) and causing the crash.

I went out to inspect the accident and discovered that I was a crash victim. The vehicle was parked between two cars and a van (bearing plate number G2087686M) and the vehicle behind it was stopped. The driver (bearing plate number G2087686M) (V1) was in the driver's seat.

After getting into Traffic Police station at around 18:00hrs, I was interviewed by Traffic Police and I was interviewed by a Traffic Police officer (name: JTF8743) (V2) and I was interviewed by a Traffic Police officer (name: JTF8743) (V2) and I was interviewed by a Traffic Police officer (name: JTF8743) (V2).



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Hong Kah North NPP
370 Bukit Batok Street 31 #01-201
SINGAPORE 650370
Tel No: 1800-5679999



7/20220505/2083

3 of 4

Report No: 7/20220505/2083

CONTINUATION OF REPORT

From the incident, my vehicle sustained serious dents and scratches on the rear door, V1 sustained serious dents and scratches on the front hood and bumper, rear door and broken rear windshield, V2 sustained serious damages on the front hood and bumper, V3 was totally damaged and V4 sustained slight scratches on the rear bumper.

The rider was injured and conveyed by ambulance to the nearest hospital, the lady passenger of V2 has a minor laceration on her shin. Other than that, no one else was injured or conveyed by ambulance.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Hong Kah North NPP
370 Bukit Batok Street 31 #01-201
SINGAPORE 650370
Tel No: 1800-5679999



7/20220505/2083

4 of 4

Report No: 7/20220505/2083

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 8442 808 during the report interview as reference.

Signature of Officer Recording This Report:
Officer: HARILAN ARSIN
OTTHAN

Signature of Insurance:
Not applicable

Officer in Charge of Case:
Officer: ITAM YULI BUDAH BUDDY SANTOSO
Case No: 65475 113

IP No:

Signature of Informant:

Date/Time:
20220505 14:54

Classification Of Case:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	955R
Vehicle Details	
Vehicle No.:	GBE5109M
Vehicle to be Exported:	No
Intended Deregistration Date:	06 May 2022
Vehicle Make:	NISSAN
Vehicle Model:	NV200 1.5 MT ABS AIRBAG 2WD 6DR E5 W/RC
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	K9KC400D054907
Chassis No.:	VSKYBAM20Z0114947
Maximum Power Output:	-
Open Market Value:	\$19,737.00
Original Registration Date:	29 Dec 2015
First Registration Date:	29 Dec 2015
Transfer Count:	0
Actual ARF Paid:	\$987.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Dec 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$44,056.00
COE Rebate Amount:	\$16,047.00
Total Rebate Amount:	\$16,047.00

The information contained herein is correct as at 06 May 2022

OK

Nissan NV200 1.5M

[Overview](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)**ABWIN** 諭輝

YOUR FIRST CHOICE AUTOMOTIVE SERVICE PROVIDER



Price	\$32,800	Lifespan	30-Dec-2035
Depreciation	\$9,010 /yr View models with similar depre	Reg Date	31-Dec-2015 (3yrs 7mths 19days COE left)
Mileage	N.A.	Manufactured	2015
Road Tax	N.A.	Transmission	Manual
Dereg Value	\$5,829 as of today (change)	Fuel Type	Diesel
COE	\$16,009	OMV	\$19,737
Engine Cap	1,461 cc	ARF	\$987
Curb Weight	1,260 kg	No. of Owners	2