







# Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref	: WH1170
Vehicle No.	: GBE5109M
Make & Model	: NISSAN NV200

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
	<b>PARTS (LIST ITEMS)</b>			
1	Rear fender outer panel LH <i>buc /</i>		1637.00	
1	Tail lamp outer panel LH <i>?</i>		466.00	
1	Rear fender center track garnish LH <i>X</i>		168.00	
1	Rear floor panel <i>repa-y</i>		1375.00	
1	End panel top garnish <i>?</i>		96.00	
1	Rear fender inner panel LH <i>st /</i>		1354.00	
1	Rear fender inner pillar panel LH <i>st /</i>		155.00	
1	Rear wheel housing outer panel LH <i>?</i>		373.00	
1	Tail lamp LH <i>buc /</i>		252.00	
1	Rear bumper <i>de /</i>		486.00	
2	Rear bumper side bracket LH/RH @2*\$38 <i>m /</i>		76.00	
1	Rear bumper side reflector LH <i>m13 /</i>		62.00	
1	End panel inner <i>st /</i>		576.00	
1	End panel outer <i>st /</i>		157.00	
1	Rear trunk weatherstrip <i>m /</i>		102.00	
1	Rear door RH weatherstrip <i>m /</i>		70.00	
1	Rear door LH <i>st /</i>		1215.00	
1	Rear door inner trim board LH <i>de /</i>		73.00	
1	Rear door upper lock LH <i>?</i>		109.00	
1	Rear door lower lock LH <i>?</i>		116.00	
1	Rear door central lock LH <i>?</i>		254.00	
1	Rear door upper hinge LH <i>?</i>		108.00	
1	Rear door lower hinge LH <i>?</i>		108.00	
1	Rear door checker LH <i>?</i>		84.00	
1	Rear door checker bracket LH <i>X</i>		34.00	
1	Rear door logo badge <i>m /</i>		65.00	
1	Rear door emblem "nv200" <i>m /</i>		95.00	
1	Rear door emblem "dci" <i>m /</i>		136.00	
1	Rear door center garnish LH <i>buc / m13 /</i>		352.00	
2	Rear car plate side lamp LH/RH @2*\$81 <i>con / m13 /</i>		162.00	
1	Rear door outer handle <i>m13 X</i>		254.00	
1	Rear Wiper arm motor <i>?</i>		238.00	
1	Rear Wiper arm <i>X</i>		84.00	
1	Rear Wiper arm cover <i>m13 /</i>		21.00	

1	Rear door RH <i>bt</i>	911.00		
1	Rear door upper lock RH <i>?</i>	109.00		
1	Rear door lower lock RH <i>?</i>	116.00		
1	Front bumper <i>da. de</i>	542.00		
2	Front bumper side retainer LH/RH @2*\$27 <i>X</i>	54.00		
1	Front bumper towing cover <i>de</i>	25.00		
1	Headlamp side lower garnish L/RH @2*\$369 <i>1 pc sm</i>	738.00		
1	Front reinforcement <i>?</i>	767.00		
1	Front bumper sponge <i>?</i>	272.00		
Part Items Total:		14447.00		
		-10%	-1444.70	
			13002.30	
SPECIAL NETT ITEMS				
1	Rear bumper clips <i>m</i>	25.00		
1	Rear floor panel sealant <i>X</i>	60.00		
1	End panel sealant <i>m</i>	<del>60.00</del>		<i>40</i>
1	Rear fender sealant LH <i>m</i>	<del>60.00</del>		<i>40</i>
1	Rear door windscreen sealant LH <i>m</i>	<del>60.00</del>		<i>80</i>
1	Rear door windscreen sealant RH <i>m</i>	<del>60.00</del>		<i>80</i>
1	Rear fender sealant <i>m</i>	<del>50.00</del>		<i>40</i>
1	Rear Reverse Sensor <i>m</i>	200.00		<i>m</i>
1	Front car plate with holder <i>bt</i>	35.00		
1	Rear car plate with holder <i>sea</i>	35.00		
1	Rear floor panel top board <i>ca</i>	<del>300.00</del>		<i>200</i>
1	Rear fender company sticker <i>m</i>	<del>400.00</del>		<i>200</i>
1	Rear both door company sticker <i>m</i>	<del>400.00</del>		<i>200</i>
1	70 km/h sticker <i>m</i>	<del>20.00</del>		<i>10</i>
1	Bizsafe 3 sticker <i>m</i>	<del>80.00</del>		<i>50</i>
SN Items Total:		1845.00		
Total Parts:		14847.30		



# Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref : WH1170  
Vehicle No. : GBE5109M  
Make & Model : NISSAN NV200

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
1	<b>LABOUR</b> To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	<del>2000.00</del>	1500
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	<del>1600.00</del>	1000
3	To remove and repair/refix wiring system at accident damaged area and check for all electrical proper function	<del>90.00</del>	60
4	To remove and replace Rear reverse sensor	<del>100.00</del>	60
5	To perform anti-rust treatment on affected areas	<del>90.00</del>	40
6	To remove and refit rear door LH windscreen	<del>120.00</del>	60
7	To remove and refit rear door RH windscreen	<del>120.00</del>	60
8	To remove and refit/replace rear compartment fitting, timming, garnish, rear spare tyre with bracket and ect	<del>100.00</del>	60
Labour Total :		4220.00	
TOTAL (PARTS & LABOUR):		19067.30	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Perme  
Hp 900 100 68  
12 days  
L/S  
10/05/22 @ 1200  
Reg after repair



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any fees reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission 05/05/2022 18:02 (SGT)  
Date of Accident 04/05/2022 17:05 (SGT)  
Exact Location of Accident Singapore  
Additional Location Information PIE(Tuas) after CTE(AYE) exit  
Country/State of Loss Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number GBES109M  
  
INSURED/POLICYHOLDER  
  
Is company? Yes  
Name Of Registered Owner CIS-TRONICS PTE LTD  
Company Reg No 200104955R  
Email Address nicolas@cistronics.com.sg  
Mobile Phone No (Phone) +65-96635895  
Alternative Phone No +65-96635895

### VEHICLE PARTICULARS

Manufacturer Nissan  
Model Nv200  
Variant  
Exact purpose for which vehicle was being used at time of accident Employment  
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party  
Vehicle Category Commercial vehicle  
Transmission Manual  
CC 2000

### INSURANCE COMPANY

Name of Insurance Company NTUC Income Insurance Co-operative Ltd  
Type of Coverage Comprehensive  
Fleet Policy No  
Policy Number 5114898202-02  
Cover Note Number

### DRIVER

Name of Driver ISLAM NOZRUL  
Passport No/FIN G2087686M

Accident report SN0722550015

Date Of Birth 06/01/1984  
Occupation Outdoor  
Date Of Driving Pass 08/10/2020  
Driving experience 1 YEAR AND 7 MONTHS  
Gender Male  
Mobile Number (Phone) +65-88457610  
Alt. Phone Number  
Email Address nicolas@cistronics.com.sg  
Address 50 Toh Guan Road East  
Address complement #03-01  
Postcode S608587  
Is the driver the policyholder? No  
If No, Relationship of the Driver with the Insured Employee  
Does Driver Own Other Vehicles? No  
Vehicle Registration Number of Other Vehicle Owned by Driver  
Insurance Company of Other Vehicle Owned by Driver

### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Chain Collision  
Weather Conditions Clear  
Road Surface Dry

### OTHER INFORMATION

Was any foreign vehicle involved in the accident? Yes  
Number of vehicles involved in the accident 8  
Was anybody injured in the Accident? Yes  
Was any injured conveyed to hospital by ambulance? Yes  
Was any other vehicle or property damaged? Yes  
Number of Passengers (Including Driver) 2  
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

### FOREIGN VEHICLE 1

Vehicle Registration Number JTF9743  
Vehicle Category Motorcycle

### PASSENGER 1

Name SOLAYMAN  
Gender Male

### DETAILS OF POLICE ACTION

Was the accident reported to the police? Yes  
Police Station Name Hong Kah North Neighbourhood Police Post  
Police Station Phone No (Phone) +65-1800567999  
Alt. Police Station Phone No (Fax) +65-65652508  
Police Station Address Blk 370 Bukit Batok Street 31 #01-201 Singapore 650370  
Was notice of Intended Prosecution given? No  
If yes, against whom?

### CIRCUMSTANCES OF ACCIDENT

Refer to sketch plan

### ATTACHMENT(S)

Are accident photos available for attachment? Yes  
Was there any video captured by Car Camera? No  
Was there any audio recorded? No

Accident report SN0722550015

# DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBJ3098Y  
Vehicle Manufacturer  
Vehicle Model  
Vehicle Variant  
Vehicle Colour  
Vehicle Category Commercial vehicle  
Name of Driver  
Contact Number  
Address  
Address complement  
Postcode  
Insurance Company Name  
Nature Of Damage  
Details of property damaged in accident  
No. Of Passenger (including Driver)

# DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number CB7721K  
Vehicle Manufacturer  
Vehicle Model  
Vehicle Variant  
Vehicle Colour  
Vehicle Category Bus  
Name of Driver  
Contact Number  
Address  
Address complement  
Postcode  
Insurance Company Name  
Nature Of Damage  
Details of property damaged in accident  
No. Of Passenger (including Driver)

# DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number EP1118U  
Vehicle Manufacturer  
Vehicle Model  
Vehicle Variant  
Vehicle Colour  
Vehicle Category Private car  
Name of Driver  
Contact Number  
Address  
Address complement  
Postcode  
Insurance Company Name  
Nature Of Damage  
Details of property damaged in accident  
No. Of Passenger (including Driver)

# DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number JTF9743  
Vehicle Manufacturer  
Vehicle Model  
Vehicle Variant  
Vehicle Colour  
Vehicle Category Motorcycle  
Name of Driver  
Contact Number

Address  
Address complement  
Postcode  
Insurance Company Name  
Nature Of Damage  
Details of property damaged in accident  
No. Of Passenger (including Driver)

# DETAILS OF OTHER VEHICLE PROPERTY 5

Vehicle Registration Number UNKNOWN  
Vehicle Manufacturer  
Vehicle Model  
Vehicle Variant  
Vehicle Colour  
Vehicle Category Taxi  
Name of Driver  
Contact Number  
Address  
Address complement  
Postcode  
Insurance Company Name  
Nature Of Damage  
Details of property damaged in accident  
No. Of Passenger (including Driver)

# INJURED PERSONS DETAILS

## INJURED 1

Name of injured person UNKNOWN  
Gender  
Phone No  
Address  
Address Complement  
Post Code  
Approximate Age Years Old  
Injuries Sustained  
Injured person in which vehicle? JTF9743  
Were seat belts worn? No  
Was this injured conveyed to hospital by ambulance? Yes









**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Hong Kah North NPP  
370 Bukit Batok Street 31 #01-201  
SINGAPORE 650370  
Tel No: 1800-5679999



1/20220504/0096

1 of 4

Report No. T/20220504/0096

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 05/05/2022 18:58		Vide Report No.: J/20220504/0096	Station Diary No.: 69
Name of Informant: ISLAM NOZRUL		Address: 60 TOH GUAN ROAD EAST #03-01 QUEK INDUSTRIAL BUILDING SINGAPORE 606587	
ID Type / ID No.: FIN NO / G2087686M		Contact No.: Home/Office: Mobile: 88457810	
Nationality: BANGLADESHI		Email:	
Sex: Male	Age: 38	Date of Birth: 06/01/1984	Type of Informant: Driver
Race: Bangladeshi		Language:	
Occupation: SYSTEM INSTALLER		Institution / School Name:	
Driving Licence Information: Class: 3		Date of Expiry:	

Type of Accident: Collision	Injury Sustained by Police: None	Drink Drive: No	Date/Time of Accident: 04/05/2022 17:05	Type of Location: Borough Road
Location: PAN ISLAND EXPRESSWAY				
Road Surface: Dry		Road Speed Limit: None		
Traffic Control: Not Controlled		Traffic Volume: Moderate		
Weather Condition: Clear		Anyone conveyed by ambulance: Yes		

Vehicle	Make	Model	Color	Damage	Notes
VEHICLE 1	TOYOTA	SPACE SUPER GL	White	Seriously Damaged	1
VEHICLE 2	TOYOTA	MODELS STANDARD RANGE	White	Slightly Damaged	0



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Hong Kah North NPP  
370 Bukit Batok Street 31 #01-201  
SINGAPORE 650370  
Tel No: 1800-5679999



1/20220504/0096

1 of 4

Report No. T/20220504/0096

**CONTINUATION OF REPORT**

Vehicle	Make	Model	Color	Damage	Notes
GBES108M	Van	NISSAN NV200 1.8 MT ABS AIRBAG ZWD 6DR ELNWB	White	Seriously Damaged	1
GBJ308Y	Van	TOYOTA HIACE VAN TURBO 5DR MT	Silver	Seriously Damaged	0
JTF8743	Motorcycle	YAMAHA LC135		Seriously Damaged	0

Are Pedestrians Involved: No		Use of Pedestrian Crossing: NA	
No. of Pedestrians Injured: NA			
Name:	ISLAM NOZRUL	ID No.:	G2087686M
Related Vehicle:	GBES108M (Van)	Contact No.:	88457810
Hospital/ Clinic:	NA	Class of Driving Licence & Expiry Date:	Class: 3 Date of Expiry: NA
Date/Time of Accident:	04/05/2022 17:05	Date/Time of Report:	05/05/2022 18:58
Rev. of Driver's License:	NA	Rev. of Driver's License:	NA

**Witness Details:**  
On 04/05/2022 at around 17:05hrs, I was driving along the expressway. I was driving along the road and I was driving along the road and I was driving along the road.

Vehicle bearing plate number GBES108M (Van) was in front of me and had moved down. I stopped down to see what happened and I saw that the vehicle had moved down. I saw that the vehicle had moved down.

A white van (Van) was in front of me and had moved down. I stopped down to see what happened and I saw that the vehicle had moved down. I saw that the vehicle had moved down.

I saw that the vehicle had moved down and I saw that the vehicle had moved down. I saw that the vehicle had moved down and I saw that the vehicle had moved down.

Police officers from Traffic Police arrived at the scene. They saw that the vehicle had moved down and they saw that the vehicle had moved down.





**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Hong Kah North NPP  
370 Bukit Batok Street 31 #01-201  
SINGAPORE 650370  
Tel No: 1800-5679999



7/20220505/2083

3 of 4

Report No: 7/20220505/2083

**CONTINUATION OF REPORT**

From the incident, my vehicle sustained serious dents and scratches on the rear door, V1 sustained serious dents and scratches on the front hood and bumper, rear door and broken rear windshield, V2 sustained serious damages on the front hood and bumper, V3 was totally damaged and V4 sustained slight scratches on the rear bumper.

The rider was injured and conveyed by ambulance to the nearest hospital, the lady passenger of V2 has a minor laceration on her shin. Other than that, no one else was injured or conveyed by ambulance.



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Hong Kah North NPP  
370 Bukit Batok Street 31 #01-201  
SINGAPORE 650370  
Tel No: 1800-5679999



7/20220505/2083

4 of 4

Report No: 7/20220505/2083

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 8442 808 during the report interview as reference.

Signature of Officer Recording This Report

Officer: HARILAN ABE BIN  
OTHMAN

Signature of Insurance  
Not applicable

Officer in Charge of Case

Officer: ITAM YULU BUDAH BUDDY SANTOSO  
Case No: 65475 113

IP No:

Signature of Informant

Date/Time:  
05/05/2022 14:54

Classification Of Case:



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	955R
<b>Vehicle Details</b>	
Vehicle No.:	GBE5109M
Vehicle to be Exported:	No
Intended Deregistration Date:	06 May 2022
Vehicle Make:	NISSAN
Vehicle Model:	NV200 1.5 MT ABS AIRBAG 2WD 6DR E5 W/RC
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	K9KC400D054907
Chassis No.:	VSKYBAM20Z0114947
Maximum Power Output:	-
Open Market Value:	\$19,737.00
Original Registration Date:	29 Dec 2015
First Registration Date:	29 Dec 2015
Transfer Count:	0
Actual ARF Paid:	\$987.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	28 Dec 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$44,056.00
COE Rebate Amount:	\$16,047.00
<b>Total Rebate Amount:</b>	<b>\$16,047.00</b>

The information contained herein is correct as at 06 May 2022

OK



# Nissan NV200 1.5M

[Overview](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)**ABWIN** 諭輝

YOUR FIRST CHOICE AUTOMOTIVE SERVICE PROVIDER



Price	<b>\$32,800</b>	Lifespan	30-Dec-2035
Depreciation	\$9,010 /yr <a href="#">View models with similar depre</a>	Reg Date	31-Dec-2015 (3yrs 7mths 19days COE left)
Mileage	N.A.	Manufactured	2015
Road Tax	N.A.	Transmission	Manual
Dereg Value	\$5,829 as of today (change)	Fuel Type	Diesel
COE	\$16,009	OMV	\$19,737
Engine Cap	1,461 cc	ARF	\$987
Curb Weight	1,260 kg	No. of Owners	2