

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT					
	NTUC INCOME INS		Ref:	CS/INC22004286/Rvy3e2	
	73 BRAS BASAH R #05-01 NTUC TRAI 189556	OAD DE UNION HOUSESINGAPORE		Date:	08/07/2022
	ATTN: CYNTHIA AI	NG		Code:	INC
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBJ 3098Y	Veh. Inspected		GBE 5109M
	Policy No.		Coverage (\$)		0.00
	Claim No.	MT/1171307-002	Excess (\$)		0.00
	Assign From	Hazalysa Binte Ibrahim	Assign Date		09/05/2022
2. Vehicle Particulars & Condition					
	Make & Model	NISSAN NV200 1.5 MT	c.c		1461
	Engine No.	HIDDEN	Year of Reg.		2015
	Chassis No.	VSKYBAM20Z0114947	Colour		WHITE
	Odometer	168261 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		NIL
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	175/70 R14	DUNLOP		6 mm
	L/H Front Tyre	175/70 R14	DUNLOP		6 mm
	R/H Rear Tyre	175/70 R14	DUNLOP		6 mm
	L/H Rear Tyre	175/70 R14	DUNLOP		6 mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	04/05/2022	Inspect Date /	Time	10/05/2022 (12:02 PM)
	Survey held at	Id at WAH HONG MOTORS & CREDIT PTE LTD 38 TOH GUAN ROAD EAST #01-57 ENTERPRISE HUB SINGAPORE 608581			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORM	AL PERIOD FOR REPAIR:		12 Work	king Days