

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE I	PTE LTD		Ref:	CS/ASM22004342/Uty3s2	
	8 SHENTON WAY AXA TOWERSING			Date:	30/05/2022	
				Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SHD 3044M	Veh. Inspected	l	SMC 6052R	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	S2M040JV	Excess (\$)		0.00	
	Assign From	OH Vale	Assign Date		10/05/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA CITY (A)	c.c		1497	
	Engine No.	HIDDEN	Year of Reg.		2014	
	Chassis No.	MRHGM6660EP000111	Colour		SILVER	
	Odometer	092566 KM	Steering		AFFECTED	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	185/55 R16	MICHELIN		6 mm	
	L/H Front Tyre	185/55 R16	MICHELIN		6 mm	
	R/H Rear Tyre	185/55 R16	MICHELIN		6 mm	
	L/H Rear Tyre	185/55 R16	MICHELIN		6 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.					
	DAMAGES SEE DE	AMAGES SEE DETAILS.				
5.	General Information					
	Accident Date	06/05/2022	Inspection Dat	е	10/05/2022	
	Survey held at	vey held at SIONG HAI MOTOR WORKSHOP				
		1 KAKI BUKIT AVENUE 6 # 02-03 AUTOBAY SINGAPORE 417883.				
5a.	5a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORN	MAL PERIOD FOR REPAIR:		4 Worki	ng Days	