



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KHOR SAW THENG			Ref: CC4/ASM22004346/Kpa3q2 Date: 02/11/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLN 2182D	Veh. Inspected	GBE 3099X	
Policy No.	GA554046	Coverage (\$)	0.00	
Claim No.	S2M040L4	Excess (\$)	0.00	
Assign From		Assign Date	10/05/2022	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV200 (A)	c.c	1597	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	VM20082812	Colour	SILVER	
Odometer	164845 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	165 R14X8	YOKOHAMA	8 mm	
L/H Front Tyre	165 R14X8	YOKOHAMA	8 mm	
R/H Rear Tyre	165 R14X8	YOKOHAMA	8 mm	
L/H Rear Tyre	165 R14X8	YOKOHAMA	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/04/2022	Inspection Date	11/05/2022	
Survey held at	KIEN CHEONG MOTOR WORKS BLK 9 SIN MING IND EST SECTOR C #01-26 SINGAPORE 575644			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		