

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 May 2022 <a href="#">Sendback Est</a>	07 May 2022 15:04 <b>S\$ 3,830.81</b>	10 May 2022 11:07 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

### CLAIM SUBFOLDER DETAILS

Insured:	NUR HASLINA KOH BINTE JOHARI , ID : S9106032I		
Main Claimant:	NUR HASLINA KOH BINTE JOHARI		
Vehicle Reg. No.:	SMX9331E	Date of Loss :	26/04/2022 10:00 - :59 [14 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM22D202847/C02/TAYHP	Policy/Cover Note No. :	SNM22D202847/C02/TAYHP
Vehicle Reg. No. (Insured):	SJD8849B	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Auto Insure Pte Ltd (HQ) (Woodlands) 6 Marsiling Lane, 739145 Woodlands - Tel: 3157 2626		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 20/05/2022]		
Driver/Custodian (Insured):	NUR HASLINA KOH BINTE JOHARI ( / Female) , NRIC: S9106032I Email:		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

### ALL ASSOCIATED FILE NOTES

[Create New](#)

No.	Status	Type	Viewer/Assigned To	Note	Created On	Created By	1st Read By
No results.							

### ADJUSTER'S CLAIM REFERENCE

Assignment From:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		
Adj File Ref No:	CS/CTI22004352/RTY3	Assignment Date:	10/05/2022
Inspection / Investigation Date:		Report Date:	
Insurance Claim No:	SNM22D202847/C02/TAYHP	Recmd'd Resv. (S\$):	
Manager:	DENISE TAY KWEE CHENG	Adjuster:	MOHD RASUL
Clerical:	(First Pick-up)		
Present Vehicle Loc.:	Auto Insure Pte Ltd (HQ) (Woodlands) (from est.) (Check-in: 07/05/2022)		
Assignment Remarks:	PLEASE SURVEY AND REVERT		

### DESCRIPTION OF VEHICLE

Vehicle Model:	<b>TOYOTA RAIZE 1.0 X CVT (A)</b>					
Engine No:	1KRK035924			Chassis No:	A200A0030265	
LTA Reg Date (Man Yr):	05/02/2021 (2021)					
Colour of Vehicle:	Metallic Blue			Odometer Reading:	14909 km	

### CLAIM LOSS DETAILS

Police Report No (Date):		Party At Fault:	Unknown
Collision With:	Private Vehicle	Nature of Loss:	
Description of Accident/Loss:			

DOCUMENTS CHECKLIST

All Completed   Reset   Save   Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

DOCUMENTS SUMMARY

Assessment Reports

- Auto Insure Pte Ltd (HQ) (Woodlands) [Thumbnails]:(07/05/22) Repairer Estimates

Photos/Images

- Auto Insure Pte Ltd (HQ) (Woodlands) [Thumbnails]:(07/05/22) Front View, Front View Left, Front View Right, Rear View, Rear View Left, Rear View Right, Photographs of Damaged Parts, Photographs of Damaged Parts, Photographs of Damaged Parts, Photographs of Damaged Parts, Photographs of Damaged Parts, Photographs of Damaged Parts, Odometer Reading, BADGE CHASSIS

Documentation

- Auto Insure Pte Ltd (HQ) (Woodlands) [Thumbnails]:(07/05/22) AUDATEX ESTIMATE GIA REPORT