

ASS. REC. BY: PAHREF: CS/CT1 2200 4852 R143

Rny3

032 L

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMX 9331Eat Workshop m/s ANNOINSUREof 6, marescunh laneInsured: CTI

Policy No. _____


Claims No. SNM22D202847/C02

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 92k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMX 9331E Yr Regn: 2021 / FEB

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA RAIZE 1.0XCVT c.c. 996Colour: BLUE A/C: Insured / Std / NI / NASp. Reading: 15178 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: A200A 0036 265Gen. Cond: Good / PA / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NI / S/Rim / STD A/Rim orTyre Size: F: 195/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 26/08/22 D.O.I. 10/08/22Survey held at ANNOINSUREDes. of Damages: Frt / Rear / O/S / NI / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>REPAIR LIMIT - 51K</u>
	We will be advising our principal a cost of repair P/P \$2,211.69 /- with 05 days of repair, subject to their approval. (red, 1619.12, 42%)

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 5

1) 30/11/22

☐ : Final ReportResurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee:

2)

Transportation:

Add Fee: ☐ : Site Insp (\$ _____)

S + RS. SI

☐ : Interview (\$ _____)

Photos

☐ : Tech. Invs (\$ _____)

Others

Repair Format: 2211.69

Lum Sum / P/P (\$ _____)