

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI22004367/Uqy3m4	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924		Date	30/05/2022	
			Code	: AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMH 7453J	Veh. Inspected	FBR 2971R	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10014780/CD	Excess (\$)	0.00	
	Assign From	SHAFAWATI MD RABU	Assign Date	10/05/2022	
2.	2. Vehicle Particulars & Condition				
	Make & Model	YAMAHA XMAX 300	c.c	292	
	Engine No.	HIDDEN	Year of Reg.	2020	
	Chassis No.	MH3SH0842KK009252	Colour	BLACK	
	Odometer	-	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	120/70-15	MAXXIS	6 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	140/70-14	MAXXIS	6 mm	
	L/H Rear Tyre			mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION AND O/S BODY.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	16/04/2022	Inspection Date	10/05/2022	
	Survey held at	ey held at EROFIA MOTOR WORKSHOP			
		1 KAKI BUKIT AVENUE 6 #02-62			
		SINGAPORE 417883			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: