ASS. REC. BI.	SIGNMENT
ASC	SmE 3741)
From: Date:	Veh No: SML 17188 Yr Regn: 2758 P 2017
Estimated Cost:	Type: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Mazda Cx-5 c.c 1998
at Workshop m/s Bifrost Auto	Colour Black A/C: Insured / Std / MT/ NA
of	Sp.Reading 76447 T/Radio: Insured Std / NI / NA
Insured:	Eng/No:
Policy No.	C/NO: JM6KF2W7AK6232718
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Ironger / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Irorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 225/65 R17
(Policy Condition)	R: 225/65 RM
Remark: The veh had commenced its N/S O/S	
repair at the time of inspection.	TOYO/YOKO or Falken
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 5 mm R/Bal. 5 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 5 mm L/Bal. 5 mm
Est. Repairs: 8 days Res.: Yes or No	D.O.A. 08/05/22 D.O.I. 11/05/22
Lum Sum: % 3 Val.: Yes or No	Survey held at Bi Frost Auto Pte Ltd
CA / REV / REP. / 24 HRS	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OL	JT Front 0/5
Date:Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	yearly!\$
	J
We accept the finalized amount of	of LS \$7600/8 DAYS MV ! \$
(red, \$13404.4, 64%)	
	NV ! \$
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 8
1) 27/02/23 : Final Report	Resurvey No. of Trip: 2 Survey Fee:
Date/Time, File Return to?	Transportation:
2) Add F	Lancación de la constantina della constantina de
	: Interview (\$) Photos
Report Format :	: Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$ 7600)	:Weekend (\$)
	TOTAL

CS/INC22004382/Bqy3

REF: