

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	NTUC INCOME IN:	SURANCE CO-OPERATIVE LTD		Ref:	CS/INC22004385/Rny3m4	
	73 BRAS BASAH F #05-01 NTUC TRA 189556	ROAD DE UNION HOUSESINGAPORE		Date:	12/08/2022	
	ATTN: CYNTHIA A	NG		Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SKJ 8698B	Veh. Inspected	ł	SKZ 9542B	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1171734-001	Excess (\$)		0.00	
	Assign From	JESS TOH	Assign Date		10/05/2022	
2. Vehicle Particulars & Condition						
	Make & Model	MITSUBISHI ATTRAGE 1.2	c.c		1193	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	MMBSTA13AFH018916	Colour		GREY	
	Odometer	110589 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/55 R15	RASSURER		6 mm	
	L/H Front Tyre	195/55 R15	RASSURER		6 mm	
	R/H Rear Tyre	195/55 R15	RASSURER		6 mm	
	L/H Rear Tyre	195/55 R15	RASSURER		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
					1.5	
5.		General Information				
	Accident Date	30/04/2022	Inspect Date /	Time	11/05/2022 ( 02:54 PM )	
	Survey held at	FC AUTO GARAGE PTE LTD	<u> </u>			
	8 KAKI BUKIT AVENUE 4, #04-03, PREMIER @ KAKI BUKIT, SINGAPORE 415875					
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.		Estimate Days of Repair				
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:		8 Worki	ing Days	
	•					