



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC22004386/Rqy3e2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 19/10/2022

ATTN: CYNDIE YONG

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|----------------|----------------|------------|
| Insured Veh. | SMA 9164S | Veh. Inspected | SNB 6575S |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | MT/1170750-002 | Excess (\$) | 0.00 |
| Assign From | JESS TOH | Assign Date | 10/05/2022 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|-------------------------------|--------------|------------|
| Make & Model | MERCEDES BENZ GLB200 AMG L | c.c | 1332 |
| Engine No. | HIDDEN | Year of Reg. | 2021 |
| Chassis No. | W1N2476872W083555 | Colour | WHITE |
| Odometer | 10049 KM | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | SPORTS RIM |
| General | FAIR | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------------|---------|---------|
| R/H Front Tyre | 235/50 R19 | PIRELLI | 6 mm |
| L/H Front Tyre | 235/50 R19 | PIRELLI | 6 mm |
| R/H Rear Tyre | 235/50 R19 | PIRELLI | 6 mm |
| L/H Rear Tyre | 235/50 R19 | PIRELLI | 6 mm |

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

| | | | |
|----------------|---|---------------------|-------------------------|
| Accident Date | 03/05/2022 | Inspect Date / Time | 11/05/2022 (03:06 PM) |
| Survey held at | FC AUTO GARAGE PTE LTD 8 KAKI BUKIT AVENUE 4, #04-03, PREMIER @ KAKI BUKIT, SINGAPORE 415875 | | |

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

| | |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 7 Working Days |
|-------------------------------------|----------------|