Landa Server 1 1 1 1 1 1 12

SA1E22590005 / Abwin Service Pte Ltd ENTRY DATE & TIME: 09/05/2022 16:10 (SGT) SUBMITTED BY: Gerine Cheng VERSION: 1 (09/05/2022 16:10 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Authorised Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies

Any false reporting may be referred to the Police for investigation. 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT 09/05/2022 16:10 (SGT) Date of Submission 09/05/2022 10:20 (SGT) Date of Accident Punggol West Flyover, Singapore **Exact Location of Accident** PUNGGOL WEST FLYOVER TOWARDS SENGKANG EAST Additional Location Information ROAD Singapore Country/State of Loss

DETA		0-	CHAIN	VEL I	
	II S		OWN	VEH	
UEIA	ILO	\mathbf{o}		V - III	

Vehicle Registration Number

SLK2271X

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner NRIC No **Email Address** Mobile Phone No Alternative Phone No

LEE DUAN NENG (LI DUANNENG) SXXXX271G DUANNENG2271@GMAIL.COM (Phone) +65-93379505 (Home) +65-93379505

VEHICLE PARTICULARS

Manufacturer Model

Variant

Exact purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

Vehicle Category Transmission

CC

Honda Hr-v

Private use

No - Claiming third party Private car

Auto 1496

INSURANCE COMPANY

Name of Insurance Company Type of Coverage Fleet Policy

Policy Number

Cover Note Number

Comprehensive

Liberty Insurance Pte Ltd

SD20V16607/VPC2/R02

DRIVER

Name of Driver

LEE DUAN NENG (LI DUANNENG)

SXXXX271G NRIC No 12/12/1983 Date Of Birth Indoor Occupation 01/09/2008 Date Of Driving Pass 13 YEARS AND 8 MONTHS Driving experience Female Gender (Phone) +65-93379505 Mobile Number (Home) +65-93379505 Alt. Phone Number DUANNENG2271@GMAIL.COM **Email Address** 164 LENTOR LOOP Address 07-02 Address complement 789096 Postcode Yes Is the driver the policyholder? If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Collision - Head to Rear Type of Accident Clear Weather Conditions Dry Road Surface OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? Yes Was any injured conveyed to hospital by ambulance? No Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) No soliciting/offering accident claims assistance? DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT PLEASE REFER TO SKETCH PLAN ATTACHED ATTACHMENT(S) Yes Are accident photos available for attachment? Was there any video captured by Car Camera? No No Was there any audio recorded? DETAILS OF OTHER VEHICLE PROPERTY 1 SKR4606B Vehicle Registration Number Vehicle Manufacturer Vehicle Model Vehicle Variant

Private car

Vehicle Colour

Vehicle Category Name of Driver Contact Number Address

Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	LEE DUAN NENG (LI DUANNENG)
Gender	Female
Phone No	(Phone) +65-93379505
Address	164 LENTOR LOOP
Address Complement	07-02
Post Code	789096
Approximate Age Years Old	38
Injuries Sustained	-
Injured person in which vehicle?	SLK2271X
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

- 1. Pea sereport correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available af oresaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lundersland, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

WeliA: SLK2271X JELIB. SKR4606B



Describe Circumstances of the Accident
The state of the s
XII
V
X()
01

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &

Oriver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel ON THE STATED DATE AND TIME. I, VEHICLE A (SLK2271X) WAS TRAVELLING STRAIGHT ON LANE 3 OF PUNGGOL WEST FLYOVER TOWARDS SENGKANG EAST ROAD. WHEN THE FRONT VEHICLE SLOWED DOWN AND STOP, I FOLLOWED SUIT WITHOUT HAVING ANY COLLISION WITH THE FRONT VEHICLE. SUDDENLY, I FELT A HUGE IMPACT FROM THE REAR PORTION OF MY STATIONARY VEHICLE. AFTER I ALIGHTED I THEN REALISE THAT IS VEHICLE B (SKR4606B) THAT HAD COLLIDED ONTO MY VEHICLE.

VEHICLE A: SLK2271X

VEHICLE B: SKR4606B

