

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CTPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	09/05/2022
Vehicle Reg. No.:	SHD3482G	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Vehicle Reg. Date:	19/03/2022
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEKU411464	Chassis No:	KMHC851CVLU190519
Odometer:	28405 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

COST OF CLAIMS

	Amount
Parts	
Miscellaneous Items	1,688.22
Labour	11.00
Paintwork Labour	1,020.00
Towing	0.00
	0.00
Gross Total (S\$)	2,719.22
+ GST 7.00% (S\$)	190.35
Nett Amount (S\$)	2,909.57

This claim is handled by: CHIANG LIAT CHOON

REPAIR DETAILS**Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 09 May 2022)**Parts:** 143 HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHD3482G/09/05/2022 14:53**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER CENTRE MOULDING	20.00	0.00	de *451.25 FL
2	1		*REAR BUMPER	20.00	0.00	R *459.40 FL
3	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	? *394.80 FL
4	10		*REAR BUMPER CLIP	20.00	0.00	ady *22.00 FL
5	2		*REAR BUMPER BRACKET - LH / RH	20.00	0.00	X *111.60 FL
6	1		*REVERSE SENSOR	20.00	0.00	? *180.00 FL
7	1		*REAR NUMBER PLATE W/HOLDER	0	0.00	an *55.00 FS
8	1		*REAR FOG LAMP	0	0.00	X *201.50 FS
9	2		*REAR NUMBER LAMP LH/RH	20.00	0.00	X *170.60 FL

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)**2,046.15****- List Item Discount on L Items (S\$)****357.93****Total Parts (S\$)****1,688.22**

ComfortDelGro Engineering Pte Ltd/SHD3482G/09/05/2022 14:53. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (\$\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	350 600.00
2	SPRAY PAINTING	New	250 300.00
3	CHECK LIGHTING AND WIRING	New	30 60.00
4	REMOVE/REFIX REVERSE SENSOR	New	30 60.00
Gross Labour Cost (\$\$)			1,020.00

ComfortDelGro Engineering Pte Ltd/SHD3482G/09/05/2022 14:53. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tarfein 97495749
WP 4/5/22 03:15pm
2 days
Pls using new parts
tarfein@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company


Acknowledged by Repairer
Signature:
Date:

Team: ARC Repair TP(CLS0)1		JOB CARD	Sales Order: 4204584	JC NO:305515218
STOMER		REGN NO.: SHD3482G	MILEAGE	
V/MS COMFORT TRANSPORTATION PTE LTD		MAKE : HYUNDAI	FUEL	
STOMER NO. 7010045		MODEL IONIQ(G3)	DATE/TIME IN 09.05.2022 10:30	
DRESS 383 SIN MING DRIVE		YR OF MANU. 18.03.2020	TARGET DATE	
Singapore SINGAPORE 575717		CHASSIS CODE KMHC851CVLU190519	COMPLETION DATE/TIME:	
(R) 65508755 (O)				
(P)				
COUNT CARD NO.				

JOB DESCRIPTION

Accident Date: 09.05.2022
NATURE: 3P 09.05.2022

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Knowledge Slip

Exit Pass

No.: SHD3482G CHIANG

Vehicle No.: SHD3482G

of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard