

Your Ref: RN.1771.21.AXA

Date: 17th Jun 2022

Our Ref: CS1/LAW22004412/Gqy3e2

M/s Tan Kok Quan Partnership

1 Wallich Street #07-02

Guoco Tower

Singapore 078881

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMD 97X**INSURED VEHICLE: GBE 1079S****ACCIDENT DATE: 07/09/2020**

We thank you for your instruction on 11/05/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SMD 97X from M/s Cozon Engineers.
- b) Survey report by Infiniti Appraisal Service with colour photographs.
- c) Final Repair Bill of SMD 97X from M/s Garage 13 Pte Ltd.
- d) Singapore Accident Statement of Vehicles SMD 97X and GBE 1079S.
- e) Colour damaged vehicle photographs of SMD 97X.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SMD 97X
Make & Model	: BMW 535I
Chassis Number	: WBAFR72070C264673
Year of Registration	: 2010
Engine Capacity	: 2979 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.