



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22004426/Aqy3e2	
			Date: 16/09/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBK 8504D	Veh. Inspected	SLN 895T	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2201611/RUC	Excess (\$)	0.00	
Assign From	MELVIN YE	Assign Date	11/05/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA MOBILIO	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	MRHDD4870GP000509	Colour	SILVER	
Odometer	42402 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	YOKOHAMA	6 mm	
L/H Front Tyre	185/65 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	185/65 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	185/65 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/05/2022	Inspection Date	10/05/2022	
Survey held at	BLK C KAKI BUKIT AVE 6 #01-59			
Repairer	D&K AUTOMOTIVE SERVICES PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			9 Working Days	