Company & GST Registration No. 200616038C

2 Kaki Bukit Avenue 2 #01-17/#01-18 /Heavy Vehicle #01-08/Spray Painting #02-27

Kaki Bukit Autohub Singapore 417921

Tel: 68420051

Fax: 67410510

Email: sales@n51.com.sg

Our Ref:

SMN 1181 B

Your ref:

SKU 6863 X

10 May 2022

AUTO & GENERAL INSURANCE (S) PTE LTD

SINGAPORE SHOPPING CENTRE 190 CLEMENCEAU AVENUE #03-01 SINGAPORE 239924 Attn: Motor Claims Department

Dear Sir/Madam,

NAME OF CLAIMANT: MIRS INNOVATE PTE LTD

VEHICLE NUMBER: SMN 1181 B

YOUR INSURED VEHICLE NUMBER: SKU 6863 X

ACCIDENT ON 07 May 2022 ALONG PIE TWDS TUAS B4 KALLANG EXIT

AT ABOUT 09:00 HOURS

We refer to your email/fax dated **10 May 2022** informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment **LKK** as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit Autohub
2 Kaki Bukit Avenue 2
#01-18
Singapore 417921

Contact Person:

6842 0051 / 6744 0510 (Melody)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



FOR SURVEYOR:

Please initial here after completion of pre-repair inspection. Thank you!
Appointed surveyor:

(Name & Signature):

Date & Time of Inspection: