

**COMFORTDELGRO
ENGINEERING**ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969Our Job Ref No : 305514521Date : 18.05.2022**FINALIZATION FORM**To : LKK

Fax :

Attn : GILO GIANGVehicle Reg No. : SHA4429X28.04.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- Z The repair job shall bill to: CHINA SBD2985A
2. The finalized amount shall be:
- (a) Spare Parts after List discount _____
- (b) Labour Charges _____
- Total for Part-By-Part Repair Cost** _____
- (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: _____
Final Lumpsum Repair cost \$950.00

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and
finalized amountSignature : Name : CHIANGTel : 62148314Fax : 65468156

Signature : _____

Name : _____

Date : _____

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

