

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/EQ122004436/4ty3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Call out - 28-02-2031

No mv for Garbage / Sanitary wegen

8/6/22 4/5 @ 2800 informed Schui

RED: 4627.14;62%

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Preli. Report☐ : Final Report

Days Of Repair: 2

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

) S + RS. SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I: (\$)

TOTAL

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	873W
Vehicle Details	
Vehicle No.:	XD4441D
Vehicle to be Exported:	No
Intended Deregistration Date:	12 May 2022
Vehicle Make:	MAN
Vehicle Model:	TGS 26.320 6X4 BB
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	50527551072756
Chassis No.:	WMA26SZZXBM563799
Maximum Power Output:	-
Open Market Value:	\$124,837.00
Original Registration Date:	07 Mar 2011
First Registration Date:	07 Mar 2011
Transfer Count:	0
Actual ARF Paid:	\$6,242.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Feb 2031
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$34,471.00
COE Rebate Amount:	\$30,326.00
Total Rebate Amount:	\$30,326.00

The information contained herein is correct as at 12 May 2022

OK

MAH LIAN MOTOR VEHICLE REPAIRER

No.38 Defu Lane 9 Singapore 539278
 TEL: 62823336 FAX: 62893336 Email: mahlian@singnet.com.sg
 GST:M90362564P RCB NO:201327339E

M/S : EQ Insurance Company Ltd
 5 Maxwell Road #17-00 ,
 Towing Block MND Complex ,
 Singapore 069110
 TEL: 6223 9433 FAX: 6224 3903
 ATTN: Motor Claim Department
 Your Ref No: TEE ENVIRONMENTAL PL
 Claim Type: Third Party
 Accident Date: 05/05/2022
 TP Veh Reg No: YL4104Z

Estimate No: ES1700981
 Date: 05 May 2022
 Policy No: 21-MJ001333-R03
 Veh Reg No: XD4441D
 Make/Model: MAN TGS 26.320 6X4 BB
 Chassis No: WMA26SZZXBM563799
 Engine No: 50527551072756
 Reg. Date: 07/03/2011

Estimate Repair Cost to Vehicle No :XD4441D

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 Corner Panel RH	219.62	1 PC	219.62	
2 Door Assy RH	2,438.12	1 PC	2,438.12	
3 Door Hinge Upper RH	134.50	1 PC	134.50	
4 Door Hinge Lower RH	134.50	1 PC	134.50	
5 Side Mirror Assy RH	1,220.26	1 PC	1,220.26	
6 Side Mirror Bracket Lower RH	20.14	1 PC	20.14	
			4,167.14	4,167.14
Labour				
7 Labour to renew corner panel ,door assy RH ,side mirror .	980.00	1 JOB	980.00	
8 To spray & painting on affected area .	1,800.00	1 JOB	1,800.00	
9 To rust proofing .	480.00	1 JOB	480.00	
			3,260.00	3,260.00
			Total	S\$ 7,427.14
			Add GST @ 7%	519.90
			Total Amount Payable	S\$ 7,947.04

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND NINE HUNDRED FORTY SEVEN AND CENTS FOUR ONLY

For MAH LIAN MOTOR VEHICLE
REPAIRER

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not Allowed
 12/5/22
 1/5 \$ 2800
 2 days

2-2926-74

102
 2634.06

900

3534.06

202

2827