

ASS. REC. BY: Pam

REF:

ASSIGNMENT

633D

LOG # 124: 2023/MAY

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMW 4581M

at Workshop m/s GARAGE 13

of _____

Insured: LPC

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 19K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMW 4581M Yr Regn: 2013 / MAY

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Volkswagen Golf A71.4 c.c. 1395

Colour: GREY A/C: Insured / Std / NI / NA

Sp. Reading: 78878 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVWZZZ4H2DW099234

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NI / S/Rim / STD A/Rim or

Tyre Size: F: 225/40R18

R: _____

BS / DUN / EXNOVA / SV / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 26/04/22 D.O.I. 27/04/22

Survey held at GARAGE 13

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 9K

ESTIMATE RANGE OF REPAIR / NO. OF DAYS - (2K-3K) / 3 days

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

Photos _____

Others _____

Report Format: _____

Lump Sum / L.B.K. (\$) _____

Volkswagen Golf 1.4A TSI

Overview

[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

Price

\$20,800

Depreciation ⓘ

\$15,950 /yr

[View models with similar depre](#)

Reg Date

13-Jun-2013

(1yr 1mth 8days COE left)

Mileage

165,000 km (18.5k /yr)

Manufactured ⓘ

2013

Road Tax ⓘ

\$624 /yr

Transmission

Auto

Dereg Value ⓘ

\$10,911 as of today (change)

OMV ⓘ

\$20,925

COE ⓘ

\$67,301

ARF ⓘ

\$6,295

Engine Cap

1,395 cc

Power

90.0 kW (120 bhp)

Curb Weight ⓘ

1,249 kg

No. of Owners ⓘ

2

Type of Vehicle

[Hatchback](#)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	033D
Vehicle No.:	SMW4581M
Vehicle to be Exported:	No
Intended Deregistration Date:	04 May 2022
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	GOLF A7 1.4 TSI AT BMT 5G13GZ
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	CMB125122
Chassis No.:	WVWZZZAUZDW099234
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$20,925.00
Original Registration Date:	27 May 2013
First Registration Date:	27 May 2013
Transfer Count:	1
Actual ARF Paid:	\$6,295.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 May 2023
PARF Rebate Amount:	\$3,462.00
COE Expiry Date:	26 May 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$61,029.00
COE Rebate Amount:	\$6,463.00
Total Rebate Amount:	\$9,925.00

The information contained herein is correct as at 04 May 2022

OK