(08/11/13)	
ASS. REC. BY: REF: CS CTI	22004439 Day3
	SSIGNMENT
From: Date:	Woh May & MLU 22252
Estimated Cost:	Veh No: SMH 2325, D Yr Regn: Jan 12019  Type M Carl M Cycle / Rug / Ven / Law (7)
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Type M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or
To Inspect Vehicle No:	11
at Workshop m/s	41
of	
Insured:	Sp.Reading 7/157 T/Radio: Insured / Std / NI / NA
Policy No.	Eng/No: <u>LEB1441064</u>
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil /S/Rim / STD A/Rim or
(Policy Condition)	Tyre Size: F: 205 45 7.17
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or avadyer
Bal. or Market Value:	<u>Front</u> Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. P/Bal
GIA / PR Seen: Consistent? : Yes or No	L/Bal. C mm L/Bal
Est. Repairs: 4 days Res.: Yes or No	D.O.A. 11 05 222 D.O.I. 11 05 222
Lum Sum: % 3 Val.: Yes or No	Survey held at JWG AMK
CA / REV / REP. / 24 HRS	Des. of Damages : Ert / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted: Vehicle: IN / OUT	Kay
Date / Time   Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
Chipa Taiping 1P 84342	
3 09 15 Jun 10 1,0001. 2:	to 4 days of land to (8487.04, 82
•	
Date/Time, File Pass to? : Preli. Report	16
July page - Freil, Report	Days Of Repair:
Date/Time, File Return to?	Resurvey No. of Trip: Survey Fee:
Add Fee:	Transportation:
	Intention (\$
Report Format: MER-1/	Tech. Invs (\$ ) Others
ump Sum / I. B.1: (\$ 4000)	: Weekend (\$

# JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592 E-Mail: jwg.claims@yahoo.com

To: CHINA TAIPING INSURANCE SINGAPORE PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING YP8434Z [YOUR INSURED] & SMH2325D [OUR CLIENT] ON 11/05/2022.

## **ESTIMATED REPAIR COSTS FOR SMH2325D**

<u>QTY</u>	<u>PARTS</u>	<b>AMOUNT</b>	
1PC	TAILGATE Devote 962.80	\$ 1,102.00	1
1PC	TAILGATE WINDSCREEN MOULDING Have 138-00	\$ 201.50	1
1PC	TAILGATE CENTER GARNISH	\$ 301.20	X
1PC	TAILGATE HONDA LOGO	\$ 55.00	X
1PC	TAILGATE 'HYBRID' EMBLEM NCC	\$ 92.00	1
2PCS	TAILGATE DAMPER LH / RH @ \$322.90 EACH	\$ 645.80	X
1PC	TAILGATE INNER TRIM BOARD money water 341.80	\$ 429.30	1
1PC	TAILGATE WEATHER STRIP ( LT   NC 148.20	\$ 331.20	
1SET	TAILGATE STOPPERS HH	\$ 20.00	X
1PC	TAILGATE LOCK & Den 180.66	\$ 342.40	*
1PC	TAILGATE SWITCH HH	\$ 442.30	X
1PC	TAILGATE STRIKER LOCK	\$ 109.30	X
1PC	TAILGATE INNER HANDLE	\$ 99.80	7
2PCS	TAILGATE NO. PLATE LAMP LH / RH @ \$95.00 EACH	\$ 190.00	X
2PCS	TAILGATE LAMP LH / RH @ \$295.80 EACH Swall manyly crede	\$ 591.60	7
2PCS	TAIL LAMP LH / RH @ \$492.40 EACH Screeteld mounty evant	\$ 984.80	L
2PCS	TAIL LAMP PANEL LH / RH @ \$401.80 EACH	\$ 803.60	X
2PCS	TAIL LAMP LOWER BRACKET LH / RH @ \$101.80 EACH	\$ 203.60	X
1PC	REAR BUMPER duting 592:77	\$ 659.40	1
2PCS	REAR BUMPER SIDE RETAINER LH / RH @ \$66.90 EACH	\$ 133.80	7
1PC	REAR BUMPER CENTER GARNISH many water 146.90	\$ 3,98.70	L
2PCS	REAR BUMPER REFLECTOR LH / RH @ \$109.80 EACH	\$ 219.60	7
2PCS	REAR BUMPER REFLECTOR GARNISH LH / RH @ \$209.80 EACH 03 H	\$ 419.60	L
1PC	REAR BUMPER LOWER LID HE	\$ 498.50	X
1PC	REAR END PANEL Dewn 468.50 with	\$ 784.50	~
1PC	REAR END PANEL TOP GARNISH	\$ 295.30	X
1PC	SPARE WHEEL PANEL Had	\$ 994.80	*
2PCS	SPARE WHEEL QUARTER PANEL LH / RH @ \$492.70 EACH WW	\$ 985.40	X
1PC	SPARE WHEEL PANEL TOP BOARD	\$ 599.00	*
1PC	SPARE WHEEL PANEL TOOL BOX	\$ 398.00	X
PL	REAR BUMPER SPONGE LH borker 88.10	\$ 158.00	-
172	REAR KETLESS SENSOR noneybaker 95.60	9 350 W	1

HH \$		400.00
Ψ	1	198.00
RH @ \$168.80 Hu \$	,	337.60
	RH @ \$168.80 Hu \$	RH @ \$168.80 Hu \$

4061.52

PARTS SUM: \$ 17,512.60 PARTS LESS 20%: \$ 3,502.52 PARTS TOTAL: \$ 14,010.08

# **LABOUR & SPECIAL NETT ITEMS**

*	TO SUPPLY REAR WINDSCREEN SEALANT How	\$ 50.00 401-
*	TO SUPPLY REAR WINDSCREEN DAMPING SEAL HH	\$ 50.00 ×
*	TO SUPPLY TAILGATE INNER TRIM BOARD CLIPS Luc	\$ 5.0.00 15  -
*	TO SUPPLY TAILGATE CENTER GARNISH CLIPS	\$ 50.00 ×
*	TO SUPPLY REAR BUMPER CLIPS HUC	\$ ا مد 50.00 عن إ-
*	TO SUPPLY REAR END PANEL SEALANT MC	\$ 80.00 40 -
*	TO SUPPLY REAR END PANEL TOP GARNISH CLIPS	\$ 50.00 >
*	TO SUPPLY SPARE WHEEL PANEL SEALANT HAD	\$ 80.00 >
*	TO SUPPLY SPARE WHEEL PANEL SEALANT HAD  TO SUPPLY REAR FENDER SEALANT HAD  396.00	\$ 80.00 ×
*	TO SUPPLY REAR FENDER INNER TRIM CLIPS HH	\$ 50.00 >
*	TO SUPPLY REAR FENDER QUARTER GLASS SEALANT	\$ 80.00 🗡
*	TO SUPPLY REAR FENDER QUARTER GLASS DAMPING SEAL	\$ 30.00 ⊀
*	TO SUPPLY REAR NO. PLATE & CASING HH	\$ 100.00 /
*	TO SUPPLY REVERSE SENSOR Dem	\$ 300.00 220  -
*	TO SUPPLY REVERSE CAMERA	\$ 600.00 ×
*	TO SUPPLY FEET EMBLEM Hee	\$ 100.00 301
*	TO SUPPLY PAW EMBLEM He	\$ 200.00 30  -
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILIATE	\$ 400.00 # 801-
	REPAIRS	
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 2,000.00 500
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$ 2,000.00 600  -
*	TO TUFF COAT DAMAGED AREAS	\$ 300.00 40
*	TO RNR TAILGATE MECHANISM TO FACILITATE REPAIRS	\$ 200.00 60/
*	TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS	\$ 150.00 40  -
*	TO RNR TAILGATE WINDSCREEN TO FACILITATE REPAIRS	\$ 3,00.00 120 -
*	TO RNR REAR FENDER QUARTER GLASS TO FACILITATE REPAIRS	\$ 200.00 ⊣⊣
*	TO RNR REVERSE CAMERA TO FACILITATE REPAIRS	\$ 100.00 HH
*	TO RNR FUEL TANK FILLER PIPE TO FACILITATE REPAIRS	\$ 100.00 HA

TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS

1470·N/ \$ 200.00 30/-

TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS

300.00 HH

LABOUR & S/N TOTAL: \$ 8,250.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 22,260.08

11/05/2022 e 1700ms

5114.21 4,000/-

LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Acknowledged by Repairer** 

A Signature:

SC09225B0002 / Cheng Hoe Motor Pte Ltd[568047] ENTRY DATE & TIME: 11/05/2022 21:19 (SGT) SUBMITTED BY: LI YAZHU DORLYN VERSION: 1 (11/05/2022 21:19 (SGT))



# SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

Please report <u>correctly</u> the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Authorised Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### **ACCIDENT STATEMENT**

Date of Submission
Date of Accident
Exact Location of Accident
Additional Location Information

Country/State of Loss

11/05/2022 21:19 (SGT) 11/05/2022 07:40 (SGT)

Singapore

WOODLANDS AVE 12 TOWARDS SLE BEFORE WOODLANDS

AVE 5 Singapore

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number

SMH2325D

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

NRIC No

**Email Address** 

Mobile Phone No

Alternative Phone No

No

LOW CHUNG YEN MELVIC

S9217155H

lowchungyenmelvic.w@gmail.com

(Phone) +65-96931157

+65-96931157

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of

accident

Are you claiming under your own insurance policy for repair to

your vehicle?

Vehicle Category

Transmission

CC

Honda

Fit

Private use

No - Claiming third party

Private car

Auto

1496

INSURANCE COMPANY

Name of Insurance Company

Type of Coverage

Fleet Policy

Policy Number

Cover Note Number

NTUC Income Insurance Co-operative Ltd Comprehensive

No

5125227862 DC

16/01/2022 - 15/01/2023

DRIVER

Name of Driver

LOW CHUNG YEN MELVIC

NRIC No Date Of Birth Occupation

Date Of Driving Pass

Driving experience

Gender Mobile Number Alt. Phone Number

**Email Address** Address

Address complement

Postcode

Is the driver the policyholder?

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions Road Surface

Number of vehicles involved in the accident

Was anybody injured in the Accident?

Was any other vehicle or property damaged?

soliciting/offering accident claims assistance?

**DETAILS OF POLICE ACTION** 

Was the accident reported to the police? Was notice of intended Prosecution given?

If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

REFER TO STATEMENT

ATTACHMENT(S)

Are accident photos available for attachment?

Yes

No

No

YP8434Z

DETAILS OF OTHER VEHICLE PROPERTY 1

Commercial vehicle

OTHER INFORMATION

Was any foreign vehicle involved in the accident?

Was any injured conveyed to hospital by ambulance?

Number of Passengers (Including Driver)

Has the driver been approached by unknown person(s)

Collision - Head to Rear

Raining Wet

S9217155H

16/05/1992

30/09/2015

+65-96931157

6 YEARS AND 8 MONTHS

lowchungyenmelvic.w@gmail.com

BLK 407 SEMBAWANG DRIVE #10-812

(Phone) +65-96931157

Indoor

Male

750407

Yes

No

No

No

Yes

1

No

No

No

Was there any video captured by Car Camera?

Was there any audio recorded?

Vehicle Registration Number Vehicle Manufacturer

Vehicle Model Vehicle Variant


Vehicle Colour Vehicle Category Name of Driver

Contact Number Address

Address complement	
Postcode	
nsurance Company Name	
Nature Of Damage	
Details of property damaged in accident	
No. Of Passenger (Including Driver)	(

#### SKETCH PLAN

#### **IMPORTANT NOTICE**



- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful</u> and <u>accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

lunderstand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Mhi	Mi	11/2/2013
Policyholder's Signature / Date & Time	Driver's Signature (If driver is n & Time	
Sketch Plan		Personnel DOMM (AMK) 1110
Woodland Ave 12 towards	SLE before Woodland Av	ve 5 Vehicle A- IMH 23251
	<del>-</del>	Vehicle 8 - YP 84342

	01	n th	e state	ed date	and	time	,	1, vel	nicle	Α	(m)	12325	(0)	was	tra	relling	stra	ight
along	at	the	stated	locatio	n on	lane	a	. A <u>c</u>	vehic	e	in fro	nt of	me.	vol2	wed	down	and	cam
to a	stop	114	followed	suit. (	lut of	udde	n,	1 felt	an	ir	npact	from	n my	rea	r po	rdron	, vehic	6 8
(YP843	4Z)	collid	ed on	to the	rear	porte	bn	d my	vehi	cle	i (	au Sin	g dan	nages				
		l wi	11 repai	ining m	ny vel	nide o	a+	JWG	Inter	na	tronal	Pte	Цd.					
										_								
							-											
										_	hand of the same							
										-								
	_																	-
							-											
							_											
							-								_			
							_				-							
												-						
			-										-					
															_			

#### Declaration

We declare the foregoing particulars are true in every respect,

Policyholder's Signature / Date &

11/5/2022 Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (AMK)