



Your Ref: 2022 - 49

Date: 25<sup>th</sup> May 2022

Our Ref: CS1/SCD22004447/Eqy3e2

**M/s Singapore Civil Defence Force (MHA05)**

91 Ubi Ave 4

Singapore 408827

Attn: Ralf Tay Gim Chye

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SNE 5045X**

**INSURED VEHICLE: QX 2143E**

**ACCIDENT DATE: 10/05/2022**

We thank you for your instruction on 11/05/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SNE 5045X from M/s Cycle & Carriage Industries Pte Ltd.
- b) Police Report of Vehicles SNE 5045X.
- c) Colour damaged vehicle photographs of SNE 5045X.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SNE 5045X
Make & Model	: Mercedes Benz A 180 Saloon
Chassis Number	: W1K1771842J3287396
Year of Registration	: -
Engine Capacity	: -

- 2. We recommend that the repairs of the entire damage require about 3 (Three) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.