

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |   |  |                 |       |                   |  |
|---|---|--|-----------------|-------|-------------------|--|
|   | AXA INSURANCE   | PTE LTD  | R               | Ref:  | CS/ASM22004463/y3 |  |
|   | 8 SHENTON WAY<br>AXA TOWERSING  |  | D               | Date: | 12/05/2022        |  |
|   |   |  | C               | ode:  | ASM               |  |
| 1. Policy Particulars :- THIRD PARTY CLAIM                        |   |  |                 |       |                   |  |
|   | Insured Veh.  | SHD 4203P  | Veh. Inspected  |       | SMS 755B          |  |
|   | Policy No.  |  | Coverage (\$)   |       | 0.00              |  |
|   | Claim No.   | S2M03VAC   | Excess (\$)     |       | 0.00              |  |
|   | Assign From   | KHONG Lynn   | Assign Date     |       | 12/05/2022        |  |
| 2. Vehicle Particulars & Condition                                |   |  |                 |       |                   |  |
|   | Make & Model  |  | c.c             |       | 0                 |  |
|   | Engine No.  | HIDDEN   | Year of Reg.    |       |                   |  |
|   | Chassis No.   |  | Colour          |       |                   |  |
|   | Odometer  | -  | Steering        |       |                   |  |
|   | Brakes  | Modification   |                 |       |                   |  |
|   | General   |  |                 |       |                   |  |
| 3. Conditions of Tyres  |   |  |                 |       |                   |  |
|   |   | Size   | Make            |       | Balance           |  |
|   | R/H Front Tyre  |  |                 |       | mm                |  |
|   | L/H Front Tyre  |  |                 |       | mm                |  |
|   | R/H Rear Tyre   |  |                 |       | mm                |  |
|   | L/H Rear Tyre   |  |                 |       | mm                |  |
| 4.  | Description of Damages  |  |                 |       |                   |  |
|   |   |  |                 |       |                   |  |
| 5.  | General Information   |  |                 |       |                   |  |
|   | Accident Date   | 04/03/2022   | Inspection Date |       |                   |  |
|   | Survey held at  | EADY AUTO CARE PL  |                 |       |                   |  |
|   |   | BLK 10 #03-06, AMK AUTOPOINT, ANG MO KIO AVE 5, INDUSTRIAL PARK 2A, SINGAPORE 568047 |                 |       |                   |  |
| 5a. Rema  |   |  | emarks          |       |                   |  |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                 |       |                   |  |