



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: LYNN KHONG			Ref: CS/ASM22004463/Kqy3s2 Date: 25/05/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 4203P	Veh. Inspected	SMS 755B	
Policy No.		Coverage (\$)	0.00	
Claim No.	S2M03VAC	Excess (\$)	0.00	
Assign From	KHONG Lynn	Assign Date	12/05/2022	
2. Vehicle Particulars & Condition				
Make & Model	VOLVO XC60 (A)	c.c	1969	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	YV1DZ40LDH2155896	Colour	WHITE	
Odometer	80860 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	255/45 R20	MICHELIN	8 mm	
L/H Front Tyre	255/45 R20	MICHELIN	8 mm	
R/H Rear Tyre	255/45 R20	MICHELIN	8 mm	
L/H Rear Tyre	255/45 R20	MICHELIN	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/03/2022	Inspection Date	13/05/2022	
Survey held at	READY AUTO CARE PL BLK 10 #03-06, AMK AUTOPOINT, ANG MO KIO AVE 5, INDUSTRIAL PARK 2A, SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	