

REF:

From: _____ Date: _____

Veh No: SL23108A Yr Regn: 2018 / April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Civic C.C. 1597

Colour: Black/c A/C: Insured / Std / NI / NA

Sp. Reading 85102 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MRHFC5650JTO00387

Gen. Cond. Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16.

N/S	O/S

R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO of

Front

Rear

R/Bal.	06	mm	R/Bal.	06	mm
--------	----	----	--------	----	----

L/Bal.	06	mm	L/Bal.	06	mm
--------	----	----	--------	----	----

D.O.A. _____ D.O.I. 12/05/22

*Survey held at JL

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP Chiam
	MV :
	PV :
	Nett:
	128D.

☐: Prel. Report

Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Report Format :

Add Fee: : Site Insp (\$

1: Interview (\$)

1: Tech. Invs (3)

$$S + RS \rightarrow S$$

Photos

Others