ASS. REC. BY:	REF: (17/	220044961kgy3 C
Kenneth		SSIGNMENT
Estimated Cost: OD ITP I WS / TP RES / OD RES / EVA To Inspect Vehicle No:	ate:	Veh No: SNC 84036 Yr Regn: (1 2/ Type: M.Car/ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or
GIA / PR Seen: Consistent	PSS: N/S O/S N/S O/S 17: Yes or No 17: Yes or No 17: Yes or No	Colour White A/C: Insured/Std/NI/NA Sp.Reading G26P T/Radio: Insured/Std/NI/NA Eng/No: C/No: C/R W3 F7 FA *8 m C 3852/ Gen. Cond: 6000 Fair / Poor / Burnt Steering: Inorder / Jammed / Leaked / Burnt or Brake: Inorder / Jammed / Leaked / Burnt or Modl: Nil / S/Rlm / STD A/Rim or Tyre Size: F: C/S C/No: C/No
CA / REV / REP. / 24 HRS Date: Person Contacted: Date / Time Action / Instruction	Vehicle: IN/OUT	D.O.A. 12/5/22 Survey held at Des. of Damages: Frt Rear O/S N/S U/C Rooftop or The U/C Chassis frame Body Structure affected due to collision.
Date/Time, File Pass to? Prell. Report Final Report Cute/Time, File Return to? Report Format: MARTP Lump Stim I.B.I. (\$ 7682.20	04,	ys Of Repair: survey No. of Trip: Survey Fee: Transportative: Site Insp (\$) S - RS SI Interview (\$) FINAS Tech Invs (\$) Others Weekend (\$)

OPT/MA ///ERKZ SINGAPORE

OPTIMA WERKZ PTE LTD

Co. Reg. No. 201212455W

www.ow.sg

(7) /OptimaWerkz

OptimaWerkz

Date:

12/05/2022

Reluny B4 pains

Third Party Insurer: Third Party Veh No:

CHINA TAIPING

Vehicle No: SNC8405G

Date of Accident:

GBB7280C

Model:

TESLA MODEL 3 STANDARD RANGE

12/05/2022

Chassis:

LRW3F7FA8MC385216

Estimator:

KIT

Reg. Year:

2021

Sday, 87/82.20

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BOOTLID	1		R \$728.97
2	REAR BOOTLID "TESLA" EMBLEM	1		Ma \$37.38
3	REAR BOOTLID LAMP LH	1		Bro \$177.57
4	REAR BOOTLID LAMP RH	1	1	Gem \$177.57
5	REAR BOOTLID NUMBER PLATE LAMP LH	1		Ph \$14.95
6	REAR BOOTLID NUMBER PLATE LAMP RH	1		5m \$14.95
7	REAR BOOTLID OUTER HANDLE WITH REVERSE CAMERA	1		Nd \$121.50
8	REAR BOOTLID MECHANISM LOCK	1		n \$54.21
9	REAR BOOTLID LOCK STRIKER	1		n \$52.34
10	REAR BOOTLID INNER TRIM BOARD	1	/	MycM \$345.79
11	REAR BOOTLID HINGE LH	1	Dis	. \$61.68
12	REAR BOOTLID HINGE RH	1	Dis	\$61.68
13	REAR BOOTLID WEATHERSTRIP	1		り か \$121.50
14	REAR TAIL LAMP LH	1		CM \$280.37
15	REAR TAIL LAMP RH	1	my	
16	REAR TAIL LAMP BRACKET LH	1	,	ry \$2.80
17	REAR TAIL LAMP BRACKET RH	1		In \$2.80
18	REAR BUMPER	1		A \$663.55
19	REAR BUMPER SIDE BRACKET LH	1		Pm \$7.48
20	REAR BUMPER SIDE BRACKET RH	1		CM \$7.48
21	REAR BUMPER CENTER BRACKET	1		CM \$52.34
22	REAR BUMPER LOWER LIP	1		DU \$140.19
23	REAR BUMPER UNDER COVER	1	CI	\$205.61
24	REAR BUMPER REFLECTOR LH	1		Br \$20.56
25	REAR BUMPER REFLECTOR RH	1		fn \$20.56
26	REAR BUMPER PARKING SENSOR Short	A	/ \$158.88	\$635.62
27	REAR BUMPER PARKING SENSOR BRACKET	4	\$4.67	Ma \$18.68
28	REAR BUMPER REINFORCEMENT	1		By \$271.03
29	REAR END PANEL	1		B \$448.60
30	REAR END PANEL TOP GARNISH	1		NJ \$299.07
	- 111 ;			
	1		SUB TOTAL	\$5,327.20
	in Centre		LESS 10%	\$532.72
			PARTS TOTAL	\$4,794.48

Head office

6 Kung Chong Road Singapore 159143 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112 Branch

9A Serangoon North Ave 5 Singapore 554500 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011





OPTIMA WERKZ PTE LTD

Co. Reg. No. 201212455W

www.ow.sq

6 /OptimaWerkz

@ /OptimaWerkz

Date:

12/05/2022

Vehicle No: SNC8405G

Model:

TESLA MODEL 3 STANDARD RANGE

Chassis:

LRW3F7FA8MC385216

Reg. Year:

2021

Third Party Insurer: CHINA TAIPING

Third Party Veh No: GBB7280C

Date of Accident:

12/05/2022

Estimator:

KIT

Surveyor:

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOL	JNT S\$
1	REAR BOOTLID INNER TRIM CLIPS	1		na	\$50.00
2	REAR BUMPER CLIPS	1		Me	\$60.00
3	REAR END PANEL JOINT SEALANT NEC	1			\$80.00
4	REAR NUMBER PLATE WITH HOLDER	1		Su	\$50.00
	iAI				_
	-		S/N TOTAL		\$240.00

LABOUR CHARGES:

KIT

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS & ETC.

\$1,000.00 600/

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREAS & ETC.

\$1,000.00

TO REMOVE & REINSTALL REAR BOOTLID MECHANISM BACK TO ORIGINAL FUNCTIONS & ETC

\$120.00

LABOUR CHARGES TO REMOVE & REPLACE REAR PARKING SENSOR.

\$150.00

TO DAIGNOSIS FAULT CODE & RESET MEMORY.

\$150.00

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$120.00 201

TO TUFF KOTE & UNDERSEAL MATERIALS.

\$180.00 30/

LABOUR TOTAL \$2,720.00

TOTAL

\$7,754.48

LKK Auto Consultants hence notify

- the Repairer of the following: To resurvey before/lifter spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office 6 Kung Chong Road Singapore 159143 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

9A Serangoon North Ave 5 Singapore 554500 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



/ SINGAPURE

Date:

12/05/2022

Third Party Insurer:

CHINA TAIPING

Vehicle No: SNC8405G

Third Party Veh No:

GBB7280C

Model:

TESLA MODEL 3 STANDARD RANGE

Date of Accident:

Chassis:

LRW3F7FA8MC385216

Estimator:

12/05/2022

KIT

Reg.Year:

2021

Surveyor:

SUPPLEMENTARY

NO.	DESCRIPTION	QTY	UNIT S\$		JNT S\$
1	FRONT SAFETY SEAT BELT LH	1		Ta	\$158.88
2	FRONT SAFETY SEAT BELT RH	1		Jn	\$158.88
3	REAR SAFETY SEAT BELT LH	1		Ta	\$149.53
4	REAR SAFETY SEAT BELT RH	1		Ta	\$149.53
5	REAR SAFETY SEAT BELT CENTRE	1		Ta	\$135.51
6	BATTERY PYRO DISCONNECTOR ASSY	1		New	\$22.18
7	RESTRAINT CONTROL MODULE	1		New	\$560.75
8	REAR BLE ASSEMBLY	1		Mil	\$29.91
9	REAR SPARE TYRE PANEL TOP CARD BOARD	1		CM	\$186.92
10	REAR TRUNK LUGGAGE COMPARTMENT	1		cm	\$58.88
			SUB TOTAL		\$1,610.97
			LESS 10%		\$161.10
			PARTS TOTAL		\$1,449.87

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	CERAMIC COATING	1		\$400.00
			S/N TOTAL	\$400.00
CIT			TOTAL	\$1,849.87

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	931B
Vehicle No.:	SNC8405G
Vehicle to be Exported:	No
Intended Deregistration Date:	12 May 2022
Vehicle Make:	TESLA
Vehicle Model:	MODEL 3 STANDARD RANGE
Primary Colour:	White
Manufacturing Year:	2021
Engine No.:	-
Chassis No.:	LRW3F7FA8MC385216
Maximum Power Output:	239.0 kW (320 bhp)
Open Market Value:	\$58,311.00
Original Registration Date:	19 Nov 2021
First Registration Date:	19 Nov 2021
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$31,960.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Nov 2031
PARF Rebate Amount: Intended COE Rebate Details	\$23,970.00
COE Expiry Date:	18 Nov 2031
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$70,200.00
COE Rebate Amount:	\$66,807.00
Total Rebate Amount:	\$90,777.00

The information contained herein is correct as at 12 May 2022

SO03225C0001 / OPTIMA WERKZ PTE LTD ENTRY DATE & TIME: 12/05/2022 10:57 (SGT) SUBMITTED BY: Ary Chua VERSION: 1 (12/05/2022 10:57 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Please report <u>correctly</u> the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Authorised Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any faise reporting may be referred to the Police for Investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Date of Accident **Exact Location of Accident** Additional Location Information Country/State of Loss

12/05/2022 10:57 (SGT) 12/05/2022 07:46 (SGT) Near 2 Sunrise Ave, Singapore 806664 YIO CHU KANG RD TOWARDS SLE/TPE

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SNC8405G

Singapore

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner NRIC No

Email Address Mobile Phone No Alternative Phone No

WARREN CHIN CHEE HOW SXXXX931B WARRENCHINSG@GMAIL.COM (Phone) +65-98391169 +65-98391169

VEHICLE PARTICULARS

Manufacturer Model Variant

Exact purpose for which vehicle was being used at time of

Are you claiming under your own insurance policy for repair to your vehicle? Vehicle Category

Transmission CC

Tesla MODEL 3

MODEL 3 STANDARD RANGE

Private use

No - Claiming third party

Private car Auto 1999

INSURANCE COMPANY

Name of Insurance Company Type of Coverage

Fleet Policy Policy Number

Cover Note Number

Allianz Insurance Singapore Pte. Ltd.

Comprehensive No

SP2000703334-01

DRIVER

Name of Driver NRIC No

WARREN CHIN CHEE HOW SXXXX931B



Date Of Birth 31/01/1989 Occupation Indoor **Date Of Driving Pass** 01/04/2008 Driving experience 14 YEARS AND 1 MONTH Gender Mobile Number (Phone) +65-98391169 Alt. Phone Number +65-98391169 **Email Address** WARRENCHINSG@GMAIL.COM Address BLK 458A SENGKANG WEST RD #07-434 Address complement Postcode S791458 Is the driver the policyholder? Yes

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Head to Rear Weather Conditions Clear Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?

No
Number of vehicles involved in the accident

Was anybody injured in the Accident?

Was any injured conveyed to hospital by ambulance?

Was any other vehicle or property damaged?

Number of Passengers (Including Driver)

Has the driver been approached by unknown person(s)

soliciting/offering accident claims assistance?

No

DETAILS OF POLICE ACTION

Was the accident reported to the police?

Was notice of intended Prosecution given?

No
If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

REFER TO ACCIDENT REPORT ATTACHED

ATTACHMENT(S)

Are accident photos available for attachment?


Was there any video captured by Car Camera?

Was there any audio recorded?

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number **GBB7280C** Vehicle Manufacturer Toyota Vehicle Model Hiace Vehicle Variant Vehicle Colour Gray Vehicle Category Commercial vehicle Name of Driver **FAN LONG** Work Permit No GXXXX227W Contact Number (Phone) +65-97873028 Address



Address complement	-
Postcode	-
Insurance Company Name	_
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	_

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

l understand, acknowledge, agree and consent that :

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date &

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel ARY CHUA 12 MAY 2022

Sketch Plan

A=SNCOYOSE
B=GBB72800

Yio Chu tang
Rd towards SLE/TPE

A=SNCOYOSE

A=SNCOYOSE

B=GBB72800

Yio Chu tang
Fowards City

escribe Circumstances of the Accident	1 140.00
On 12fosts022 @ 07:46 hours I was driving of	Yio Chy
Kong Rd - Suddenly which B: GBE 72800	collided
into my rear which A: SNC 8405 G and	aused
into my rear vehicle A: SNC 8405 G and badly dangged. We alighted and exchange	particula
after accident.	
claration	

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

ARY CHUA 1

1 2 MAY 2021