

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/1908 GST Reg. No. 19-900/190-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERAL	INSURANCE (S) PL	F	Ref:	CS/AGI22004498/Uvy3n2	
	(BUDGET DIRECT 190 CLEMENCEAU SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE	[Date:	31/05/2022	
			(Code:	AGI	
1.	I. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SML 4713H	Veh. Inspected		SLL 1100H	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10015147/JM	Excess (\$)		0.00	
	Assign From	SHAFAWATI MD RABU	Assign Date		12/05/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ GLA180 (A)	c.c		1595	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	WDC1569422J327323	Colour		RED	
	Odometer	55610 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	235/50 R18	DUNLOP		7 mm	
	L/H Front Tyre	235/50 R18	DUNLOP		7 mm	
	R/H Rear Tyre	235/50 R18	DUNLOP		7 mm	
	L/H Rear Tyre	235/50 R18	DUNLOP		7 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	07/05/2022	Inspection Date	!	17/05/2022	
	Survey held at	EEVOLVE AUTO				
		1 KAKI BUKIT AVENUE 6 AUTOBAY @ KAKI BUKIT #02-25 SINGAPORE 417883				
5a.		Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: