

(08/11/13) wef

ASS. REC. BY: *Marcus*

REF:

*CS/AG/22004498/4vy3***ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: *SLL 1100H*at Workshop m/s *EE VOLVO AUTO*of *02-25*Insured: *SML 4713H 0*

Policy No. _____

Claims No. *C10015147/JM*


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: *890k.*

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: *4* days Res.: Yes or NoLum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

412A
Vehicle: IN / OUTDate: _____ Person Contacted: *LTA 442729*Veh No: *SLL 1100H* Yr Regn: *17/02/17*Type: *Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or *CA*Make: *Mer Benz GLA180* c.c. *1595*Colour: *Red* A/C: Insured / Std / NI / NASp. Reading: *55610* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *WDC15694225 327323*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt orModi: Nil / S/Rim / *STD A/Rim* or

Tyre Size: F: _____

R: *235/50 R18*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. *7* mmR/Bal. *7* mmL/Bal. *7* mmL/Bal. *7* mmD.O.A. *07/05/22*D.O.I. *17/05/22*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction *Dop 17k.**have video**25/5/22 4/5 @ 3850 informed Bertrand (red 6973.89, 64%)*

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: *4*

1)

☐ : Final ReportResurvey No. of Trip: *2*

Date/Time, File Return to?

Survey Fee:

2) *26/5/22-typist*Add Fee: ☐ : Site Insp (\$)) *S + RS* \$☐ : Interview (\$)

) Photos

☐ : Tech. Invs (\$)

) Others

☐ : Weekend (\$)

)

Report Format : TP

Lump Sum / L.B.L. (\$ *3850*)

TOTAL

➤ **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	412A
Vehicle Details	
Vehicle No.:	SLL1100H
Vehicle to be Exported:	No
Intended Deregistration Date:	17 May 2022
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	GLA180 (R18 BI)
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	27091031155779
Chassis No.:	WDC1569422J327323
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$28,212.00
Original Registration Date:	17 Feb 2017
First Registration Date:	17 Feb 2017
Transfer Count:	0
Actual ARF Paid:	\$26,497.00 13248
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Feb 2027
PARF Rebate Amount:	\$18,547.00
Intended COE Rebate Details	
COE Expiry Date:	16 Feb 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,889.00
COE Rebate Amount:	\$24,182.00
Total Rebate Amount:	\$42,729.00

The information contained herein is correct as at 17 May 2022

OK

Car Accessories & Products

Pimping up your ride? Browse thousands of car products for even more choices!
Read honest reviews by our trusted consumers before you make a purchase.

Post an Advertisement

Sell it yourself! Advertise it at just

\$68 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Fiat Doblo Cargo Maxi 1.6 Auto At \$58k.



Extremely Low Mileage, 6700KM
Yearly Only! 1st Owner, Accident
Free!
Direct Owner StarAd

click here to view
our **PRISTINE USED CARS**
at **GREAT PRICES**

Sort by Date Posted 20 results/page

13 vehicles












Mercedes Benz gla180

Any Category

Advanced Search



Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Mercedes Benz gla180		Any	Any	2017	Any	Any	Any	Available
	Mercedes-Benz GLA-Class GLA180		\$98,000	\$18,140 /yr	17-Jan-2017	1,595 cc	62,000 km	SUV	Available
	Very Well Maintained C&C Unit, Full C&C Serviced Record w Low Mileage 62,000km, Red Exterior / Black interior. Direct Owner Sale, SM...								DIRECT OWNER
	Posted: 17-May-2022								
	Mercedes-Benz GLA-Class GLA180 Urban Edition		\$110,800	\$18,030 /yr	20-Oct-2017	1,595 cc	70,000 km	SUV	Available
	C&C Agent unit, G63 Bodykit, upgraded sport rims, low milleage, tiptop condition, Full loan in house interest rates from 2.xx%, Bank loa...								PREMIUM AD
	Precise Auto Trading Pte Ltd								
	Posted: 14-May-2022								
	Mercedes-Benz GLA-Class GLA180 Urban Edition		\$110,800	\$18,100 /yr	02-Oct-2017	1,595 cc	58,000 km	SUV	Available
	2017 Face lift, Single owner with fully agent serviced unit, 10 years engine warranty with C&C, 100% loan available with immediate appr...								PREMIUM AD
	Straits Euro Motors Pte Ltd								
	Posted: 14-May-2022								
	Mercedes-Benz GLA-Class GLA180		\$97,800	\$17,620 /yr	23-Feb-2017	1,595 cc	77,500 km	Sedan	Available
	1 owner only. C&C unit. Super condition! Clean and neat interior, very well maintained by previous owner! Buy with a peace of mind fro...								PREMIUM AD
	Autolink Holdings Pte Ltd								
	Posted: 13-May-2022								
	2021 Mercedes-Benz G Class G63 AMG (For Lease)								
	\$17,888/mth G63 Amg For Rent with bold stylish exterior and spacious interior/storage space.								
	More info about this vehicle								
	Mercedes-Benz GLA-Class GLA180 Urban Edition		\$113,800	\$18,000 /yr	13-Dec-2017	1,595 cc	92,300 km	SUV	Available
	One Careful Owner. 10 years engine warranty with C&C, 100% loan available with immediate approval, flexible loan with attractive inter...								
	Posted: 12-May-2022								
	Mercedes-Benz GLA-Class GLA180		\$96,800	\$17,760 /yr	19-Jan-2017	1,595 cc	33,000 km	SUV	Available
	1 Owner, Low Mileage 6200km Done Yearly, Full C&C Serviced Record, 10 Years C&C Engine Warranty With 1 x Free Servicing With Age...								
	Posted: 12-May-2022								

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	09/05/2022 17:43 (SGT)
Date of Accident	07/05/2022 11:30 (SGT)
Exact Location of Accident	S730900, 900 South Woodlands Drive, W'Lands Civic Ctr, Singapore 730900
Additional Location Information	CARPARK GANTRY
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL1100H
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	CHUA LENG LENG
NRIC No	S7422412A
Email Address	llchua2@gmail.com
Mobile Phone No	(Phone) +65-97710868
Alternative Phone No	+65-97710868

VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	Gla180
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1595

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	7210004952-01
Cover Note Number	-

DRIVER

Name of Driver	CHUA LENG LENG
----------------	----------------

NRIC No	S7422412A
Date Of Birth	19/07/1974
Occupation	Indoor
Date Of Driving Pass	10/02/2004
Driving experience	18 YEARS AND 3 MONTHS
Gender	Female
Mobile Number	(Phone) +65-97710868
Alt. Phone Number	+65-97710868
Email Address	llchua2@gmail.com
Address	BLK 6 MARSILING DRIVE #08-86
Address complement	-
Postcode	730006
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

I WAS WAITING TO EXIT THE CARPARK AT THE CIVIC CENTRE WOODLANDS. I WAS BEHIND VEHICLE B (SML4713H) WHO IS RIGHT IN FRONT OF THE GANTRY. WHEN THE GANTRY BAR LIFTED, HE REVERSED INSTEAD OF GOING FORWARD AND COLLIDED ONTO THE FRONT OF MY VEHICLE.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SML4713H
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	LI YANGJIAN


NRIC No	S8232126H
Contact Number	(Phone) +65-98248108
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	VEHICLE B
No. Of Passenger (Including Driver)	1

SKETCH PLAN

SKETCH PLAN

IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident


I was waiting to exit the carpark at the civic centre wordland.

I was behind vehicle no B SML4713H who is right in front of the gantry.

~~Photo~~ When the gantry bar lifted, he reversed instead of going forward and collided into the front of my vehicle.

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time
7/5/2022

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

EEVOLVE AUTO

1 KAKI BUKIT AVENUE 6
AUTOBAY@KAKIBUKIT #02-25
SINGAPORE 417883

Not Authorized
Liu
narcus
90096608
4 days.
Take photo After repair
17/5/22

VEHICLE

NUMBER PLATE
MODEL
CHASSIS

SLL1100H
MERCEDES GLA 180
WDC1569422j327323

1/5 \$3810

ITEMS		DESCRIPTION	QTY	RATE	AMOUNT
1	Front bumper	de/ torn	1	\$1,467.60	\$1,467.60
2	Front side retainer RH LH	11	2	\$82.50	\$165.00
3	Front bumper lower grille	eng	1	\$176.32	\$176.32
4	Front bumper lower trim	cut	1	\$342.82	\$342.82
5	Front bumper center cover	si. hu	1	\$479.57	\$479.57
6	Front bumper lower support cover	11	1	\$249.30	\$249.30
7	Front grille complete assembly	cm	1	\$823.20	\$823.20
8	Front number plate bracket	102.32	1	\$115.70	\$115.70
9	Front hood	11	1	\$1,078.38	\$1,078.38
10	Energy absorber (sponge)	torn	1	\$208.74	\$208.74
11	Impact bar (reinforcement)	11	1	\$327.81	\$327.81
12	Front bumper Upper mounting (top bracket)	cm	1	\$115.90	\$115.90
13	Front bumper lower molding	cm	1	\$153.40	\$153.40
14	Side bracket RR LH	11	2	\$76.80	\$153.60
15	Parking sensor wire harness	11	1	\$172.00	\$172.00
16	Parking sensor spacer ring	11	2	\$10.20	\$20.40
17	Parking sensor bracket	11	2	\$36.50	\$73.00
18	Upper support tie bar	11	1	\$594.60	\$594.60
19	Lower support tie bar	11	1	\$506.70	\$506.70
20	Radiator support RH LH	11	2	\$78.52	\$157.04
21	Rail extension RH LH	11	2	\$173.75	\$347.50
22	Air duct RH LH	0/5 torn	2	\$44.50	\$89.00
23	Headlamp unit assembly RH LH	11	2	\$1,186.50	\$2,373.00
24	Headlamp washer nozzle RH LH	11	2	\$146.70	\$293.40
25	Headlamp washer pump RH LH	11	2	\$70.65	\$141.30
26					
27	inter cooler				
28					
ITEMS TOTAL					\$10,625.28
TOTAL -10%					\$9,562.75

SPECIAL NETT		DESCRIPTION	QTY	RATE	AMOUNT
1	Bumper cover rivet	11	10	\$5.00	\$50.00
2	Bumper clip set	11	20	\$3.50	\$70.00
3	MBZ top logo	11	1	\$45.90	\$45.90
4	Parking sensor	11	4	\$142.90	\$571.60
6	Front grille emblem + support	11	1	\$244.61	\$244.61
7	Front number plate	11	1	\$45.00	\$45.00

SPECIAL NETT ITEMS TOTAL	\$1,027.11
--------------------------	------------

LABOUR				
	DESCRIPTION	QTY	RATE	AMOUNT
	Panel beating, repair work 1 head and replace			\$1,400.00
	Spray painting	5	\$200.00	\$1,000.00
	To apply sealant and anti-rust	1	\$60.00	\$60.00
	To install reverse sensor and check wiring system	1	\$80.00	\$80.00
	To perform electrical components recalibration and reprogram	4	\$100.00	\$400.00
LABOUR TOTAL				\$2,940.00

TOTAL REPAIR COST

\$13,529.86

TOTAL LUMP SUM (-20%)	\$10,823.89
-----------------------	-------------

LOST OF USE

6 DAYS

P-3934-77
 102
 P-3541-29
 S.N-135-90
 L-1160
 4837-19
 203
 3869