

ASS. REC. BY:

REF:

SMO/ 22004512/Kg3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

CMTD2201653/AGC

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.:

Yes or No

Lum Sum:

1.B.1

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

26/05/22@11.59am revised to Agnes Chan by email.

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

), Fines

), Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Case Details

Case Reference Number : TAX/05/22/2032
Type of Repair : Accident Repair
Vehicle Registration Number : SHB5735A

Company Type : Strides Taxi Pte Ltd
Estimation ID : EST-18263-ID
Assigned By : Taxi Claims Manager Team

Insurance Company Name : Sompo Insurance Singapore Pte. Ltd
Accident Date and Time : 12/05/2022 02:55 AM
Vehicle Age(In Months) : 17

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval				Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace		
One Time Key In	Main			COVER, RR BUMPER ASSY	1	485.60	485.60	25.00	364.20	Replace	1	364.20	Replace	▼	
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	332.70	332.70	25.00	249.52	Replace	0	0	Not Give	▼	
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 3	2	11.00	22.00	25.00	16.50	Replace	2	16.50	Replace	▼	
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 2	2	4.00	8.00	25.00	6.00	Replace	2	6.00	Replace	▼	
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 1	2	4.00	8.00	25.00	6.00	Replace	2	6.00	Replace	▼	
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.30	22.60	25.00	16.95	Replace	2	16.95	Replace	▼	
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	132.60	132.60	25.00	99.45	Replace	1	99.45	Replace	▼	
One Time Key In	Main			SEAL, RR BUMPER , RH	1	118.30	118.30	25.00	88.72	Replace	0	0	Not Give	▼	
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	4.50	45.00	25.00	33.75	Replace	10	33.75	Replace	▼	
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	374.50	374.50	25.00	280.88	Replace	1	280.88	Replace	▼	
Total Spare Part Cost									9,638.87	Surveyor Total		1,705.69			
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		0			
Final Spare Part Cost									9,638.87	Final Sur Total		1,705.69			

SMRT Recommendation

Surveyor Approval

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, GUARD RR BUMPER LOWER	1	22.00	22.00	25.00	16.50	Replace	1	0	Old Dam	▼
One Time Key In	Main			PAD, RR BUMPER, CTR	3	11.00	33.00	25.00	24.75	Replace	3	24.75	Replace	▼
One Time Key In	Main			REAR BUMPER REFLECTOR ASSY, REFLEX, RH	1	39.00	39.00	25.00	29.25	Replace	0	0	Check	▼
One Time Key In	Main			TAIL GATE BACK DOOR HINGE ASSY, RH & LH	2	61.00	122.00	25.00	91.50	Replace	0	0	Not Give	▼
One Time Key In	Main			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	1,147.80	1,147.80	25.00	860.85	Replace	0	0	Not Give	▼
One Time Key In	Main			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	913.60	913.60	25.00	685.20	Replace	0	0	Not Give	▼
One Time Key In	Main			TAIL GATE LOWER GLASS SUB-ASSY, BACK DOOR	1	761.40	761.40	25.00	571.05	Replace	0	0	Not Give	▼
One Time Key In	Main			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	2	28.90	57.80	25.00	43.35	Replace	0	0	Not Give	▼
One Time Key In	Main			TAIL GATE MOULDING LOWER GLASS, BACK DOOR, LH	1	30.90	30.90	25.00	23.17	Replace	0	0	Not Give	▼
One Time Key In	Main			TAIL GATE MOULDING LOWER GLASS, BACK DOOR, RH	1	30.90	30.90	25.00	23.17	Replace	0	0	Not Give	▼
One Time Key In	Main			STRIDES LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Give	▼
One Time Key In	Main			STICKER DECAL 65558888	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Give	▼
One Time Key In	Main			SPOILER SUB-ASSY, REAR	1	1,575.40	1,575.40	25.00	1,181.55	Replace	1	0	Repair	▼
One Time Key In	Main			END PANEL SUB-ASSY, BODY LOWER BACK	1	651.00	651.00	25.00	488.25	Replace	0	0	Not Give	▼
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP, RH	1	339.60	339.60	10.00	305.64	Replace	1	305.64	Replace	▼

Total Spare Part Cost 9,638.87

Surveyor Total 1,705.69

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 9,638.87

Final Sur Total 1,705.69

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, REAR COMBINATION LAMP, RH	1	69.90	69.90	25.00	52.43	Replace	1	52.43	Replace	▼
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP, NO.2 RH	1	261.00	261.00	10.00	234.90	Replace	1	234.90	Replace	▼
One Time Key In	Main			LAMP ASSY, REAR, RH	1	293.60	293.60	10.00	264.24	Replace	1	264.24	Replace	▼
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Give	▼
One Time Key In	Main			ANTENNA, ELECTRICAL KEY	1	72.00	72.00	10.00	64.80	Replace	0	0	Not Give	▼
One Time Key In	Main			COVER, REAR FLOOR UNDER , RH	1	175.10	175.10	25.00	131.32	Replace	0	0	Not Give	▼
One Time Key In	Main			COVER, REAR FLOOR UNDER , LH	1	241.90	241.90	25.00	181.43	Replace	0	0	Not Give	▼
One Time Key In	Main			COVER, REAR FLOOR UNDER CENTER	1	229.90	229.90	25.00	172.43	Replace	0	0	Not Give	▼
One Time Key In	Main			PANEL SUB-ASSY, FENDER REAR RH	1	871.50	871.50	25.00	653.63	Replace	0	0	Not Give	▼
One Time Key In	Main			PATCH, SIDE PANEL REAR END , RH & LH	1	33.70	33.70	25.00	25.28	Replace	0	0	Not Give	▼
One Time Key In	Main			LINER, REAR FENDER , RH	1	139.80	139.80	25.00	104.85	Replace	0	0	Not Give	▼
One Time Key In	Main			WHEEL, DISC	1	1,879.40	1,879.40	25.00	1,409.55	Replace	0	0	Not Give	▼
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	▼
One Time Key In	Main			HUB & BEARING ASSY, RH & LH	1	668.90	668.90	25.00	501.67	Replace	0	0	Not Give	▼
Total Spare Part Cost									9,638.87	Surveyor Total		1,705.69		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		0		
Final Spare Part Cost									9,638.87	Final Sur Total		1,705.69		

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION RH	845.00	200	
Total:			845.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY REAR SPOILER	180.00	100	
3	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0	
4	Main	TO RESPRAY TAIL GATE	378.00	0	
5	Main	TO RESPRAY BUMPER BEAM	180.00	0	
6	Main	TO RESPRAY REAR PANEL	180.00	0	
7	Main	TO RESPRAY REAR FENDER RH	378.00	0	
8	Main	TO RESPRAY RIM	180.00	0	
Total:			2,034.00	300.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REMOVE AND REFIX TAILGATE GLASS	120.00	0	
2	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
3	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	50	
4	Main	TO REPLACE SUNDRY PARTS	100.00	0	
5	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
6	Main	TO WASH AND VACUUM	60.00	0	
Total:			600.00	70.00	

Summary

Estimator Assessment(\$)

Surveyor Assessment(\$)

Estimator Assessment(\$)

Surveyor Assessment(\$)

Total Spare Part Detail	9,638.87	1,705.69
Total Labour Cost	845.00	200.00
Total Spray Painting	2,034.00	300.00
Other	600.00	70.00
Overall Total	13,117.87	2,275.69
Lump Sum Repair Option		☐
Lump Sum Total	0.00	2,275.69
Surveyor Approved Amount		2,275.69
No of Repair Days*	7	2


Remarks

PART BY PART REPAIR / BEFORE PAINT PHOTO / FOR
CHECK ITEM and REPLACE ITEM PLEASE CALL
SURVEYOR Kenneth Kong (LKK) HP : 9691 0663 / Email

Surveyor Name

Kenneth Kong (LKK)

Signature



Save

Clear

Survey Date

13/05/2022

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer**Signature:****Date:**

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	12/05/2022 14:52 (SGT)
Date of Accident	12/05/2022 10:55 (SGT)
Exact Location of Accident	10 Admiralty St, Singapore 757695
Additional Location Information	NORTHLINK BUILDING ADMIRALTY STREET
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB5735A
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	Strides Taxi Pte Ltd
Company Reg No	1XXXXX369K
Email Address	AUTO-SVCS-TARC@SMRT.COM.SG
Mobile Phone No	(Phone) +65-68662671
Alternative Phone No	(Office) +65-68662672

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1800

INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Type of Coverage	ThirdParty
Fleet Policy	Yes
Policy Number	D-22099115MFSH
Cover Note Number	-

DRIVER

Name of Driver	QUAN SHU PING
NRIC No	SXXXX225G

IMPORTANT NOTICE

SKETCH PLAN

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



A - SHB5735A
B - YN3077P