ASS. RECABY: STEW CS/CT1 120	04520/EVC
ASSIC	ENMENT
From: Date:	Veh No: SKS 6269 Y Yr Regn: 28/4//5
Estimated Cost:	Type: M.Carl M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
OD INDI WS ITP RES I OD RES I EVA I INV I MY	Truck / Traller or
To Inspect Vehicle No:	Make: RMW X3 c.c 1997
at Workshop m/s	Colour SIVEY A/C: Insured / Std / NI / NA
of	Sp.Reading 13/860 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	CNO: WBAWY970900300048.
Claims No.	Gen. Cond: Good I F or I Poor I Burnt
Sum Insured: Excess:	Steering: In order / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorfee / Jammed / Leaked / Burnt or
Make of Veh;	Modi: Nil / S. Rim / STD A/Rim or
	Tyre Size: F:
(Policy Condition)	R: '1
Remark: The veh had commenced its N/S O/S	BS I OUN EXNOVA I GY I FS I LIZA I MIC I OHTSU I PIR I SUMI I
repair at the time of inspection.	TOYOTYOKO or
Bal. or Market Value:	Front Rear R/Bal. 5 mm
IDAC Accident Rport: Consistent? : Yes or No	Noal, J
GIA / PR Seen:Consistent? : Yes or No	DBal
Est Repairs: days Res.: Yes or No	Dodroma Podroma
Lum Sum: % · 3 Val.: Yes or No	Solvey hold at
CA / REV / REP. / 24 HRS	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OU	The U/C / Chassis frame / Body Structure affected due to collision.
Date:Person Contacted:	The state of the s
Date / Time Action / Instruction	1
**	
Osie/Time, File Pass to? : Prell. Report	Days Of Repair:  Survey Fee:
; Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	(2)
Add	ree:
	- Illiterates (
Ropert Format :	; fech, mvs (v
Lunsp Stun / L.B.J. (F	:Westend (*
	. TOTAL

BMW Dealer

### Performance Motors Limited

A Sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)

303. Alexandra Road Sime Darby Performance Centre Singapore 189941 Fax. 64747770 280, Kampong Arang Road East Coast Centre Singapore 438180 Pax. 63449773

115, Alexandra Road Simme Darby Susiness Centre Singapore 159944



#### ESTIMATE

Estimate No.

: b1 61781

Page No. : 1 of 5

Date Estimated

: 12/05/2022

801.80

99.95

209.30

65.60

26.15

131.55

27.85

Total Parts

1,495.00

1

1

1

Prepared By

: Inthiran A/L Thurasamy

ESTIMATE REPAIR FOR -

Wong Sheow Yit 10 Holland Avenue

#03-09

- ACCOUNT -135

China Taiping Insurance (S) Pte Ltd

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

Singapore 271010

REGN. NO.

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE

CECESEON

RR BUMPER CARRIER ECE

MODEL LETTERING X3 //

REAR BUMPER PANEL PRIMED (PDC) / 00

(DG/SL)ADHESIVE PRIMER VP 206 (30ML

(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)

COVER MIDDLE BOTTOM

(DG) CLEANER R1 (100ML)

/ CM

REAR BUMPER CLADDING (PDC/SCHWARZ) (MAK) / (M

SKS6269Y	WBAWY920900J00048 28/04/2015	X3 sDrive20	94738
	To replace rear bumper, tailgate and attachements.  To painting rear bumper and tailgate.	SSOX2	VALUE 1711 2,550.00 1972 2,076.00
	To remove and install rear windscreen glass to facilitate repair.		545 574.00
	To conduct water leak tests.		71 75.00
	To check electrical wiring system and lighting at the rear section for proper function.		68 177.00
	To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.		168 177.00
	To carry out body cavity preservation. (Per panel).		//2 118.00
	Sundries.		7 150.00
		Total Labour 1:	5,897.00
	DESCRIPTION ON	OTY PRIC 1 1,870.95	VALUE 1,870.95

801.80

99.95

209.30

65.60

26.15

131.55

27.85

4,728.15

1,495.00

EMW Dealer

## **Performance Motors Limited**

A Sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Pax. 64747770

280, Kampong Arang Road East Coast Centre Singapore 438180 Fax. 63449773

Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSa:
64796624 (Motorrac (AfterSales) (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No.

: b1 61781 Page No. : 2 of 5

Date Estimated

: 12/05/2022

Prepared By

WBAWY920900J00048

: Inthiran A/L Thurasamy

MILEAGE

REGN. NO. SKS6269Y CHASSIS NO.

REGN. DATE 28/04/2015

X3 sDrive20

MODEL

94738

Steve CLKK) WIND PIP 25/7/12, 3m/ MBLY 5 Ly



5,897.00 Labour 1 Parts 4,728.15 Labour 2 0.00 : Excess 0.00 743.76 Total GST @ 7% Grand Total 11,368.91



<sup>\*\*</sup> THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

<sup>\*\*</sup> PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

## SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process

2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

3. Intrination provided must be as truthful and accurate as possible. Any wilnut misrepresentation of witholding of material facts may allow insurance companies to reputate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### **ACCIDENT STATEMENT**

Date of Submission Date of Accident **Exact Location of Accident** 

Additional Location Information

Country/State of Loss

09/05/2022 15:27 (SGT) 06/05/2022 16:21 (SGT)

Singapore

TRAFFIC LIGHT INFRONT OF SPC (JUNCTION OF JALAN

LEBAN AND UPPER THOMSON)

Singapore

#### **DETAILS OF OWN VEHICLE**

SKS6269Y Vehicle Registration Number

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

NRIC No

**Email Address** Mobile Phone No

Alternative Phone No

No

WONG SHEOW YIT

SXXXX429A

SHEOWYIT@GMAIL.COM

(Phone) +65-94746937

(Home) +--

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of

Are you claiming under your own insurance policy for repair to your vehicle?

Vehicle Category Transmission

CC

**X3** 

**BMW** 

Private use

No - Claiming third party

Private car Auto

1998

No

INSURANCE COMPANY

Name of Insurance Company

Type of Coverage Fleet Policy **Policy Number** 

Cover Note Number

DRIVER

Name of Driver

WONG HUI JUIN

Comprehensive

P10355926R02

Auto & General Insurance (Singapore) Pte. Limited.

Accident report SP0122590006

Page 1 of 23



SXXXX586B NRIC No Date Of Birth 15/04/1982 Indoor Occupation 06/05/2004 Date Of Driving Pass 18 YEARS Driving experience Female Gender (Phone) +65-82018367 Mobile Number Alt. Phone Number SHEOWYIT@GMAIL.COM **Email Address** 10 HOLLAND AVENUE Address #03-09 Address complement 271010 Postcode

No Is the driver the policyholder?

If No. Relationship of the Driver with the Insured Spouse Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Collision - Head to Rear Type of Accident Clear Weather Conditions Dry Road Surface

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) 2 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

PASSENGER 1

WONG FUN YEE Name Male Gender

DETAILS OF POLICE ACTION

Was the accident reported to the police? No No Was notice of intended Prosecution given? If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

SEE ATTACHED SKETCH PLAN

ATTACHMENT(S)

Yes Are accident photos available for attachment? Was there any video captured by Car Camera? Yes Was there any audio recorded? No

#### **DETAILS OF OTHER VEHICLE PROPERTY 1**

**SLK4366T** Vehicle Registration Number Honda Vehicle Manufacturer Vehicle Model Vehicle Variant Black Vehicle Colour

Accident report SP0122590006

Page 2 of 23



Vehicle Category
Name of Driver
Contact Number
Address
Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)
Private hire
Company
Co



#### SKETCH PLAN

#### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

tallfat Seruhelmbonn V.

Date & Time:

222

Driver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

NRIC/FIN No.

Name:

303 Alexandra Road coo Darby Performance Contre Cinuapore 1590/1

**CS** CamScanner

SKETCH PLAN	= x s 6 > 6 9 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
DESCRIBE CIRCUMSTANCES OF THE A	

# Auident tack place at 4.21pm at the traffic light in front of 892 (Sunction of Dalan Wan and upper Thanson). I was at the red light when I heard a bring and feet a bring. I got out from my car to cheek and noticed that the car, SLK 4366T, had bumped on the near of my car. I On closer inspection, the bumper (black starts) was slightly dest to the touch. There was also a squarish, rounded don't below the carplage. This Was likely caused by the squarish frame of the Handa sin. The damages above were acknowledged by the driver of SLK 43667. The diver gave me his custout number of personal details 1c: S1829957G Name: Chua Kay Meng

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time: 2 Man

GATM I diller on yo

Driver's Signature

(If driver is not the policyholder)

Date & Time:

**Aurasamy** Reporting Centre Production Signature
Name: 303/Alexand Road
NRIC/FIN Name Darby Performance Centre

Singapore 159941