ASS. REC. BY: STOP 1 ALG	
ASSI	GNMENT
From; Date:	Veh No: SND 548A Yr Regn: 30 11/21
Estimated Cost:	Type: (M.Cor / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
OD TP/WS/TP RES/OD RES/EVA/INV/MY	Truck / Traller or
To Inspect Vehicle No:	Make: Aud 1 At c.c 1984
at Workshop m/s	Colour White A/C: Insured / Std / NI / NA
of	Sp.Reading 1/178 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	CINO: WAY 222 F45 LN 014 197:
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inforder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder/Jammed/Leaked/Burnt or
Make of Veh;	Modl: Nil / SIRIm / STD A/Rim or
1 ~ ~ ~	Tyre Size: F: 125/50R17
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYOTYOKO or Hankook
Bal. or Market Value:	Fron! Rear
IDAC Accident Roort Consistent? : Yes or No	R/Bal. () mm , R/Bal. () mm
GIA / PR Seen: Consistent?: Yes or No	UBal. U mm UBal. U mm
Est Repairs: days Res.: Yes or No	D.O.A. 10/6/7/ Promium 13/5/7/
Lum Sum: % · 3 Val.: Yes or No	Survey held at Premium
CA / REV / REP. / 24 HRS	Des. of Damages : Frt Rear O/S N/S U/C Rooftop or
Vehicle: IN/O	The U/C / Chassis frame / Body Structure affected due to collision.
Date: Person Contacted:	The U/C / Chassis traine / Body Structure discourse
Date / Time Action / Instruction	
1414-1437	
,	<u> </u>
Oste/Time, File Pass to? : Preli. Report	Days Of Repair:
- I Brook	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
	Fee: : Site Insp (\$)s + RsSI
	:Interview (\$) Photos
Report Format :	:Tech, Invs (\$) Others
Lump Sum / LO.J: (%	: Weellend (%
	TOTAL
· · · · · · · · · · · · · · · · · · ·	



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE

: ACCIDENT REPAIRS

WORKSHOP CONTACT NO FAX NO : UBI ROAD 1 : 6366 2323 : 6841 1183

REFERENCE

: PA/OD/0373/2022/JT

DATE

: 12-May-22

WIP

: 23418

VEHICLE IN WORKSHOP, KINDLY ARRANGE FOR SURVEY ON 13/5/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY #07-16 AIG BUILDING SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME

: M/S PREMIUM AUTOMOBILES PTE LTD

ADDRESS

: 55 UBI ROAD 1

SINGAPORE 480699 40NE : HP +65 68365223

 TELEPHONE
 : HP +65 68365223

 TYPE OF CLAIM
 : OWN DAMAGE CLAIM

 POLICY NO
 : 099999355/1220000168

VEHICLE NO : SND 548 A

MODEL CODE : AUDI A4 2.0 TFSI S TRONIC

MODEL YEAR : 30/11/2021 ENGINE NO : DEM 024241

CHASSIS NO : WAUZZZF45LN014797

MILEAGE : -

DATE IN : -

ESTIMATED BY : JOHNNY BOO / ALLAN WU

ACCIDENT DATE : 10-May-22

PLACE OF ACCIDENT : GUILLEMARD ROAD

55 UBI ROAD 1, SINGAPORE 408699 TEL : 6366 2323 FAX : 6841 1183 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SND 548 A

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
3/14				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N	\$ 480.00	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N	\$ 700.00	250
3	TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI- LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N	\$ 350.00	280
4	TO REMOVE AND REINSTALL LHS FRONT PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR.	S/N	\$ 280.00	X
5	TO REMOVE AND REINSTALL FRONT SEAT ASSY, BACK REST, AB PILLAR TRIMS, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS.	S/N	\$ 1,800.00	?
6	TO REMOVE AND RENEW BOTH FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME.	S/N	\$ 2,400.00	7
7	TO REMOVE AND RENEW LHS REAR WHEEL SUSPENSION ASSY WITH SUBFRAME.	5/N	\$ 2,400.00	. ?
	SUB TOTAL LABOUR CHARGES	:	\$ 8,410.00	=



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SND 548 A

				ESTIMATED	SURVEYOR'S
S/N	NATURE OF JOBS			CHARGES	RECOMMENDATIONS
8	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS.	S/N :	5	1,400.00	?
9	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDER, BONNET, RHS FRONT DOOR AND BOTH HEADLIGHT. TO REPAIR RHS FRONT FENDER TOP SUPPORT AND LHS FRONT DOOR. TO CUT OUT AND WELD LHS LOWER A-PILLR WITH LHS SILL PANEL. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGAMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	松 4	\$	10,000.00	1200
10	TO RESPRAY FRONT BUMPER, BONNET HINGES, BOTH FRONT FENDERS, BOTH FRONT DOORS, RHS FRONT FENDER TOP SUPPORT, LHS A-PILLAR, LHS SILL PANEL AND DOOR ENTRANCE.		6 s	8,000.00	3300
11	TO RENEW RHS FRONT RIM WITH TYRE, LHS FRONT RIM WITH TYRE AND LHS REAR RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N	\$	560.00	/
12	TO TOW BACK THE VEHICLE FROMT ACCIDENT SCENE.	S/N	\$	280.00	X
13	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N	\$	384.00	
	TOTAL LABOUR CHARGES	:	\$	29,034.00	_



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SND 548 A

DAMAGED PARTS & PRICES

			DAI IAGED FARTS	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER / JR	1	\$ 2,377.00	
2	FRONT BUMPER FIXING PARTS / M	1	\$ 393.00	
3	FRONT BUMPER SECURING STRIP / TT (PH)	12	\$ 79.00	
4	FRONT BUMPER GRILLE - CENTER	1	\$ 219.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER /	JK 1	\$ 293.00	
6	FRONT BUMPER AIR GUIDE - LH / RH / //	21	\$ 102.00	
7	FRONT BUMPER CLOSING ELEMENT - UPPER CENTER	1	\$ 293.00	
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH / Mis	2	\$ 302.00	
9	FRONT BUMPER TRIM - LH / RH / CM7	21	\$ 108.00	
10	RADIATOR GRILLE & / OK	1	\$ 1,754.00	
11	FRONT BUMPER FOAM FILLER PIECE	1	\$ 212.00	
12	FRONT BUMPER REINFORCEMENT	1	\$ 899.00	
13	FRONT BUMPER BRACKET - LH / RH	2	\$ 508.00	
14	FRONT BUMPER GUIDE SECTION- LH / RH	21	\$ 82.00	
15	FRONT BUMPER TOP COVER / IR	1	\$ 143.00	
16	CAUTION STICKER - No.	1	\$ 16.00	
17	AIR COND STICKER / M	1	\$ 9.00	
18	FRONT BUMPER LOCK CARRIER BRACKET	1	\$ 154.00	
19	FRONT BUMPER SUPPORT - LH / RH	2	\$ 64.00	
20	FRONT BUMPER POP RIVET	4	\$ 4.00	
	SUB TOTAL SPARE PARTS	:	\$ 8,011.00	

55 UBI ROAD 1, SINGAPORE 408699 TEL : 6366 2323 FAX : 6841 1183 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SND 548 A

DAMAGED	PARTS &	PRICES
---------	---------	--------

				Drift Drift Control	
S/N	PARTS DESCRIPTION	QTY		S/NETT	REMARKS
		2	5	273.00	
21	HORN-LH/RH X		5	66.00	
22	HORN BRACKET - LH / RH (X)	. ~	5	530.00	
23	FRONT PARKING AID SENSOR - OUTER	12		10.00	
24	FRONT PARKING AID SENSOR SEAL RING / //C	4	\$	642.00	
25	FRONT BUMPER WIRING SET	1	\$		
26	FRONT FENDER - LH / RH / 00	(2)	\$	2,454.00	
27	FRONT FENDER ATTACHMENT PARTS χ	1	\$	211.00	
28	FRONT FENDER CLOSING ELEMENT - LH / RH / 1/10	2	\$	162.00	
	FRONT FENDER BRACKET - LH / RH / nec	21	\$	82.00	
29		21	\$	264.00	
30		12	\$	46.00	
31	FRONT FENDER POP RIVET / M(11	\$	110.00	
32	FRUNT FENDER BRACKET CENTER	2	5	71.00	
33	FRONT FENDER BRACKET END - LH / RH			74.00	
34	FRONT FENDER CLOSING ELEMENT END - LH / RH	2	\$	4	
35	FRONT WHEEL HOUSING LINER - LH / RH / T1	(2)	\$	518.00	
36	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	N ° 1	\$	149.00	
	FRONT WHEEL SPOILER - LH / RH / DR	71	\$	164.00	
37	PROINT WHELE STORES	21		79.00	
38	FRONT WHEEL SPOILER LOWER - LH / RH / MIJ	1	\$	3,425.00	
39	BONNET Y R	1	\$	431.00	
40	BONNET ATTACHMENT PARTS X	1	,		
	TOTAL SPARE DARTS	:	\$	9,761.00	
	SUB TOTAL SPARE PARTS		_		

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SND 548 A

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY		S/NETT	REMARKS
41	BONNET HINGE - LH / RH X	2	\$	680.00	
	BONNET IMPACT PROTECTION - CENTER / LH / RH / Me	3	5	93.00	
42		1	\$	64.00	
43	LA.	1	5	15.00	
44	AM		\$	16,344.00	
45	HEADLIGHT - LH / RH / CM	21	\$	83.00	
46	HEADLIGHT HOSE	2		270.00	
47	SPACER	6	\$	462.00	
48	LIFT CYLINDER - LH/RH /MI	21	\$		
49	LIFT CYLINDER BRACKET / MI	21	\$	14.00	
50	LIFT CYLINDER CORRUGATED PIPE / BR	1	\$	107.00	
51	LIFT CYLINDER CORRUGATED PIPE - UPPER X	1	\$	53.00	
52	WASH WATER RESERVOIR	1	\$	160.00	
53	LOCK CARRIER	1	\$	1,127.00	
54	LOCK CARRIER BRACKET - LH / RH	2	\$	85.00	
55	RADIATOR COOLANT	6	\$	282.00	
	RADIATOR AIR GUIDE - LH / RH	2	\$	102.00	
56	RADIATOR AIR GUIDE INNER - LH / RH	2	\$	38.00	
57	0	1	\$	19.00	
58	RADIATOR AIR GUIDE - UPPER 1	1	\$	25.00	
59	RADIATOR AIR GUIDE - LOWER			3,431.00	
60	FRONT DOOR - RH X K	1	\$	3,431.00	
	SUB TOTAL SPARE PARTS	:	\$	23,454.00	



 ∞

55 UBI ROAD 1, SINGAPORE 408699 TEL : 6366 2323 FAX : 6841 1183 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SND 548 A

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY		S/NETT	REMARKS
		_		229.00	
61	FRONT DOOR OUTER SEAL - RH	1	\$	51.00	
62	BONDING AGENT X	1	\$		
63	CLEANING SOLUTION X	1	\$	74.00	
64	APPLICATOR	1	\$	8.00	
65	FRONT DOOR ATTACHMENT PARTS	1	\$	1,153.00	
66	FRONT DOOR CATCH - RH X	1	\$	116.00	
67	TYRE PRESSURE DATA PLATE	1	\$	42.00	
68	FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - LH / RH	2	\$	688.00	
	A/B PILLAR FRAME MEMBER - LH	1	\$	2,874.00	
69	FRONT DOOR SILL TRIM STRIP-LH Y	1	\$	133.00	
70	ALUMINIUM RIM (FIN PH, LH Pa. LH) - BT	3	\$	3,876.00	
71		1	7 5	15.00	
72		1	\$	2,096.00	
73	* * *	2	\$	1,210.00	
74		2	\$	2,114.00	
75	FRONT SUSPENSION GUIDE - LH / RH	2	5	1,150.00	
76		2	\$	1,150.00	
77	REAR SUSPENSION GUIDE UPPER - LH / RH	2	\$	2,140.00	
78	FRONT WHEEL BEARING HOUSING - LH / RH			427.00	
79	1	2		995.00	
8	PEARING WHEEL HUB	2	\$		
01		:	\$	20,541.00	
	SUB TOTAL SPARE PARTS				r.



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SND 548 A

DAMAGED	PARTS &	PRICES
---------	---------	--------

S/N	PARTS DESCRIPTION	QTY		S/NETT	REMARKS
	1				
01	DOUBLE BALL BEARING FLANGE	2	\$	545.00	
81	7	2	\$	586.00	
82	SUSPENSION FORKS - LH / RH	4	\$	516.00	
83	COUPLING ROD			478.00	
84	ANTI-ROLL BAR	1	\$		
85	GAS SHOCK ABSOBER 7	2	\$	664.00	
-	VELOCITY JOINT DRIVE SHAFT 7	2	\$	5,998.00	
86	-1	1	\$	7,318.00	
87	STEERING GEAR TRACK ROD JOINT	2	\$	218.00	
88	TRACK ROD . 1		\$	434.00	
89	TIE ROD END - LH / RH	2		3,643.00	
90	CLIBERAME SUPPORT	1	\$		
-	WISHBONE ALUMINIUM - LOWER 7	1	\$	963.00	
91	()	1	5	624.00	
92	WISHBONE - LH UPPER	1	5	137.00	
93	WISHBONE - LH FRONT	1	5	501.00	
94	WISHBONE - LH REAR			188.00	
95	TRACK ROD - LH REAR 7	1	\$	-	
	REAR WHEEL BEARING HOUSING - LH	1	\$	1,097.00	
96	0	1	\$	723.00	
97	WHEELHUB BEAKING 2	1	5	49.00	
98	WHEEL BEARING HOUSING STONE CHIP GUARD		5	640.00	
99	FRONT NOISE INSULATION ?	1		60.00	
100	NC	S/N	\$	60.00	
100			\$	25,382.00	
	SUB TOTAL SPARE PARTS	•	_	20,000	



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO.SND 548 A

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY		S/NETT	REMARKS
	1			180.00	
101	ARYLIC SEALANT	S/N	\$		
	CAVITY WAX 1	S/N	\$	140.00	
	ρ / N	S/N	\$	180.00	
	STUNE CHIP 1	S/N	\$	280.00	
104	METAL FILLER POWDER	3/14	J		
105	RHS FRONT TYRE 80% TA	S/N		TBC	
	6 11 1/2 /	S/N		TBC	
	LHS FRONT TYRE TO h	S/N		TBC	
107	LHS REAR TYRE (), Th	3/14			
108	SUNDRIES		\$	1,000.00	
	Y .		5	88,929.00	
	TOTAL SPARE PARTS	•			
	TOTAL LABOUR CHARGES	:	\$	29,034.00	
		:	\$	117,963.00	
	GRAND TOTAL	,			

ALL CHARGES ARE NOT INCLUSIVE OF GST

LECEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.

SPOR223L0009 / PREMIUM AUTOMOBILES PTE LTD [408699] ENTRY DATE & TIME: 11/05/2022 16:01 (SGT) ENBMITTED BY: FOONG CHIN FONG SUBMITTED BY: FOONG CHIN FONG YERSION: 1 (11/05/2022 16:01 (SGT))



SINGAPORE ACCIDENT STATEMENT

Please report <u>correctly</u> the details of the accident to speed up the claims process.
 This Form must be <u>completed by the Policyholder and/or the Authorised Drivet</u>
 Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

3. Information produced the second production of policy liability on the part of the insurance companies.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for Investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Date of Accident Exact Location of Accident Additional Location Information Country/State of Loss

11/05/2022 16:01 (SGT) 10/05/2022 03:00 (SGT) Guillemard Rd, Singapore

Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SND548A

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner

Company Reg No **Email Address** Mobile Phone No Alternative Phone No Yes

PREMIUM AUTOMOBILES PTE LTD 1XXXXX271W CLAIMS@PREMIUMAUTO.COM.SG

(Phone) +65-88918095

+65-88918095

VEHICLE PARTICULARS

Manufacturer Model

Variant

Exact purpose for which vehicle was being used at time of

Are you claiming under your own insurance policy for repair to your vehicle?

Vehicle Category Transmission

CC

Audi

A4

Private use

Yes Private car Auto

1984

INSURANCE COMPANY

Name of Insurance Company

Type of Coverage Fleet Policy Policy Number Cover Note Number AIG Asia Pacific Insurance Pte. Ltd. Comprehensive

Yes

099999355/1220000168

DRIVER

Name of Driver NRIC No

HUMPHERY TSOI HON YIK SXXXX745D



Accident report SP0R223L0009

Page 1 of 35

17/01/1991 of Birth Indoor 29/10/2019 ocupation Octobro Of Driving Pass 2 YEARS AND 7 MONTHS priving experience (Phone) +65-88918095 Gender Mobile Number CLAIMS@PREMIUMAUTO.COM.SG Alt. Phone Number 460 BEDOK SOUTH AVENUE 3 Email Address #14-48 Address Address complement No postcode Is the driver the policyholder? **AUTHORISED DRIVER** If No. Relationship of the Driver with the Insured No Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Collided into Property Type of Accident Clear Weather Conditions Dry Road Surface OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident No Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Yes Was any other vehicle or property damaged? Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) No soliciting/offering accident claims assistance? DETAILS OF POLICE ACTION No Was the accident reported to the police? No Was notice of intended Prosecution given? If yes, against whom? CIRCUMSTANCES OF ACCIDENT DRIVING ALONG GULLEMARD ROAD . SUDDENLY A 'BOOM' SOUND FROM FINE BURST FRONT RIGHT TYRE AND THE CAR LOSE CONTROL AND HIT THE DIVIDER. THE CAR SPINNED AND HIT AND WENT OVER THE KERB. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No No

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour NA / Unknown Vehicle Category Name of Driver Contact Number Address

Accident report SP0R223L0009

Page 2 of 35

oddress complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witcholding of male, or facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the monorce companies
- 5 Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GN Records Management Centre established by the General Insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested carties.
- 7. By the ladgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copyring the report being made available aforesaid.
- 8 Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that

- (a) My insurer , my wickshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use in sciose and/or process my personal data/personal information set out in this [form] and any other personal information provided by my or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer (s who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (ii) carrying out and/or dealing with my instructions or responding to any enquiries by me.
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes ma-
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents

(including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

too sions

Policyholder's Signature / Date &

Driver's Signature (if driver is not the policyholder) / Date 10 MAY2012 Personnel

Witnessed by Reporting Centre

& Time

Sketch Plan

1:26pm

Describe Circumstances of the Accident	
front right the and the our lost control and hit to	Would from time bilet
whit just the mil the pur loss whited out hit	he duider. On ar soil
the hie and upont own the nich	
the state of the state.	
A Section of the second section of the section of the second section of the second section of the second section of the section of the second section of the	
claration	Α.
le declare the foregoing particulars are true in every respect.	\mathcal{L}
A (P)	
Siang. (Yell)	(3(4 大)
Via 1) Uill CI	(*)
MV	
icyholder's Signature / Date & Driver's Signature (# driver is not the policyholder) / Dat	e Witnessed by Reporting Contre Personnel
briver's Signature / Date & Driver's Signature (# driver issue the post-	La Sancia
(V 141)	
1:24 pm	

Accident report SP0R223L0009

Page 5 of 35