

SEALED BY: Thuan

CS3 / LPL 22000632 / V 143 + 43

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 58k

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SCH2343Y

Yr Rogn: 10

Type: Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota prius hybrid

c.c 1797

Colour: white

A/C: Insured / Std / NI / NA

Sp. Reading: 169560

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTDKB3Fu403544059

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: 195/65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

humbro

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 13/1/22

D.O.I. 18/1/22

Survey held at Atec

Des. of Damages: Fit Rear / O/S / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MV: <u>58k</u>
	rebate: <u>32387</u> submit PRS Report
	NU: <u>25613</u>
	rr: <u>220220312-412</u>
	Paper survey done by Simon Ho
27/06/2022	Submit LS \$2,300.00 : 4 days
	(Red: \$10,000.00 : 81%)

Date/Time, File Pass to?

☐

: Prell. Report

ij

☐

: Final Report

Date/Time, File Return to?

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trlp: \_\_\_\_\_

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Wash and

Survey Fee:

Transportation:

\_\_\_\_ S + RS. \_\_\_\_ \$

Finis

Others

Total

Request Form:

Line 344 / 1.1.1