

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Rog. No. 10000110010 To 0001100 TO					
Affiliated to Federation Internationale Des Experts En Automobile					
	JUSEQUITY LAW	CORPORATION	Ref:	CS/LAW22004531/Aqce2	
	133 NEW BRIDGE #10-03 CHINATOV SINGAPORE 0594	VN POINT	Date	e: 05/07/2022	
			Cod	e: L053	
1.	Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
	Insured Veh.	XE 345U	Veh. Inspected	PC 4776M	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	MC/MC 4483/2021	Excess (\$)	0.00	
	Assign From	KIRAN KAUR	Assign Date	13/05/2022	
2.	2. Vehicle Particulars & Condition				
	Make & Model	NISSAN NV350	c.c	2488	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	JN1UC4E26Z0001766	Colour	SILVER	
	Odometer	277018 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	195 R15C	FALKEN	6 mm	
	L/H Front Tyre	195 R15C	FALKEN	6 mm	
	R/H Rear Tyre	195 R15C	FALKEN	6 mm	
	L/H Rear Tyre	195 R15C	FALKEN	6 mm	
4.	Description of Damages				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
	REPAIR CONDITION SEE DETAILS.				
5.	General Information				
	Accident Date	11/09/2019	Inspection Date	18/05/2022	
	Survey held at	BLK 51 DEFU LANE 9 SINGAPORE 539291			
	Repairer	AUTOMOBILE HUB ENTERPRISE			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

10 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: