

ASS. REC. BY:

REF:

AIG / 22004543 / Ke

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

28/6 11pm @ 5100k Continue

Veh No:

GIBB 91192 Yr Regn: 01, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Dyna c.c. 2982

Colour:

Yellow A/C: Insured / Std / NI / NA

Sp. Reading

101884 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JT FAT 35 Y 30k 214851

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Mic 195R15X8

R: Falken 155R12X8(D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4 mm

R/Bal.

2 2 mm

L/Bal.

4 mm

L/Bal.

2 2 mm

D.O.A.

12/5/22

D.O.I.

13/5/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

1st N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

F. Miles

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

GBB9119Z
 TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Estimate No: ES2290480/YISHUN

Date: 13 May 2022

Policy No: DMCVSNW00010342202

Veh Reg No: GBB9119Z

Make/Model: TOYOTA TOYOTA
 DYNA 150 5MT

WS Ref: TP/AIG

Claim Type: Third Party

Accident Date: 12/05/2022

TP Veh Reg No: GBF8585X

Chassis No: JTFAT35Y30K214651

Engine No: 1KDB015501

Reg. Date: 15/01/2020

Estimate Repair Cost to Vehicle No :GBB9119Z

PAGE:1/1

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 FRONT GRILLE	643.85	1 PC	643.85	✓
2 FRONT GRILLE LOGO	74.40	1 PC	74.40	✓
3 FRONT GRILLE CLIPS	4.50	4 PCS	18.00	✓
4 LH HEADLAMP	969.20	1 PC	969.20	✓
5 FRONT LH CORNAL PANEL	356.70	1 PC	356.70	✓
6 FRONT PANEL	1,156.70	1 PC	1,156.70	✓
7 FRONT LH SIDE MIRROR	636.40	1 PC	636.40	✓
8 FRONT LH SIDE MIRROR MOTOR	666.90	1 PC	666.90	✓
9 FRONT WINDSCREEN GLASS RUBBER	280.10	1 PC	280.10	✓
10 FRONT BUMPER	683.90	1 PC	683.90	✓
			5,486.15	
		Less 25%	1,371.54	4,114.61
Special Net				
11 FRONT LH DOOR COY STICKER	20.00	1 PC	20.00	✓
12 FRONT NUMBER PLATE	20.00	1 PC	20.00	X
			40.00	40.00
Labour				
13 REMOVE AND REFIX FRONT WINDSCREEN GLASS	60.00	1 LA	60.00	✓
14 REMOVE & REFIX DASHBOARD,METER ASSY AND CHECK WIRING	230.00	1 LA	230.00	220
15 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
16 REMOVE & REFIX FRT BUMPER ASSY,GRILLE,HEADLAMPS,SIDE MIRROR,TO CUT,WELD & RENEW FRT PANEL AND REALIGN THE SAME	780.00	1 LA	780.00	700
17 PUTTY & RESPRAY ON FRT GRILLE,FRT PANEL,FRT WIPER PANEL,FRT BUMPER,FRT LH DOOR	1,000.00	1 LA	1,000.00	800
18 TO REWRITE ADVERTISEMENT	900.00	1 LA	900.00	600
			3,070.00	3,070.00

Total S\$ 7,224.61

Add GST @ 7% 505.72

Total Amount Payable S\$ 7,730.33

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

For Cheng Hoe Motor Pte Ltd

Acknowledged by Repairer

Signature:

Date:

AUTHORISED SIGNATURE