Surveyor:

REF: CS1/LPM22004553/Rty3

Special Instruction:
P/P 24739.16 / 13DAYS
Third Parties:
Claimant:
Surveyor: T&C AUTOMOBILE
Workshop: MING HUA AUTO SERVICE

ASSIGNMENT (Office)

From (Person): LILLIAN SIM of LPM Date/Time: 17/05/2022
Estimated Cost: Bill to:

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SLH 7253G Insured: JQQ 3348
at Workshop m/s MING HUA AUTO SERVICES Tel:
of 160 SIN MING DRIVE #02-16 SIN MING AUTO CITY SINGAPORE 575722
Policy No: Claim No:
Sum Insured: Excess:
Make of Veh: D.O.A. 09/09/2018
(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle **IN / OUT**

Date/Time: **Confirmed with** **Final Fig** , days (Red $ / %; Original 7 days)

Date/Time: 22/6/2022 **Submit Final Fig** 7400 , 6 days (Red $ 17339.16 / 70 %; Original 7 days)

Date/Time	Action/Instruction

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : *NC*)

Para(3) : Nett Value

Market Value :
Salvage Value :
Nett Value :

Inspected/ Evaluated by:

Fee Charged:	*Date:*
Basic & Add	
Transport	
Photos	
Others	
Total	

1) Date/Time File Pass to 2) Date/Time File Return to
3) Date/Time File Pass to 4) Date/Time File Return to
5) Date/Time File Pass to 6) Date/Time File Return to