			N .
Serveyor:	REF: CS1/LAW2	22004577/Avc	Special Instruction;
From (Person): Sherlyn Estimated Cost:	ASSIGNI of Riaz LLC Da	te/Time: 13/05/2022	LS \$4,800.00 Third Parties: Claimant: Surveyor: Advanced Automotive
OD/TP Re-inspection / Evalua	tion		Workshop: Equator Brotherhood
To Inspect Vehicle No:F	BP 3800E	Insured:FBN 1822R	Workshop. Equator Brotherhood
at Workshop m/sEquator E	74lll	Tel:9011 3391	
of 25 Kaki Bukit Road 4#	03-19	101. 0011 0001	
Policy No: RT/SB/202/202	1/xf	Claim No: WAN.51472	6 I
Sum Insured:		Execc:	
Make of Veh:		DOA 19/10/2019	
(Client's Record)		_D.O.A19/10/2019	
5 -		н	H.O.D. Endorsement/Date:
Date/Time:	Person Contacted:	Vehicle IN / OUT	
Date/Time: Confi	rmed with Final	Fig,days (Red	d \$/%; Original_4_days)
Date/Time: 26/7/22 Subm	it Final Fig LS 1200	3 days (Red \$ 3600 /	75 %; Original days)
Date/Time Action/Instruction			
FBP 3800E -	X		
FBN 1822R -	Χ	**	
Para(1): Parts found not replaced (To highlight R or UB, LR, Etc)			
	, ,	8 1 1 1 1 2 2	, 210)
Para(2): Comments on consistency of damages (Parts Not Consistent: NC)			
Para(2) . Note X7.1			
Para(3): Nett Value			
Market Value	<u> </u>		Fee Charged: Date:
1		Inspected/	Basic & Add
Salvage Value	:	Evaluated by:	Transport Photos
Nett Value			Others
	<u>:</u>		Total
1) Date/Time F	ile Pass to	2) Date/Time	File Return to
	ile Pass to	4) Date/Time	File Return to
5) Date/Time F	ile Pass to	6) Date/Time	Pile Determine