

ASS. REC. BY:

Thiruvann

REF:

CS/SMR 220045811vty3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

45k

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

3 days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

PC3/23D

Yr Regn: _____

10/2/115

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Toyota hiace

c.c 2982

Colour: _____

white

A/C: Insured / Std / NI / NA

Sp. Reading: _____

326260

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

KDH/2230021818

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: 195/45

R: 195/45

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. _____

6

mm

Rear

R/Bal. _____

6

mm

L/Bal. _____

6

mm

L/Bal. _____

6

mm

D.O.A. _____

14/5/22

D.O.I. _____

24/5/22 / 700

Survey held at

Speedworks

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV: 45k

rebate: 12098

NV: 32902

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	416D
Vehicle Details	
Vehicle No.:	PC3123D
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Jul 2022
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE COMMUTER GL 3.0 AT 2WD 4DR LWB
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	1KD2458299
Chassis No.:	KDH2230021818
Maximum Power Output:	-
Open Market Value:	\$38,545.00
Original Registration Date:	10 Feb 2015
First Registration Date:	10 Feb 2015
Transfer Count:	0
Actual ARF Paid:	\$1,928.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	09 Feb 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$47,677.00
COE Rebate Amount:	\$12,098.00
Total Rebate Amount:	\$12,098.00

The information contained herein is correct as at 27 Jul 2022

OK

CARSMITH PRIVATE LIMITED

Bartley Biz Centre 13 Kaki Bukit Road 4 #01-20 Singapore 417807

Tel: 9091 0000/ Email: info@carsmith.biz

VEHICLE NO: PC3123D

MAKE & MODEL: TOYOTA HIACE

DOA: 17.05.2022

CLAIM TYPE: TP CLAIM

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
FRONT BUMPER	1	\$ 1,219.00	671 / 1784
FRONT LH RETAINER	1	\$ 187.00	116
FRONT LH HEADLAMP	1	\$ 1,523.00	1246 / 508
		\$ 2,929.00	
	LESS 25%	\$ 732.25	
	SUB TOTAL	\$ 2,196.75	1578

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
FRONT BUMPER CLIP	1 SET	\$ 80.00	30 N/C
FRONT HEADLAMP CLIP	1 SET	\$ 107.00	30 N/C
	SUB TOTAL	\$ 187.00	

LABOUR	QTY	PRICE (\$)	REMARKS
SPRAY PAINTING ON AFFECTED AREAS	1	\$ 800.00	200
LABOUR TO REMOVE AND INSTALL AFFECTED PARTS	1	\$ 800.00	200
	SUB TOTAL	\$ 1,600.00	2038

GRAND TOTAL \$ 3,983.75

F: 1650

RT-3

-2010
= 1630

= 1650

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: