

## ASSIGNMENT

FROM: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SMX 7244L Yr Regn: 27/1/22Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Tiguan c.c. 1395Colour: Silver A/C: ☒ Insured / Std / NI / NASp. Reading: 18940 T/Radio: ☒ Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WVG222SN2LW849534Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim orTyre Size: F: 255/45R19R: 11☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or \_\_\_\_\_

Front

Rear

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 12/5/22 D.O.I. 20/5/22Survey held at VolkswagenDes. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MV-180K</u>
	<u>COR: 6,916.29, 5 Working days</u>
	<u>red: 7899.73:53%</u>

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 5

1)

☐ : Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Report Format: \_\_\_\_\_

Lump Sum / L.B.E. (\$ \_\_\_\_\_)

## VOLKSWAGEN CENTRE SINGAPORE

47 Alexandra Road  
Singapore 159934  
Biz. Reg. No.: 199101494Z  
GST No.: M200985052



## Quotation

Non binding - Preview

Page

1/2

Company  
CHINA TAIPING INSURANCE (S) PL  
3 ANSON ROAD  
#18-00 SPRINGLEAF TOWER  
Singapore 079909

Customer Details:  
Ms.  
LI  
YUEMIN  
BLK 4 EVERTON PARK  
#07-40  
SINGAPORE 080004

Document no.  
Document date 19-05-2022  
Customer no. 5211001170  
Customer GST-ID 200208384E  
Dealer 30001  
Job order number 2022013942/ 1  
Job order date 14-05-2022  
Service Advisor CHARMAINE KONG

License plate SMX7244L	Model code AD14N6R0	First registration 27-01-2021	VIN WVGZZZ5NZLW849534	Model Tiguan R-Line 1.4 I TSI 110kW N6 DSG	Mileage 12,931
---------------------------	------------------------	----------------------------------	--------------------------	---	-------------------

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#1	280.00	299.60
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#1	480.00	513.60
5NA807421 GRU	Cover For Bumper Primed REAR BUMPER ( UPPER )	1	pcs.	1,586.27	#1	1,586.27	1,697.31
5NA807521C GRU	Spoiler Primed REAR BUMPER ( CTR )	1	pcs.	436.50	#1	436.50	467.06
5NA807568C 041	Rear Diffusor Black REAR BUMPER ( LOWER BLACK )	1	pcs.	559.44	#1	559.44	598.60
5NA807305A	Bumper ( REINFORCEMENT )	1	pcs.	782.05	#1	782.05	836.79
5NA807863	Attachment Strip BUMPER CTR BRACKET	1	pcs.	70.74	#1	70.74	75.69
5NA807393	Guide Piece LHR BUMPER BRACKET ( SIDE )	1	pcs.	45.25	#1	45.25	48.42
5NA807394	Guide Piece RHR BUMPER BRACKET ( SIDE )	1	pcs.	45.25	#1	45.25	48.42
5NA807393A	Guide Piece LHR BUMPER BRACKET ( UPPER )	1	pcs.	45.25	#1	45.25	48.42
5NA807394A	Guide Piece LHR BUMPER BRACKET ( UPPER )	1	pcs.	45.25	#1	45.25	48.42
5NA853835 ZZZ	Decorative Moulding Brigh ( CENTRE )	1	pcs.	233.76	#1	233.76	250.12
5NA853841 ZZZ	Decorative Moulding Brigh ( LH )	1	pcs.	179.92	#1	179.92	192.51
5NA853842 ZZZ	Decorative Moulding Brigh ( RH )	1	pcs.	183.84	#1	183.84	196.71
5NA919491	Sensor Bracket	1	pcs.	14.19	#1	14.19	15.18
5NA919491A	Sensor Bracket	1	pcs.	14.19	#1	14.19	15.18
5NA919492A	Sensor Bracket	1	pcs.	14.19	#1	14.19	15.18
5NA919492	Sensor Bracket	1	pcs.	14.19	#1	14.19	15.18
D 822150A1	Bonding Agent For Plastic	1	pcs.	68.85	#1	68.85	73.67
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	85.94	#1	85.94	91.96
3Q0919275 GRU	Sensor Primed	1	pcs.	190.18	#1	190.18	203.49
3Q0919133 9B9	Seal Ring Satin Black	1	pcs.	4.72	#1	4.72	5.05
5NA853687 ZZZ	Inscription Bright Chrome ( TIGUAN )	1	pcs.	104.40	#1	104.40	111.71
5NA853630 FOD	Vw Sign Black High Gloss/	1	pcs.	110.64	#1	110.64	118.38
5NA845051ASNVB	Rear Window Glass Heated REAR W/SCREEN	1	pcs.	1,136.39	#1	1,136.39	1,215.94
D 169300M2	1k Window Adhesive	2	pcs.	51.44	#1	102.88	110.08
D 00940104	All Purpose Cleaner	1	pcs.	102.88	#1	102.88	110.08
D 00920002	Primer	1	pcs.	30.27	#1	30.27	32.39
D 181802M1	Activator	1	pcs.	26.27	#1	26.27	28.11
D 00950025	Applicator	2	pcs.	11.16	#1	22.32	23.88

# LKSWAGEN CENTRE SINGAPORE

Alexandra Road  
Singapore 159934  
Biz. Reg. No.: 199101494Z  
GST No.: M200985052



## Quotation

Non binding - Preview

Page

2/2

Company  
CHINA TAIPING INSURANCE (S) PL  
3 ANSON ROAD  
#18-00 SPRINGLEAF TOWER  
Singapore 079909

Customer Details:  
Ms.  
LI  
YUEMIN  
BLK 4 EVERTON PARK  
#07-40  
SINGAPORE 080004

Document no.  
Document date  
Customer no.  
Customer GST-ID  
Dealer  
Job order number  
Job order date  
Service Advisor

19-05-2022  
5211001170  
200208384E  
30001  
2022013942/ 1  
14-05-2022  
CHARMAINE KONG

License plate	Model code	First registration	VIN	Model	Mileage
SMX7244L	AD14N6R0	27-01-2021	VWGZZZ5NZLW849534	Tiguan R-Line 1.4 TSI 110kW N6 DSG	12,931

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	REAR WSCREEN SOLAR FILM	1	pcs.	400.00	#1	400.00	428.00
	Spray Painting	4	pcs.	800.00	#1	3,200.00	3,424.00
	LABOUR	4	pcs.	840.00	#1	3,360.00	3,595.20
	R&R REAR W/SCREEN	1	pcs.	840.00	#1	840.00	898.80

Quotation valid till 21-05-2022

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	14,056.02	7%	1,037.12	14,816.02	15,853.14
Total	760.00	14,056.02		1,037.12	14,816.02	15,853.14

Customer

Service Advisor

—VISIT OUR WEBSITE: [aftersales.vw.com.sg](https://aftersales.vw.com.sg) (for online service appointments) and [volkswagen.com.sg](https://volkswagen.com.sg) and [www.skoda.com.sg](https://www.skoda.com.sg) (for additional services, products and promotions).—

All invoices are denominated in SGD, unless otherwise stated.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	13/05/2022 14:48 (SGT)
Date of Accident	12/05/2022 17:25 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	PATERSON HILL BEFORE JUNCTION OF GRANGE ROAD
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMX7244L
-----------------------------	----------

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	LI YUEMIN
NRIC No	S8317964C
Email Address	minnersli@gmail.com
Mobile Phone No	(Phone) +65-87706960
Alternative Phone No	+65-87706960

#### VEHICLE PARTICULARS

Manufacturer	Volkswagen
Model	Tiguan
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1400

#### INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5122824921
Cover Note Number	-

#### DRIVER

Name of Driver	RAVEEN MISRA
NRIC No	S7903072D

Birth  
on  
Driving Pass  
g experience  
der  
obile Number  
lt. Phone Number  
Email Address  
Address  
Address complement  
Postcode  
Is the driver the policyholder?  
If No, Relationship of the Driver with the Insured  
Does Driver Own Other Vehicles?  
Vehicle Registration Number of Other Vehicle Owned by Driver  
Insurance Company of Other Vehicle Owned by Driver

03/04/1979  
Indoor  
22/06/2010  
11 YEARS AND 11 MONTHS  
Male  
(Phone) +65-91749477  
-  
RAVEENMISRA79@GMAIL.COM  
10A BENDEMEER ROAD  
#17-103  
331010  
No  
Spouse  
No

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident  
Weather Conditions  
Road Surface

Chain Collision  
Clear  
Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?  
Number of vehicles involved in the accident  
Was anybody injured in the Accident?  
Was any injured conveyed to hospital by ambulance?  
Was any other vehicle or property damaged?  
Number of Passengers (Including Driver)  
Has the driver been approached by unknown person(s)  
soliciting/offering accident claims assistance?

No  
3  
Yes  
No  
Yes  
2  
No

#### PASSENGER 1

Name  
Gender

ANUSHKA LI-MISRA  
Female

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?  
Police Station Name  
Police Station Phone No  
Alt. Police Station Phone No  
Police Station Address  
Was notice of intended Prosecution given?  
If yes, against whom?

Yes  
Traffic Police  
(Phone) +65-65470000  
(Fax) +65-65474900  
10 Ubi Avenue 3 Singapore 408865  
No  
-

#### CIRCUMSTANCES OF ACCIDENT

ON THE 12TH OF MAY 2022 AT 1725HRS, I WAS STATIONARY ON THE LEFT MOST LANE OF PATERSON HILL BEFORE THE JUNCTION GRANGE ROAD HEADING TOWARDS RIVER VALLEY, WAITING FOR THE TRAFFIC LIGHT TO TURN GREEN WHEN I WAS HIT TWICE IN THE REAR BY A GOODS VAN GBD2765T. WHEN I EXITED MY CAR TO CHECK ON MY DAUGHTER I REALISED THERE WAS A THIRD VEHICLE, SKK9088A, INVOLVED IN THE ACCIDENT. I PROCEEDED TO CHECK ON MY CAR AND THE ACCIDENT SITE. I HAVE TAKEN PICTURES AND GATHERED DETAILS FROM THE OTHER DRIVERS.

#### ATTACHMENT(S)

Are accident photos available for attachment?  
Was there any video captured by Car Camera?  
Reasons for not uploading a video of the accident  
Was there any audio recorded?

Yes  
Yes  
TO SUBMIT TO WORKSHOP  
No

## DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD2765T
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	NOORASLANTI BINTE RAMLAN
NRIC No	S7509990H
Contact Number	(Phone) +65-88201047
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	2

## DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKK9088A
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	LIM SIN HUI
NRIC No	S8032520G
Contact Number	(Phone) +65-85889088
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

## INJURED PERSONS DETAILS

### INJURED 1

Name of injured person	RAVEEN MISRA
Gender	Male
Phone No	(Phone) +65-91749477
Address	10A BENDEMEER ROAD
Address Complement	#17-103
Post Code	331010
Approximate Age Years Old	43
Injuries Sustained	WHIPLASH AND UPPER SHOULDER SORE
Injured person in which vehicle?	SMX7244L
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:


Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 13/5/2022  
1430hrs

Reporting Centre Personnel's Signature  
Name: SHAN  
NRIC/FIN No.: S990349

### SKETCH PLAN

PATERSON HILL  
TOWARDS RIVER  
VALLEY BEFORE  
GRANGE ROAD

A- SMX7244L  
B- GBD2765T  
C-SKK9088A



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO GEARS

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

**Policyholder's Signature**

Date &amp; Time:

Driver's Signature

(if driver is not the policyholder)

Date & Time: 13052022  
1430hrs

Reporting Centre Personnel's Signature

Name: **SHAN**

NRIC/FIN No.: S990349

**IMPORTANT NOTE:** Please submit the completed Addendum form to the same Accident Reporting Centre with whom you submitted the Original Report.

### ADDENDUM

**(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:**

Original Report No: SN07225D000M Vehicle Registration No: SMX7244L  
Name (as shown in NRIC): RAVEEN MISRA NRIC/FIN/Passport No: S7903072D  
(\*Vehicle Driver/Vehicle Owner) (\*) Please delete as appropriate  
Address: 10A BENDEMEER ROAD #17-103 S(331010) Singapore ( )  
Contact (Tel): \_\_\_\_\_ Mobile No.: 91749477  
Email Address: RAVEENMISRA79@GMAIL.COM  
Date of Accident: 12/5/2022 Time of Accident: 1725HRS  
Place of Accident: PATERSON HILL BEFORE JUNCTION OF GRANGE ROAD  
Insurance Company: NTUC

**(B) ADDITIONAL INFORMATION /AMENDMENTS:**

I have made a report on the above-mentioned accident and would like to include additional information or make the following amendments:

**TO ADD IN STATEMENT:**

I had a foldable bike and a pram in the boot of the car, the impact had cost them to scratch the solar film on the inside of the car.

Policyholder / Driver's Signature  
Date: 14/5/2022

Reporting Centre Personnel's Signature  
Name: SHAN  
NRIC/FIN No.: S990349  
Date: 14/5/2023