

ASS. REC. BY:

REF:

NS/INC22004601/Rqy3

2920

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SG 57654at Workshop m/s SMARTof 60, WOODMAN, INNS PR 64Insured: NTNL

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SG 57654 Yr Regn: 2016 / 2W

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MAN A95 C.C. 10518Colour: GREEN A/C: Insured / Std / NI / NASp. Reading: 395059 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WMAA9522967003234Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Mil / S/Rim / STD A/Rim orTyre Size: F: 275/10R22.5R: 275/10R22.5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

CONTINENTAL

Front

Rear

R/Bal. 8 mm R/Bal. 8/8 mmL/Bal. 8 mm L/Bal. 8/8 mmD.O.A. 23/04/22 D.O.I. 17/05/22Survey held at SMART

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Report Format: \_\_\_\_\_

Lump Sum / L.B. / C

Add Fee:

☐

: Site Insp (\$ \_\_\_\_\_)

☐

: Interview (\$ \_\_\_\_\_)

☐

: Tech. Invs (\$ \_\_\_\_\_)

S + RS. SI

Photos

Others

## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 17/05/2022

User ID : JeongCH

### Section A - Accident Details

Registration Number	SG5765G
Case Reference Number	BUS/04/22/5049
Registration Date	8/18/2016
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN A95
Name of Driver	Ooi Soo Cheong
Type of Accident	Side Swipe
Accident Date and Time	4/23/2022 3:50 PM
Accident Reported Date and Time	4/23/2022 5:15 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	Bus: Left body scratched TP: SJD2070U - NTUC INCOME
Prepared Date and Time	5/17/2022 2:20 PM
Chassis Number	WMAA95ZZ9G7003234
Mileage	
Work Shop	
Repair Completion Date and Time	

### Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$0.00
Total Spray Cost	\$772.00	\$0.00
Total Spare Part Cost	\$75.00	\$0.00
Total Other Cost	\$0.00	\$0.00
<b>TOTAL COST</b>	<b>\$1,642.00</b>	<b>\$0.00</b>
Amount Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	2 days
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date	17/05/2022 2:22 PM	
Signature		<input checked="" type="checkbox"/>
Remarks		

### Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



**SMRT Accident Vehicle Repair Estimates**

<b>SMRT Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 17/05/2022

User ID : JeongCH

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
O REPAIR LH PORTION	\$795.00	530
<b>Total Labour</b>	<b>\$795.00</b>	

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$772.00	602
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$772.00</b>	

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>Total Other Costs</b>		

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			SMRT STICKERS	1.00	\$75.00	0.00	\$75.00	Replace	nm ✓
<b>Total</b>					<b>\$75.00</b>		<b>\$75.00</b>		

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resul  
4p 200 10068  
2 days  
4/5  
17/05/22 21440  
Resurvey after repair

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	05/05/2022 14:32 (SGT)
Date of Accident	23/04/2022 15:50 (SGT)
Exact Location of Accident	760 Bedok Reservoir Rd, Bedok Reservoir Park, Singapore 479245
Additional Location Information	Bedok Resv Rd before BS: 75349 (The Clearwater Condo)
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SG5765G
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	SMRT BUSES LTD
Company Reg No	1XXXXX292D
Email Address	BARC@SMRT.COM.SG
Mobile Phone No	(Phone) +65-80000000
Alternative Phone No	(Office) +65-80000000

## VEHICLE PARTICULARS

Manufacturer	Man
Model	A95
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Bus
Transmission	Auto
CC	2000

## INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Type of Coverage	ThirdParty
Fleet Policy	Yes
Policy Number	D-22099124MFBP
Cover Note Number	-

## DRIVER

Name of Driver	Ooi Soo Cheong
NRIC No	SXXXX621H



Date Of Birth 27/02/1963  
 Occupation Outdoor  
 Date Of Driving Pass 26/03/2001  
 Driving experience 21 YEARS AND 1 MONTH  
 Gender Male  
 Mobile Number (Phone) +65-80000000  
 Alt. Phone Number -  
 Email Address BARC@SMRT.COM.SG  
 Address 60 WOODLANDS IND PARK E4  
 Address complement -  
 Postcode 757705  
 Is the driver the policyholder? No  
 If No, Relationship of the Driver with the Insured Employee  
 Does Driver Own Other Vehicles? No  
 Vehicle Registration Number of Other Vehicle Owned by Driver -  
 Insurance Company of Other Vehicle Owned by Driver -

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Side Swipe  
 Weather Conditions Clear  
 Road Surface Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? No  
 Number of vehicles involved in the accident 2  
 Was anybody injured in the Accident? No  
 Was any injured conveyed to hospital by ambulance? -  
 Was any other vehicle or property damaged? Yes  
 Number of Passengers (Including Driver) 1  
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? No  
 Was notice of intended Prosecution given? No  
 If yes, against whom? -

#### CIRCUMSTANCES OF ACCIDENT

On 23/04/2022 at around 1550hrs, I was travelling on the right lane of 02 lanes along Bedok Reservoir Road heading towards the direction of CCK Bus Interchange on service 67, SG5765G. My bus speed was around 50-55km/hrs. While bus was approaching bus stop 75349 for my pax activity, I noticed that the road ahead was a straight road and there was a pte car on my left side of the road. So, I continued to move on and prepared to drive pass the pte car, when bus was parallel travelling on its right side, the pte car on my left side suddenly filtered out from the left lane and encroached onto my path in front at close distance to make lane change. While changing lane, third party car right body and front portion grazed against the left front portion of my bus to result in this SS accident case. Upon seeing this, I immediately stopped my bus and alighted to conduct damage checks. While checking, I noticed that my bus Left front body had some scratched marked. While third party car had its front right with body portion scratched.

#### ATTACHMENT(S)

Are accident photos available for attachment? No  
 Was there any video captured by Car Camera? Yes  
 Reasons for not uploading a video of the accident FILE TOO BIG  
 Was there any audio recorded? No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJD2070U  
 Vehicle Manufacturer -  
 Vehicle Model -

Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	LIM ZHENG JIE
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	NTUC Income Insurance Co-operative Ltd
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (a insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to a Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

367  
365756 Road

← To cck  
direction

Rms: 342578

\* See Statement

## We dec

particulars are taken in every respect

Reporting Centre Personnel's Signature:  
Name:  
NRIC/Fin No.:



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	292D
Vehicle No.:	SG5765G
Vehicle to be Exported:	No
Intended Deregistration Date:	18 May 2022
Vehicle Make:	MAN
Vehicle Model:	A95
Primary Colour:	Multicolor
Manufacturing Year:	2015
Engine No.:	50343342524337
Chassis No.:	WMAA95ZZ9G7003234
Maximum Power Output:	-
Open Market Value:	\$598,127.00
Original Registration Date:	29 Jun 2016
First Registration Date:	29 Jun 2016
Transfer Count:	1
Actual ARF Paid:	\$0.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 18 May 2022

OK