

ASS. REC. BY: Thevan

REF:

Ntuc NS/INC22004632/Vqc

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. MT/1169624-003

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHD35677 Yr Regn: 1414 / 16Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota prius c.c. 1798Colour: blue A/C: Insured / Std / NI / NASp. Reading: 730778 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 3TDH33FuX03529842Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or WestlakeFront 5 mmR/Bal. 5 mmL/Bal. 5 mmD.O.A. 22/4/22 D.O.I. 25/4/22 1800Survey held at CDGEDes. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

NO GIA providedThevan finalised LS \$1550, 2 days. (Red \$913.16, 37%)

Date/Time, File Pass to?

1) 26/05 Typist

Date/Time, File Return to?

2) _____

Report Format : TPLump Sum ~~H.B.~~ (\$ 1550)Days Of Repair: 2Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL


Team: ARC Repair TP(CLS0)1 JOB CARD Sales Order: 4200073 JC NO 305513532

OWNER	REGN NO.: SHD3567X	MILEAGE
IS COMFORT TRANSPORTATION PTE LTD	MAKE: TOYOTA	FUEL
OWNER NO. 7010045	MODEL	E.....1/2.....F
LESS 383 SIN MING DRIVE	PRIUS HYBRID(G4)22.	DATE/TIME IN 04.2022 15:15
Singapore SINGAPORE 575717	YR OF MANU.	TARGET DATE
(R) 65508755 (O)	14.09.2016	
(P)	CHASSIS CODE	COMPLETION DATE/TIME:
	JTDKB3FUX03529842	
DUPLICATE CARD NO.		

JOB DESCRIPTION

Accident Date: 22.04.2022
NATURE: 3P 22.04.2022

/NO LABOR CODE DESCRIPTION



KEYED & PASSED OUT BY: _____

SERVICE ADVISOR _____ CUSTOMER'S SIGNATURE _____

edgement Slip	Exit Pass
No.: SHD3567X JU NTUC	Vehicle No.: SHD3567X
Service Advisor _____	Name of Service Advisor _____
Signature/Date _____	Date _____
turned to Service Reception upon collection	To be kept by Security Guard

NCHC (48)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 22.04.2022

REPAIR ESTIMATE

Time: 16:28:28

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305513532
REGN NO : SHD3567X
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4)
DATE OF REGN : 14.09.2016
DATE/TIME IN : 22.04.2022 15:15
ACCIDENT DATE : 22.04.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-2282-G	COVER REAR BUMPER	1	503.04	25.00	377.28	Xr
0002 04-01-0302-2287-G	GUARD-REAR BUMPER CENTER	1	654.96	25.00	491.22	/Cur
0003 04-01-0302-2288-G	REINFORCEMENT SUB-ASSY RE	1	378.32	25.00	283.74	XSLC
0004 04-01-0302-2286-G	COVER REAR BUMPER-TOW HOO	1	82.70	25.00	62.02	/Cur
0005 04-01-0302-2965-G	FILLER-REAR BUMPER EXTENS	1	148.40	25.00	111.30	Xr
0006 04-01-0302-3937-G	RETAINER RR BUMPER SIDE R	1	94.80	25.00	71.10	/NLC
0007 04-01-0302-2267-G	BUMPER PIECE	10	22.00	25.00	16.50	/NLC
0008 04-01-0302-1150-A	BUMPER PROTECTOR MAT	1 N	50.00	2.50-	50.00	XSLC

SUB-TOTAL : 1,463.16

JOB NATURE

0000 PB	PANEL BEATING	400.00	350
0001 SP	SPRAYPAINT CHARGE	300.00	250
0002 L	REMOVE/REFIX REVERSE SENSOR	50.00	30

P.T.O

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305513532
REGN NO : SHD3567X
MILEAGE : 000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID
DATE OF REGN : 14.09.2016
DATE/TIME IN : 22.04.2022 15:1
ACCIDENT DATE : 22.04.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0003 20-05 ADVERTISEMENT STICKER-BUMPER

50.00 / PIC

0004 20-05 ADVERTISEMENT STICKER-FENDER

200.00 / PIC

SUB-TOTAL : 1,000.00

TOTAL : 2,463.16

MVA NAME & SIGNATURE
DATE:

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE:

Thuan
82235769
25/4/22 1800
LIS 2 days swp

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: