

Our .	Job Re	f No :	305513631	513631 ENG		GINEERING	
Date :			06.05.2022		ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969		
FINA	LIZAT	ION FORM				, 3	
To :			LKK Fax :				
Attn 🔋			THEVAN				
Vehic	cle Reg	No. : SHA	0444T		25.04.2022		
The s	survey	and estimates of	the repairs of the above-n	nentioned vehicl	e are as follows	s:-	
Z	The	repair job shall bi	I to:	NTUC		SLQ7817H	
2.	The finalized amount shall be:						
	(a) Spare Parts after List discount						
	(b)	Labour Charge	s				
	(~)	-	By-Part Repair Cost				
	(c.)		air (if applicable)				
		Total for Lumps Final Lumpsur	um repair cost after Less: n Repair cost	_	-	\$3,250.00	
3.	Estimated normal period for repairs: working days.						
4.		hall treat the ab rking days	ove amount as Correct a	nd Confirmed i	f there is no re	eply from you within	
5. Thank you for your ass			sistance.	We confirm the estimates and finalized amount			
	Signa	ture.	1/	Sie	gnature:		
	Name	2-	00				
	Tel : 62148314			Date :			
	Fax	: 6546815		_	8		
For O	fficial	Use Only					
	Item		Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks	
Rental Rate P/Day				YES			
2. Loss of Income Paid				N			
B. Survey Fees			5	-			
LTA Search Fee Medical Fees (on behalf of driver, if applicable)			\$7.49/\$2.00	YES			
	errun						
Rema	rks:						