

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 25.04.2022
Time: 13:19:17
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305513631
REGN NO : SHA9444T
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 23.04.2019
DATE/TIME IN : 25.04.2022 09:05
ACCIDENT DATE : 25.04.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2534-G	COVER-FR BUMPER#	1	481.10	20.00	384.88	XY
0002 04-01-0104-0632-G	MOULDING-FRONT BUMPER LH	1	186.90	20.00	149.52	XSC
0003 04-01-0104-3818-G	BRACKET-FR BUMPER SIDE LH	1	35.00	20.00	28.00	/N/C
0004 04-01-0104-0574-G	PANEL-FENDER LH#	1	588.80	20.00	471.04	/PT
0005 04-01-0104-3813-G	EMBLEM-BLUE DRIVE LH	1	26.60	20.00	21.28	/N/C
0006 04-01-0104-0593-G	PANEL ASSY-FRONT DOOR LH#	1	1,797.20	20.00	1,437.76	/PT
0007 04-01-0104-2467-G	MOULDING ASSY-W/LINE FRT	1	110.10	20.00	88.08	/N/C
0008 04-01-0104-2537-G	MIRROR ASSY-O/S RR VIEW L	1	1,391.70	20.00	1,113.36	XSC
0009 04-01-0104-2834-G	GUARD ASSY-FRONT WHEEL LH	1	164.70	20.00	131.76	/SCV
0010 03-01-0104-2061-G	CAP ASSY-WHEEL HUB	1	346.40	20.00	277.12	/SCV
0011 28-01-0103-0007-A	FRT DOOR LOGO CCTPL MOQ30	1	75.00	10.00	67.50	/N/C

SUB-TOTAL : 4,170.30

JOB NATURE

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305513631
 REGN NO : SHA9444T
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 23.04.2019
 DATE/TIME IN : 25.04.2022 09:0
 ACCIDENT DATE : 25.04.2022

JOB / PARTS DESCRIPTION		QTY IND UNIT-PRICE DISC% AMOUNT	
0000 PB	PANEL BEATING	875.00	700
0001 SP	SPRAYPAINT CHARGE	900.00	750
0002 17-01	CHECK ALL LIGHTING	60.00	30
0003 L	REMOVE/REFIX DOOR PARTS	90.00	60
0004 20-08	ADJUST FRONT WHEEL ALIGNMENT	90.00	XNN

SUB-TOTAL : 2,015.00

TOTAL : 6,185.30

AUTHORISED : YES / NO

MVA NAME & SIGNATURE
 DATE :

SURVEYOR NAME & SIGNATURE
 DATE :

Thuan
 82235769
 28/4/22 1630
 L/S 3da 3day swp

F: 3250

RD: 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: