

Our Job Ref No : 305513888

Date : 30/04/22

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr Thevan

Vehicle Reg No. : SH 9519U

26/04/2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: **NTUC** --- **SNA5574G**
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$1,784.76
 - (b) Labour Charges \$660.00
 - Total for Part-By-Part Repair Cost \$2,444.76**
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Signature : _____

Name : Ms. Loke YY

Name : _____

Tel : 62148355

Date : _____

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305513888
 REGN NO : SH 9519U
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 31.03.2022
 DATE/TIME IN : 26.04.2022 09:45
 ACCIDENT DATE : 26.04.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-0578-G	COVER-FR BUMPER#	1	481.10	20.00	384.88
0002 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60
0003 04-01-0104-3818-G	BRACKET-FR BUMPER SIDE LH	1	28.00	20.00	22.40
0004 04-01-0104-2696-G	GRILLE ASSY-RADIATOR#	1	1,409.10	20.00	1,127.28
0005 04-01-0104-2417-G	MOULDING-FRT BUMPER CTR	1	35.10	20.00	28.08
0006 04-01-0104-0634-G	GRILLE-FRONT BUMPER	1	186.90	20.00	149.52
0007 28-01-0104-2028-A	VEHICLE NUMBER PLATE FRON	1	55.00	2.00-	55.00

SUB-TOTAL : 1,784.76

JOB NATURE

0000 PB	PANEL BEATING SH 9519U- TP	350.00
0001 SP	SPRAYPAINT CHARGE	250.00
0002 20-00	TUFF COAT ON AFFECTED PARTS.	30.00
0003 17-01	CHECK ALL LIGHTING	30.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305513888
REGN NO : SH 9519U
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 31.03.2022
DATE/TIME IN : 26.04.2022 09:4
ACCIDENT DATE : 26.04.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 660.00

TOTAL : 2,444.76


Loke Wei Yiang

MVA NAME & SIGNATURE

DATE :

29/4/22

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE :

DESCRIPTION	QTY	ESTIMATE	\$	REMARKS
FRT NUMBER PLATE WITH TRIM COVER	1		\$55.00	
		TOTAL	\$55. 00	