(08/11/13) wef

ASS. REC. BY: Marcus

REF: CCG/AIG 22004660/Upa3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKT9046Z

at Workshop m/s Falcon air Tampines

of

Insured: SMA 86407

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: $45

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 9,12A

Vehicle: IN / OUT

Date: Person Contacted: 27A829768

Veh No: SKT9046Z Yr Regn: 25/06/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or CA/

Make: Toyota wish c.c 1797

Colour Black A/C: Insured / Std / NI / NA

Sp.Reading 138166 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: ZGE20 6023348

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or affected

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: Toureado

R: 205/55-R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm

D.O.A. 17/5/22 D.O.I. 18/05/22

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Frt n/s l

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Dep 12500
	NO 31
26/5/22	L/S $4000 informed Joel

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp ($) ___S + RS, ___SI

☐ : Interview ($) Photos

☐ : Tech. Invs ($) Others

☐ : Weekend ($)

Report Format :

Lump Sum / I.B.I: ($)

TOTAL