

Our Job Ref No : 305516353
Date : 20.05.2022

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : GUO QIANG

Vehicle Reg No. : SHC2783A

Date of Accident : 16.05.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: INDIA I I --- GBE6758H

2. The finalized amount shall be:

(a) Spare Parts after List discount \$746.12

(b) Labour Charges (include advertisement stickers etc,if any) \$851.00

Total for Part-By-Part Repair Cost \$1,597.12

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

Final Lumpsum Repair cost

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Signature : _____

Name : LIM T S

Name : GUO QIANG

Tel : 62148398

Date : _____

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	-----	--		
4. LTA Search Fee	\$7.49 /\$2.00	Y		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305516353
REGN NO : SHC2783A
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 07.11.2019
DATE/TIME IN : 17.05.2022 09:25
ACCIDENT DATE : 16.05.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G REAR BUMPER 1 459.40 20.00 367.52

0002 04-01-0104-2533-G REAR BUMPER CTR MOULDING 1 451.25 20.00 361.00

0003 04-01-0101-0111-G REAR BUMPER CLIPS 10 L 22.00 20.00 17.60

SUB-TOTAL : 746.12

JOB NATURE

0000 PB PANEL BEATING-SHC2783A-TP 350.00

0001 SP SPRAYPAINT CHARGE 250.00

0002 L R/I REVERSE SENSORS 40.00

0003 20-05 TP MERIMEN 11.00

0004 20-05 Rear Fender Adv.Sticker RH/LH 200.00

SUB-TOTAL : 851.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 19.05.2022

Time: 15:22:54

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305516353
REGN NO : SHC2783A
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 07.11.2019
DATE/TIME IN : 17.05.2022 09:25
ACCIDENT DATE : 16.05.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

MVA NAME & SIGNATURE
DATE :

TOTAL : 1,597.12

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :