



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CS3/CTI21010541/Rqy3n2-1	
			Date: 23/06/2022	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GX 8558X	Veh. Inspected	SLG 7767X	
Policy No.	DMCVSNA00069252101	Coverage (\$)	0.00	
Claim No.	SNM21D205832/C02	Excess (\$)	0.00	
Assign From	PAULINE THAM	Assign Date	18/05/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL 1.5 X CVT	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	RU11114417	Colour	GREY	
Odometer	55173 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	BRIDGESTONE	6 mm	
L/H Front Tyre	215/60 R16	BRIDGESTONE	6 mm	
R/H Rear Tyre	215/60 R16	BRIDGESTONE	6 mm	
L/H Rear Tyre	215/60 R16	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/10/2021	Inspection Date	13/10/2021	
Survey held at	SUNDAY PLUS AUTO COMPUTERISED SERVICE CENTRE PTE LTD BLK 4003 ANG MO KIO IND. PARK 1 #01-118 AVE 10, SINGAPORE 569624			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	