

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	LONPAC INSURA	NCE BHD	F	Ref:	CS3/LPC22002543/Gvy3e2-1	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555	Ε	Date:	02/06/2022	
			C	Code:	LPC2	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	GW 1883H	Veh. Inspected		FBL 1938B	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	21/22/22/VC05/025567	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		18/05/2022	
2.	Vehicle Particulars & Condition					
	Make & Model	KAWASAKI Z800	c.c		806	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	JKBZR800ABDA15527	Colour		GREEN	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	120/70Z R17	MICHELIN		5 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	180/55Z R17	MICHELIN		5 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	16/03/2022	Inspection Date		21/03/2022	
	Survey held at	ONG MOTOR TRADING				
		NO. 464 MACPHERSON ROAD SINGAPORE 368182				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:	5	Worki	ng Days	