

Your Ref: SS/sm/2021000431 Sompo(mpd)

Date: 26<sup>th</sup> July 2022

Our Ref: CS1/LAW22004695/Dqce2

**M/s Kelvin Chia Partnership**

6 Temasek Boulevard 29th  
Floor Suntec Tower Four  
Singapore 038986

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLN 5077E  
INSURED VEHICLE: FBK 4801Y  
ACCIDENT DATE: 10/04/2019**

We thank you for your instruction on 18/05/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLN 5077E from M/s United Appraisal And Management Pte Ltd.
- b) Survey report by Priority Services with colour photographs.
- c) Singapore Accident Statement and Police Report of Vehicles SLN 5077E and FBK 4801Y.
- d) Colour damaged vehicle photographs of SLN 5077E.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLN 5077E
Make & Model	: Subaru XV 1.6I-S AWD CVT
Chassis Number	: JF1GP3KC5GG175477
Year of Registration	: 2017
Engine Capacity	: 1600 cc

- 2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.