

LKK Auto Consultants Pte Ltd

Date:

28/07/2022

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CS/LAW22004696/Ace2 Ref:

TOKIO MARINE INSURANS (MALAYSIA) BERHAD

C/O: TAN KOK QUAN PARTNERSHIP 1 WALLICH STREET #07-02

	GUOCO TOWER	SINGAPORE 078881			
			Cod	le: LAW	
	Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
	Insured Veh.	BLF 9266	Veh. Inspected	SMP 1423T	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	CF.clm.0539.22-tm(m)	Excess (\$)	0.00	
	Assign From	Christopher Fernandez	Assign Date	19/05/2022	
•		Vehicle Parti	culars & Condition		
	Make & Model	TOYOTA WISH	c.c	1794	
	Engine No.	HIDDEN	Year of Reg.	2009	
	Chassis No.	JTDER12W103002261	Colour	BLUE	
	Odometer	217127 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	195/65 R15	FALKEN	6 mm	
	L/H Front Tyre	195/65 R15	FALKEN	6 mm	
	R/H Rear Tyre	195/65 R15	FALKEN	6 mm	
	L/H Rear Tyre	195/65 R15	FALKEN	6 mm	
	Description of Damages				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
	REPAIR CONDITION	ON SEE DETAILS.			
		General Information			
	Accident Date	31/01/2020	Inspection Date	17/06/2022	
	Survey held at	HUA MENG SPRAY PAINTING	WORKSHOP		
		1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883			
a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
b.		Estimate	Days of Repair		
	ESTIMATED NORMAL PERIOD FOR REPAIR: 12 Working Days				